User's Manual For PCL6025B Pulse Control LSI

NPM Nippon Pulse Motor Co., Ltd.

[Preface]

Thank you for considering our pulse control LSI, the "PCL6025B."

To learn how to use the PCL6025B, read this manual to become familiar with the product.

The handling precautions for installing this LSI are described at the end of this manual. Make sure to read them before installing the LSI.

[Precautions]

(1) Copying all or any part of this manual without written approval is prohibited.

- (2) The specifications of this LSI may be changed to improve performance or quality without prior notice.
- (3) Although this manual was produced with the utmost care, if you find any points that are unclear, wrong, or have inadequate descriptions, please let us know.
- (4) We are not responsible for any results that occur from using this LSI, regardless of item (3) above.
- Explanation of the descriptions in this manual
 - 1. The "x" and "y" of terminal names and bit names refer to the X and Y axes, respectively.
 - 2. Terminal names with a hash mark # (e.g. #RST) are negative logic terminals. Their logic cannot be changed.

Terminals without a hash mark # in front of the name are positive logic. Their output logic can be changed.

3. When describing the bits in registers, "n" refers to the bit position. A "0" means that the bit is in position 0, and that it is prohibited to write to any bit other than the "0" bit. Finally, this bit will always return a "0" when read.

INDEX

2. Specifications .5 3. Terminal Assignment Diagram .6 4. Function of Terminals .7 5. Block Diagram 12 6. CPU Interface 13 6.1. Setting up connections to a CPU 13 6.2. CPU Interface circuit block diagram 14 6.3. CPU Interface circuit block diagram 14 6.4. Address map 16 6.4.2. Interface circuit block diagram 16 6.4.2. Interface circuit block diagram 16 6.4.2. Write the command code and axis selection (COMW, COMB) 16 6.5.1. Write the command code and axis selection (COMW, COMB) 18 6.5.2. Write to an output port (OTPW, OTPB) 18 6.5.3. Write/read the input/output buffer (BUFW, BUFB) 18 6.5.4. Avaing the main status (MSTSW, MSTSB) 19 6.5.5. Reading the main status (MSTSW, MSTSB) 19 6.5.6. Reading the main status (MSTSW, MSTSB) 12 7.1.1. Procedure for writing an operation command (the axis assignment is omitted) 21 7.1.2. Start command 22 7.1.3. Speed change command 22 7.3. Control command 22 7.3. Control command	1. Outline and Features 1-1. Outline 1-2. Features	1 1 1
3. Terminal Assignment Diagram	2. Specifications	5
4. Function of Terminals 7 5. Block Diagram 12 6. CPU Interface 13 6.1. Setting up connections to a CPU 13 6.2. Precautions for designing hardware 15 6.3. CPU Interface circuit block diagram 14 6.4. Address map 16 6.4. Address map 16 6.4. Address map 16 6.4. Diverse map details 16 6.5. Description of the map details 16 6.5. Description of the map details 16 6.5.2. Write to an output port (OTPW, OTPB) 18 6.5.3. Rescription of the input/output buffer (BUFW, BUFB) 18 6.5.4. Reading the main status (MSTSW, MSTSB) 19 6.5.5. Reading the sub status and input/output port. (SSTSW, SSTSB, IOPB) 20 7. Commands (Operation and Control Commands) 21 7.1. Operation commands 21 7.1. Procedure for writing an operation command (the axis assignment is omitted) 21 7.1. Software reset command 22 7.2. General-purpose output bit control commands 22 7.3. Software reset command 24 7.3. Control command 24	3. Terminal Assignment Diagram	6
5. Block Diagram 12 6. CPU Interface 13 6-1. Setting up connections to a CPU 15 6-2. Precautions for designing hardware 15 6-3. CPU interface circuit block diagram 14 6-4. Address map 16 6-4. Address map 16 6-4. Address map 16 6-4.2. Internal map of each axis 16 6-5. Description of the map details 18 6-5.1 Write the command code and axis selection (COMW, COMB) 18 6-5.2. Write to an output port (OTPW, OTPB) 18 6-5.4. Reading the main status (MSTSW, MSTSB) 19 6-5.5. Reading the sub status and input/output port. (SSTSW, SSTSB, IOPB) 20 7. Commands (Operation and Control Commands) 21 7.1-1. Procedure for writing an operation command (the axis assignment is omitted) 21 7.1-2. Start command 22 7.1-3. Speed change command 22 7.2. General-purpose output bit control commandss 23 7.3. Control command 24 7.3. Control command 24 7.3. Control command 24 7.3. Control command 24 7.3. Contro	4. Function of Terminals	7
6. CPU Interface 13 6-1. Setting up connections to a CPU 13 6-2. Precautions for designing hardware 13 6-3. CPU Interface circuit block diagram 14 6-4. Address map 16 6-4.1. Axis arrangement map 16 6-4.1. Internal map of each axis 16 6-4.2. Internal map of each axis 16 6-5. Description of the map details 16 6-5.3. Write to an output port (OTPW, OTPB) 18 6-5.4. Write to an output port (OTPW, OTPB) 18 6-5.5. Write/read the input/output buffer (BUFW, BUFB) 18 6-5.5. Reading the sub status and input/output port. (SSTSW, SSTSB, IOPB) 20 7. Commands (Operation and Control Commands) 21 7-1.1. Operation commands 21 7-1.2. Start command 22 7-1.4. Stop command 22 7-1.5. NOP (do nothing) command 22 7-3. Control command 24 7-3.1. Software reset command 24 7-3.2. Counter reset command 24 7-3.4. Pre-register control command 24 7-3.4. Pre-register control command 24 7-3.4. Procedure for wri	5. Block Diagram	12
7. Commands (Operation and Control Commands) 21 7.1. Operation commands 21 7.1. Operation commands 21 7.1. Procedure for writing an operation command (the axis assignment is omitted) 21 7.1.2. Start command 21 7.1.3. Speed change command 22 7.1.4. Stop command 22 7.1.5. NOP (do nothing) command 22 7.2. General-purpose output bit control commands 23 7.3. Control command 24 7.3.1. Software reset command 24 7.3.2. Counter reset command 24 7.3.3. ERC output control command 24 7.3.4. Pre-register control command 24 7.3.5. PCS input command 24 7.3.6. LTC input (counter latch) command 24 7.4.1. Procedure for writing data to a register (the axis assignment is omitted) 25 7.4.2. Procedure for reading data from a register (the axis assignment is omitted) 25 7.4.3. Table of register control commands 26 7.5. General-purpose output control commands 26 7.5.1. Command writing procedures 27 7.5.2. Command writing procedures 27	 6. CPU Interface 6-1. Setting up connections to a CPU 6-2. Precautions for designing hardware 6-3. CPU interface circuit block diagram 6-4. Address map 6-4-1. Axis arrangement map 6-4-2. Internal map of each axis 6-5. Description of the map details 6-5-1. Write the command code and axis selection (COMW, COMB) 6-5-2. Write to an output port (OTPW, OTPB) 6-5-3. Write/read the input/output buffer (BUFW, BUFB) 6-5-4. Reading the main status (MSTSW, MSTSB) 6-5 F. Poading the sub status and input/output port (SSTSW, SSTSP, IOPP) 	13 13 13 14 16 16 16 16 16 18 18 18 18 18 18 20
7-1-2. Start command 21 7-1-3. Speed change command 22 7-1-4. Stop command 22 7-1-5. NOP (do nothing) command 22 7-2. General-purpose output bit control commands 23 7-3. Control command 24 7-3-1. Software reset command 24 7-3-2. Counter reset command 24 7-3-3. ERC output control command 24 7-3-4. Pre-register control command 24 7-3-5. PCS input command 24 7-3-6. LTC input (counter latch) command 24 7-4. Register control command 25 7-4.1. Procedure for writing data to a register (the axis assignment is omitted) 25 7-4-2. Procedure for reading data from a register (the axis assignment is omitted) 25 7-4-3. Table of register control commands 26 7-5. General-purpose output control command 27 7-5.1. Command writing procedures 27 7-5-2. Command bit allocation 27	 7. Commands (Operation and Control Commands) 7-1. Operation commands	
7-2. General-purpose output bit control commands 23 7-3. Control command 24 7-3.1. Software reset command 24 7-3.2. Counter reset command 24 7-3.3. ERC output control command 24 7-3.4. Pre-register control command 24 7-3.5. PCS input command 24 7-3.6. LTC input (counter latch) command 24 7-4. Register control command 24 7-4.1. Procedure for writing data to a register (the axis assignment is omitted) 25 7-4.2. Procedure for reading data from a register (the axis assignment is omitted) 25 7-4.3. Table of register control commands 26 7-5.1. Command writing procedures 27 7-5.2. Command bit allocation 27 7-5.2. Command bit allocation 27	7-1-2. Start command 7-1-3. Speed change command 7-1-4. Stop command 7-1-5. NOP (do nothing) command	
7-3-2. Counter reset command 24 7-3-3. ERC output control command 24 7-3-4. Pre-register control command 24 7-3-5. PCS input command 24 7-3-6. LTC input (counter latch) command 24 7-4. Register control command 24 7-4. Register control command 24 7-4.1. Procedure for writing data to a register (the axis assignment is omitted) 25 7-4-2. Procedure for reading data from a register (the axis assignment is omitted) 25 7-4-3. Table of register control commands 26 7-5. General-purpose output control command 26 7-5.1. Command writing procedures 27 7-5-2. Command bit allocation 27	 7-2. General-purpose output bit control commands	
7-3-6. L1C input (counter latch) command 24 7-4. Register control command 25 7-4.1. Procedure for writing data to a register (the axis assignment is omitted) 25 7-4-2. Procedure for reading data from a register (the axis assignment is omitted) 25 7-4-3. Table of register control commands 26 7-5. General-purpose output control command 27 7-5-1. Command writing procedures 27 7-5-2. Command bit allocation 27	7-3-3. ERC output control command 7-3-4. Pre-register control command 7-3-5. PCS input command	
7-4-3. Table of register control commands 26 7-5. General-purpose output control command 27 7-5-1. Command writing procedures 27 7-5-2. Command bit allocation 27	 7-3-6. LIG input (counter latch) command 7-4. Register control command	
	 7-4-3. Table of register control commands	

8. Registers	28
8-1. Table of registers	28
8-2. Pre-registers	29
8-2-1. Writing to the operation pre-registers	29
8-2-2. Cancel the operation pre-register	29
8-2-3. Writing to the comparator pre-registers	30
8-2-4. Cancel the comparator pre-register data	30
8-3. Description of the registers	31
8-3-1. PRMV (RMV) registers (Feed amount, target position)	31
8-3-2. PRFL (RFL) registers (Initial speed)	31
8-3-3. PRFH (RFH) registers (Operation speed)	31
8-3-4. PRUR (RUR) registers (Acceleration rate)	31
8-3-5. PRDR (RDR) registers (Deceleration rate)	31
8-3-6. PRMG (RMG) registers (Speed magnification rate)	32
8-3-7. PRDP (RDP) registers (Ramping-down point)	32
8-3-8. PRMD (RMD) registers (Operation mode)	33
8-3-9. PRIP (RIP) registers (Circular interpolation center position, master axis feed amount)	35
8-3-10. PRUS (RUS) registers (S-curve acceleration range)	35
8-3-11. PRDS (RDS) registers (S-curve deceleration range)	35
8-3-12. RFA register (Speed at amount correction)	35
8-3-13. RENV1 register (Environment setting 1)	36
8-3-14. RENV2 register (Environment setting 2)	38
8-3-15. RENV3 register (Environment setting 3)	40
8-3-16. RENV4 register (Environment setting 4)	42
8-3-17. RENV5 register (Environment setting 5)	44
8-3-18. RENV6 register (Environment setting 6)	45
8-3-19. RENV7 register (Environment setting 7)	45
8-3-20. RCUN1 register (COUNTER1 < command position>)	46
8-3-21. RCUN2 register (COUNTER2 <mechanical position="">)</mechanical>	46
8-3-22. RCUN3 register (COUNTER3 <deflection counter="">)</deflection>	46
8-3-23. RCUN4 register (COUNTER4 <general-purpose counter="">)</general-purpose>	46
8-3-24. RCMP1 register (Comparison data for Comparator 1)	47
8-3-25. RCMP2 register (Comparison data for Comparator 2)	47
8-3-20. RCMP3 register (Comparison data for Comparator 3)	41
8-3-27. RCMP4 register (Comparison data for Comparator 4)	41
6-3-20. RUMP5 (PRCP5) register (Comparison data for Comparator 5)	47
6-3-29. RIRQ register (Specify event interruption cause)	40
6-3-30. RETCT register (COUNTERT later data)	40
8-3-31. RLICZ register (COUNTER2 latch data)	48
9.2.22 PLTC4 register (COUNTER) lateh data)	49
0-3-33. RETUG TEYISTER (COUNTER4 Idici) udid)	49
0-3-34. RSTSTEVISIEF (Extension Status)	50
9.3.26 DIST register (Event INT status)	51
8.3.37 DDI S register (Number of pulses left for feeding)	52
8-3-38 RSPD register (F7 counter current speed monitor)	JZ 52
8-3-39 RSDC register (Automatically calculated ramping_down point)	
8-3-40 PRCI (RCI) registers (Number of steps for interpolation)	55 הא
8-3-41 RCIC registers (Circular internolation step number counter)	55 52
8-3-42 RIPS register (Interpolation status)	55 51
	54

0. On evention Made	
9. Operation Mode	
9-1. Continuous operation mode using command control	
9-2. Positioning operation mode	
9-2-1. Positioning operation (specify a target position using an incremental value).	
9-2-2. Positioning operation (specify the absolute position COUNTER1)	
9-2-3. Positioning operation (specify the absolute position COUNTER2)	
9-2-4. Command position 0 return operation	
9-2-5. Machine position 0 return operation	
9-2-6. One pulse operation	
9-2-7. Timer operation	
9-3. Pulsar (PA/PB) input mode	
9-3-1. Continuous operation using a pulsar input	
9-3-2. Positioning operations using a pulsar input (specify incremental position)	60
9-3-3. Positioning operations using a pulsar input (specify absolute position to COL	JNTER1) 60
9-3-4. Positioning operations using a pulsar input (specify absolute position to COL	JNTER2) 60
9-3-5. Command position zero return operation using a pulsar input	60
9-3-6. Mechanical position zero return operation using a pulsar input	61
9-3-7. Continuous linear interpolation 1 using a pulsar input	61
9-3-8. Linear interpolation 1 using pulsar input	61
9-3-9. Continuous linear interpolation 2 using pulsar input	61
9-3-10. Linear interpolation 2 using pulsar input	61
9-3-11. CW circular interpolation using pulsar input	61
9-3-12. CCW circular interpolation using pulsar input	61
9-4. External switch (±DR) operation mode	
9-4-1. Continuous operation using an external switch	
9-4-2. Positioning operation using an external switch	
9-5. Zero position operation mode	64
9-5-1. Zero return operation	
9-5-2. Leaving the zero position operations	72
9-5-3. Zero search operation	
9-6. EL or SL operation mode	74
9-6-1. Feed until reaching an EL or SL position	74
9-6-2. Leaving an EL or SL position	74
9-7. EZ count operation mode	
9-8. Interpolation operations	
9-8-1. Interpolation operations	
9-8-2. Interpolation control axis	
9-8-3. Constant synthesized speed control	77
9-8-4. Continuous linear interpolation 1 (MOD: 60h)	
9-8-5. Linear interpolation 1 (MOD: 61h)	78
9-8-6 Continuous linear interpolation 2 (MOD: 62h)	78
9-8-7 Linear interpolation 2 (MOD: 63h)	79
9-8-8 Circular interpolation	80
9-8-9 Interpolation operation synchronized with PA/ PB	
9-8-10 Operation during interpolation	
10. Speed Patterns	83
10-1 Sneed natterns	
10-2 Sneed pattern settings	
10-3 Manual FH correction	
10-4 Example of setting up an acceleration/deceleration speed pattern	
10-5 Changing speed patterns while in operation	

11. Description of the Functions	94
11-1. Reset	94
11-2. Position override	95
11-2-1. Target position override 1	95
11-2-2. Target position override 2 (PCS signal)	96
11-3. Output pulse control.	97
11-3-1. Output pulse mode	97
11-3-2. Control the output pulse width and operation complete timing	98
11-4. Idling control	99
11-5. Mechanical external input control	100
11-5-1. +EL, -EL signal	100
11-5-2. SD signal	101
11-5-3. ORG, EZ signals	103
11-6. Servomotor I/F	104
11-6-1. INP signal	104
11-6-2. ERC signal	105
11-6-3. ALM signals	106
11-7. External start, simultaneous start	107
11-7-1. STA signal (#CSTA, #STA)	107
11-7-2. PCS signal	108
11-8. External stop / simultaneous stop	109
11-9. Emergency stop	111
11-10. Counter	112
11-10-1. Counter type and input method	112
11-10-2. Counter reset	114
11-10-3. Latch the counter and count condition	115
11-10-4. Stop the counter	116
11-11. Comparator	117
11-11-1. Comparator types and functions	117
11-11-2. Software limit function	121
11-11-3. Out of step stepper motor detection function	122
11-11-4. IDX (synchronous) signal output function	123
11-11-5. Ring count function	124
11-12. Backlash correction and slip correction	125
11-13. Vibration restriction function	125
11-14. Synchronous starting	126
11-14-1. Start triggered by another axis stopping	127
11-14-2. Starting from an internal synchronous signal	129
11-15. Output an interrupt signal	131
12. Electrical Characteristics	134
12-1. Absolute maximum ratings	134
12-2. Recommended operating conditions	134
12-3. DC characteristics	134
12-4. AC characteristics 1) (reference clock)	134
12-5. AC characteristics 2) (CPU I/F)	135
12-5-1. CPU-I/F 1) (IF1 = H, IF0 = H) Z80	135
12-5-2. CPU-I/F 2) (IF1 = H, IF0 = L) 8086	136
12-5-3. CPU-I/F 3) (IF1 = L, IF0 = H) H8	137
12-5-4. CPU-I/F 4) (IF1 = L, IF0 = L) 68000	138
12-6. Operation timing	139
13. External Dimensions	141

Appendix: List of various items	142
Appendix 1: List of commands	
Appendix 2: Setting speed pattern	
Appendix 3: Label list	
Appendix 4: Differences between the PCL6025 and PCL6025B	156
1. How to identify programs specifically and only for the PCL6025 and PCL602	5B 156
2. Additional items on the PCL6025B	156
2-1. Main status	156
2-2. Operation command	156
2-3. Register control command	156
2-4. PRMD (RMD) register	157
2-5. RENV2 register	157
2-6. RENV4 register	158
2-7. RENV5 register	158
2-8. RENV6 register	158
2-9. RSTS register	159
2-10. RCIC register	159
2-11. Stop in the middle of a circular interpolation	
2-12. Improved precision of FH speed corrective calculations	159
Handling Precautions	
1. Design precautions	
2. Precautions for transporting and storing LSIs	
3. Precautions for installation	
4. Other precautions	161

1. Outline and Features

1-1. Outline

The PCL6025B is a CMOS LSI designed to provide the oscillating, high-speed pulses needed to drive stepper motors and servomotors (pulse string input types).

It can offer various types of control over the pulse strings and therefore the motor performance. These include continuous feeding, positioning, zero return at a constant speed, linear

acceleration/deceleration, and S-curve acceleration/deceleration.

The PCL6025B controls two axes. It can control the linear interpolation, circular interpolations of two axes, confirm PCL operation status, and interrupt output with various conditions. It also integrates an interface for servo control drivers.

These functions can be used with simple commands. The intelligent design philosophy reduces the burden on the CPU units to control motors.

Note carefully: The PLC6025B is a PCL6025 LSI with added functions. It has the following differences from the PCL6025.

Terminal	PCL6025B	PCL6025
FUPx[65], FUPy[104]	Outputs a HIGH while accelerating	Outputs a LOW while accelerating
FDWx[66], FDWy[105]	Outputs a HIGH while decelerating	Outputs a LOW while decelerating
	Outputs a HIGH while at constant	Outputs a LOW while at constant
	speed	speed

1-2. Features

♦ CPU-I/F

The PCL6025B contains the following CPU interface circuits.

- 1) 8-bit interface for Z80 CPU.
- 2) 16-bit interface for 8086 CPU.
- 3) 16-bit interface for H8 CPU.
- 4) 16-bit interface for 68000 CPU.
- Acceleration/Deceleration speed control

Linear acceleration/deceleration and S-curve acceleration/deceleration are available. Linear acceleration/deceleration can be inserted in the middle of an S-curve acceleration/deceleration curve. (Specify the S-curve range.)

The S-curve range can specify each acceleration and deceleration independently. Therefore, you can create an acceleration/deceleration profile that consists of linear acceleration and S-curve deceleration, or vice versa.

- Interpolation operation
 Feeding with linear interpolation and circular interpolation are both possible.
- Speed override

The feed speed can be changed in the middle of any feed operation.

However, the feed speed cannot be changed during operation when the synthesized speed constant control for linear interpolation is ON while using S-curve deceleration.

- Overriding target position 1) and 2)
 - The target position (feed amount) can be changed while feeding in the positioning mode. If the current position exceeds the newly entered position, the motor will decelerate, stop (immediate stop when already feeding at a constant speed), and then feed in the reverse direction.
 - 2) Starts operation the same as in the continuous mode and, when it receives an external signal, it will stop after the specified number of pulses.
- Triangle drive elimination (FH correction function) In the positioning mode, when there are a small number of output pulses, this function automatically lowers the maximum speed and eliminates triangle driving.

• Look ahead (pre-register) function

The next two sets of data (feed amount, initial speed, feed speed, acceleration rate, deceleration rate, speed magnification rate, ramping-down point, operation mode, center of circular interpolation, S-curve range on an acceleration, S-curve range on a deceleration, number of steps for circular interpolation) can be written while executing the current data.

The next set of data, and other sets of data, can be written in advance of their execution for checking by the comparator.

When the current operation is complete, the system will immediately execute the next operation.

• A variety of counter circuits

The following four counters are available separately for each axis.

Counter	Use or purpose	Counter Input/Output
COUNTER1	28-bit counter for control of the command	Outputs pulses
	position	
COUNTER2	28-bit counter for mechanical position	EA/EB input
	control	Outputs pulses
	(Can be used as general-purpose counter)	PA/PB input
COUNTER3	16-bit counter for controlling the deviation	Outputs pulses and EA/EB input
	between the command position and the	Outputs pulses and PA/PB input
	machine's current position	EA/EB input and PA/PB input
COUNTER4	28-bit counter used to output synchronous	Outputs pulses
	signals	EA/EB input
	(Can be used as general-purpose counter)	PA/PB input
		1/2 of reference clock

All counters can be reset by writing a command or by providing a CLR signal. They can also be latched by writing a command, or by providing an LTC or ORG signal. The PCL6045B can also be set to reset automatically soon after latching these signals. The COUNTER1, COUNTER2, and COUNTER4 counters have a ring count function that repeats counting through a specified counting range.

Comparator

There are five comparator circuits for each axis. They can be used to compare target values and internal counter values.

The counter to compare can be selected from COUNTER1 (command position counter), COUNTER2 (mechanical position counter), COUNTER3 (deflection counter), and COUNTER4 (a general-purpose counter).

Comparators 1 and 2 can also be used as software limits (+SL, -SL).

• Software limit function

You can set software limits using two of the comparator's circuits.

When the mechanical position approaches the software limit range, the LSI will instruct the motors to stop immediately or to stop by deceleration. After that these axes can only be moved in the direction opposite their previous travel.

- Backlash correction function / Slip correction function Both the backlash and slip corrections are available. Backlash correction corrects the feed amount each time the feed direction is changed. Slip correction corrects the feed amount regardless of the feed direction. However, the backlash correction cannot be applied while performing a circular interpolation.
- Synchronous signal output function The LSI can output pulse signals for each specified rate interval.
- Simultaneous start function Multiple axes controlled by the same LSI, or controlled by multiple sets of this LSI, can be started at the same time.
- Simultaneous stop function Multiple axes controlled by the same LSI, or controlled by multiple sets of this LSI, can be stopped at the same time by a command, by an external signal, or by an error stop on any axis.

- Vibration restriction function Specify a control constant in advance and add one pulse each for reverse and forward feed just before stopping. Using this function, vibration can be decreased while stopping.
- Manual pulsar input function By applying manual pulse signals (PA/PB), you can rotate a motor directly. The input signals can be 90° phase difference signals (1x, 2x, or 4x) or up and down signals. In addition to the magnification rates above, the PCL6025B contains an integral pulse number magnification circuit which multiplies by 1x to 32x and a pulse quantity division circuit which is divided by 1 to 2048. EL signal and software limit settings can be used, and the PCL will stop outputting pulses. It can also feed in the opposite direction.
- Direct input of operation switch Positive and negative direction terminals (±DR) are provided to drive a motor with an external operation switch. These switches turn the motor forward (+) and backward (-).
- Out-of-step detection function
 This LSI has a deflection counter which can be used to compare command pulses and encoder signals (EA/EB).
 It can be used to detect out-of-step operation and to confirm a position by using a comparator.
- Idling pulse output function
 This function outputs a preset number of pulses at the self start frequency (FL) before a high-speed start acceleration operation.
 When the initial speed is set higher during the acceleration, this function is effective in preventing out-of-step operation.
- Operation mode

The basic operations of this LSI are: continuous operation, positioning, zero return, linear interpolation, and circular interpolation. By setting the optional operation mode bits, you can use a variety of operations.

<Examples of the operation modes>

- 1) Start/stop by command.
- 2) Continuous operation and positioning operation using PA/PB inputs (manual pulsar).
- 3) Operate for specified distances or in continuous operation using +DR/-DR signals (drive switch).
- 4) Zero return operation.
- 5) Positioning operation using commands.
- 6) Hardware start of the positioning operation using #CSTA input.
- 7) Change the target position after turning ON the PCS. (Delay control)
- Variety of zero return sequences
 - The following patterns can be used.
 - 1) Feeds at constant speed and stops when the ORG signal turns on
 - 2) Feeds at constant speed and stops when an EZ signal is received (after the ORG signal turns on).
 - 3) Feeds at constant speed, reverses when the ORG signal turns on, and stops when an EZ signal is received.
 - 4) Feeds at constant speed and stops when the EL signal turns on. (Normal stop)
 - 5) Feeds at constant speed, reverses when the EL signal turns on, and stops when an EZ signal is received.
 - 6) Feeds at high speed, decelerates when the SD signal turns on, and stops when the ORG signal turns on.
 - 7) Feeds at high speed, decelerates when the ORG signal turns on, and stops when an EZ signal is received.
 - 8) Feeds at high speed, decelerates and stops after the ORG signal turns on. Then, it reverse feeds and stops when an EZ signal is received.
 - 9) Feeds at high speed, decelerates and stops by memorizing the position when the ORG signal turns on, and stops at the memorized position.
 - 10) Feeds at high speed, decelerates to the position stored in memory when an EZ signal is received after the ORG signal turns on. Then, returns to the memorized position if an overrun occurs.
 - 11) Feeds at high speed, reverses after a deceleration stop triggered by the EL signal, and stops

when an EZ signal is received.

• Mechanical input signals

The following four signals can be input for each axis.

- +EL: When this signal turns on, while feeding in the positive (+) direction, movement on this axis stops immediately (with deceleration). When this signal is ON, no further movement occurs on the axis in the positive (+) direction. (The motor can be rotated in the negative (-) direction.)
- 2) -EL: Functions the same as the +EL signal except that it works in the negative (-) direction.
- 3) SD: This signal can be used as a deceleration signal or a deceleration stop signal, according to the software setting.

When this is used as a deceleration signal, and when this signal turns on during a high speed feed operation, the motor on this axis will decelerate to the FL speed. If this signal is ON and movement on the axis is started, the motor on this axis will run at the FL constant speed. When this signal is used as a deceleration stop signal, and when this signal turns on during a high speed feed operation, the motor on this axis will decelerate to the FL speed and then stop.

4) ORG: Input signal for a zero return operation.

For safety, make sure the +EL and -EL signals stay on from the EL position until the end of each stroke.

The input logic for these signals can be changed using the ELL terminal.

The input logic of the SD and ORG signals can be changed using software.

Servomotor I/F

The following three signals can be used as an interface for each axis

1) INP: Input positioning complete signal that is output by a servomotor driver.

2) ERC: Output deflection counter clear signal to a servomotor driver.

3) ALM: Regardless of the direction of operation, when this signal is ON, movement on this axis stops immediately (deceleration stop). When this signal is ON, no movement can occur on this axis. The input logic of the INP. ERC. and ALM signals can be changed using software.

The ERC signal is a pulsed output. The pulse length can be set. (12 µsec to 104 msec. A level output is also available.)

- Output pulse specifications
 Output pulses can be set to a common pulse or 2-pulse mode. The output logic can also be selected.
- Emergency stop signal (#CEMG) input
 When this signal turns on, movement on both axes stops immediately. While this signal is ON, no movement is allowed on either axes.
- Interrupt signal output

An #INT signal (interrupt request) can be output for many reasons. The #INT terminal output signal can use ORed logic for lots of conditions on each axis. (When more than one 6025B LSI is used, wired OR connections are not possible.)

2. Specifications

ltem	Description				
Number of axes	2 axes (X and Y axis)				
Reference clock	Standard: 19.6608 MHz (Max. 20 MHz)				
Positioning control range	-134,217,728 to +134,217,727 (28-bit)				
Ramp down point setting range	0 to 16,777,215 (24-bit)				
Number of registers used for setting speeds	Three for each axis (FL, FH, and FA (speed correction))				
Speed setting step range	1 to 65,535 (16-bits)				
Speed magnification	Multiply by 0.1 to 100				
range	Multiply by 0.1 = 0.1 to 6,553.5 pps				
	Multiply by $1 = 1$ to 65,535 pps				
	Multiply by 100 = 100 to 6,553,500 pps				
	(When the reference clock is 19.6608 MHz)				
Acceleration/deceleration	Selectable acceleration/deceleration pattern for both increasing and decreasing				
characteristics	speed separately, using Linear and S-curve acceleration/deceleration.				
Acceleration rate setting range	1 to 65,535 (16-bit)				
Deceleration rate setting range	1 to 65,535 (16-bit)				
Ramp down point automatic setting	Automatic setting within the range of (deceleration time) \leq (acceleration time x 2)				
Feed speed automatic correction function	Automatically lowers the feed speed for short distance positioning moves.				
Manual operation input	Manual pulsar input, pushbutton switch input				
Counter	COUNTER1: Command position counter (28-bit)				
	COUNTER2: Mechanical position counter (28-bit)				
	COUNTER3: Deflection counter (16-bit)				
	COUNTER4: General-purpose counter (28-bit)				
Comparators	28-bits x 5 circuits / axis				
Interpolation functions	Linear interpolation				
	Circular interpolation				
Operating temperature range	-40 to +85°C				
Power supply	Two power supplies of +5V±10% and 3.3 V±10%				
Package	128-pin QFP				

3. Terminal Assignment Diagram



Note: Pin number 1 is in the lower left corner when "PCL6025B" is seen right way up on the front of the chip.

4. Functions of Terminals

Signal name	Terminal No.	Input/ output	Logic	Description
GND	12, 17, 35, 48, 55, 64, 79, 94, 103, 118, 121, 122, 123, 124, 125	Power supply		Power supply ground. Make sure to connect all of these terminals.
VDD5	1, 26, 39, 61, 70,100, 109,120	Power supply		Supply +5 VDC power. The allowable power supply range is +5 VDC ±10%. Make sure to connect all of these terminals.
VDD3	15, 51, 90,126	Power supply		Supply +3.3 VDC power. The allowable power supply range is +3.3 VDC ±10%. Make sure to connect all of these terminals.
#RST	2	Input	Negative	Input reset signal. Make sure to set this signal LOW after turning ON the power and before starting operation. Input and holding #RST low for at least 8 cycles of the reference clock. For details about the chip's status after a reset, see section 11-1, "Reset" in this manual
CLK	119	Input		Input a CMOS level reference clock signal. (Signals other than the CLK are TTL level inputs.) Supply a standard reference clock frequency of 19.6608 MHz. The LSI creates output pulses based on the clock input on this terminal.
IF0 IF1	3, 4	Input		Enter the CPU-I/F modeIF1CPU exampleCPU signal connected to the terminalIF1IF0CPU example#RD#WRA0#WRQLL68000+5VR/#W#LDS#DTACKLHH8#RD#HWR(GND)#WAITHL8086#RD#WR(GND)READYHHZ80#RD#WRA0#WAIT
#CS	5	Input	Negative	When the signal level on this terminal is LOW, the #RD and #WR terminals will be valid.
#RD #WR	6 7	Input	Negative	Connect the I/F signals to the CPU. The #RD and #WR terminals are valid when #CS terminal is LOW.
A0 to A3	8 to 11	Input	Positive	Address control signals
#INT	13	Output	Negative	Outputs an interrupt request signal to an external CPU. After this terminal is turned ON, the signal will return to OFF when a RESET (error interrupt cause) or RIST (event interrupt cause) signal is received. The output status can be checked with an MSTSW (main status) command signal. The #INT output signal can be masked. When more than one 6025B LSI is used, a wired OR connection between #INT terminals is not allowed.
#WRQ	14	Output	Negative	Outputs a wait request signal to cause a CPU to wait. The LSI needs 4 reference clock cycles to process each command. If the #WRQ signal is not used, make sure that an external CPU does not access this LSI during this interval.

Signal name	Terminal No.	Input/ output	Logic	Description
#IFB	16	Output	Negative	Signal used to indicate that the LSI is processing commands. Use this signal to make connections with a CPU that does not have a wait control input terminal. When the LSI receives a write command from a CPU, this signal will go LOW. When the LSI finishes processing, this signal will go HIGH. The LSI makes sure that this terminal is HIGH and then proceeds to the next step.
D0 to D7	18 to 25	Input/ Output	Positive	Bi-directional data bus. When connecting a 16-bit data bus, connect the lower 8 signal lines here.
D8 to D15	27 to 34	Input/ Output	Positive	Bi-directional data bus. When connecting a 16-bit data bus, connect the upper 8 signal lines here. When a Z80-I/F (IF1 = H, IF0 = H) is used, provide a pull up resistor (5k to 10k ohms) on VDD5. (One resistor can be used for all 8 lines.)
#CSTA	36	Input/ Output *	Negative	Input/Output terminal for simultaneous start. When more than one LSI is used and you want to start them simultaneously, connect this terminal on each LSI. The terminal status can be checked using an RSTS command signal (extension status).
#STAx #STAy	49 88	Input U	Negative	Input terminal for external start signal. The function is identical with #CSTA input. However, it can be input independent on each axis.
#CSTP	37	Input/ Output *	Negative	Input/Output terminal for a simultaneous stop. (See Note 6.) When more than one LSI is used and you want to stop them simultaneously, connect this terminal on each LSI. The terminal status can be checked using an RSTS command signal (extension status).
#CEMG	38	Input U	Negative	Input for an emergency stop. While this signal is LOW, the PCL cannot start. If this signal changes to LOW while in operation, both of the motors will stop operation immediately.
ELLx ELLy	127 128	Input U		Specify the input logic for the ±EL signal. LOW: The input logic on ±EL is positive. HIGH: The input logic on ±EL is negative.
+ ELx + ELy	40 80	Input U	Negative %	Input end limit signal in the positive (+) direction. (See Note 6.) When this signal is ON while feeding in the positive (+) direction, the motor on that axis will stop immediately or will decelerate and stop. Specify the input logic using the ELL terminal. The terminal status can be checked using an SSTSW command signal (sub status).
- ELx - ELy	41 81	Input U	Negative %	Input end limit signal in the negative (-) direction. (See Note 6.) When this signal is ON while feeding in negative (-) direction, the motor on that axis will stop immediately, or will decelerate and stop. Specify the input logic using the ELL terminal. The terminal status can be checked using an SSTSW command signal (sub status).
SDx SDy	42 82	Input U	Negative#	Input deceleration signal. Selects the input method: LEVEL or LATCHED inputs. The input logic can be selected using software. The terminal status can be checked using an SSTSW command signal (sub status).

Signal name	Terminal No.	Input/ output	Logic	Description
ORGx ORGy	43 83	Input U	Negative #	Input zero position signal. Used for zero return and other operations. (Edge detection.) The input logic can be selected using software. The terminal status can be checked using an SSTSW command signal (sub status).
ALMx ALMy	44 84	Input U	Negative #	Input alarm signal. (See Note 6.) When this signal is ON, the motor on that axis stops immediately, or will decelerate and stop. The input logic can be selected using software. The terminal status can be checked using an SSTSW command signal (sub status).
OUTx OUTy	62 102	Output	Negative #	Outputs command pulses for controlling a motor, or outputs direction signals. When Common Pulse mode is selected: Outputs pulses, and the feed direction is determined by DIR signal. When 2-pulse output mode is selected: Outputs pulses in the positive (+) direction. The output logic can be changed using software.
DIRx DIRy	63 102	Output	Negative #	Output command pulses for controlling a motor, or outputs direction signal. When Common Pulse mode is selected: Outputs a direction signal. When 2-pulse output mode is selected: Output pulses in the negative (-) direction. The output logic can be changed using software
EAx, EBx EAy, EBy	58 59 97 98	Input U		Input this signal when you want to control the mechanical position using the encoder signal. Input a 90° phase difference signal (1x, 2x, 4x) or input positive (+) pulses on EA and negative (-) pulses on EB. When inputting 90° phase difference signals, if the EA signal phase is ahead of the EB signal, the LSI will count pulses. The counting direction can be changed using software.
EZx EZy	60 99	Input U	Negative #	Input a marker signal (this signal is output once for each turn of the encoder) when using the marker signal in zero return mode. Use of the EZ signal improves zero return precision. The input logic can be changed using software. The terminal status can be checked using an RSTS command signal (extension status).
PAx, PBx PAy, PBy	56, 57, 95, 96	Input U		Input for receiving external drive pulses, such as manual pulsar. You can input 90° phase difference signals (1x, 2x, 4x) or positive (+) pulses (on PA) and negative (-) pulses (on PB). When 90° phase difference signals are used, if the signal phase of PA is ahead of the PB signal, the LSI will count up. The counting direction can be changed using software.
#PEx #PEy	54 93	Input U	Negative	Setting these terminals LOW enables PA/PB and +DR/-DR input. By inputting an axis change switch signal, one manual pulsar can be used alternately for two axes.
+DRx, -DRx +DRy, -DRy	52 53 91 92	Input U	Negative #	You can start operation of the PCL with these signals, using external switches. Specifying the feed length, constant speed continuous feed, and high-speed continuous feed are possible. The input logic can be changed using software. The terminal status can be checked using an RSTS command signal (extension status).

Signal name	Terminal No.	Input/ output	Logic	Description
PCSx PCSy	50 89	Input U	Negative #	The PCL starts its positioning operation according to this input signal. (Override 2 of the target position.) The input logic can be changed using software. The terminal status can be checked using an RSTS command signal (extension status).
INPx INPy	45 85	Input U	Negative #	Input the position complete signal from servo driver (in-position signal). Input logic can be changed using software. The terminal status can be checked using an RSTS command signal (extension status).
CLRx CLRy	46 86	Input U	Negative #	Reset a specified counter from COUNTER1 to 4. The input logic can be changed using software. The terminal status can be checked using an RSTS command signal (extension status).
LTCx LTCy	47 87	Input U	Negative #	Latch counter value of specified counters (available on more than one) from COUNTER1 to 4. The input logic can be changed using software. The terminal status can be checked using an RSTS command signal.
FUPx FUPy	65 104	Output	Positive	Output is HIGH while accelerating.
FDWx FDWy	66 105	Output	Positive	Output is HIGH while decelerating.
MVCx MVCy	67 106	Output	Positive	Output is HIGH while at constant speed.
ERCx ERCy	69 108	Output	Negative #	Outputs a deflection counter clear signal to a servo driver as a pulse. The output logic and pulse width can be changed using software. A LEVEL signal output is also available. The terminal status can be checked using an RSTS command signal.
#BSYx #BSYy	68 107	Output	Negative	Outputs a LOW signal while feeding.
P0x/FUPx P0y/FUPy	71 110	Input/ Output*	Positive	Common terminal for general purpose I/O and FUP. (See Note 5.) As an FUP terminal, it outputs a LOW signal while accelerating As a general purpose I/O terminal, three possibilities can be specified: input terminal, output terminal, and one shot pulse output terminal. The usage, output logic of the FUP and one shot pulse parameters can be changed using software.
P1x/FDWx P1y/FDWy	72 111	Input/ Output *	Positive	Common terminal for general purpose I/O and FDW. (See Note 5.) As an FDW terminal, it outputs a LOW signal while decelerating. As a general purpose I/O terminal, three possibilities can be specified: input terminal, output terminal, and one shot pulse output terminal. The usage, output logic of the FDW and one shot pulse parameters can be changed using software.
P2x/MVCx P2y/MVCy	73 112	Input/ Output *	Positive	Common terminal for general purpose I/O and MVC. (See Note 5.) When used as an MVC terminal, it outputs a signal while performing a constant speed feed. The usage, and output logic of the MVC can be changed using software.
P3x/CP1x (+SLx) P3y/CP1y (+SLy)	74 113	Input/ Output *	Positive	Common terminal for general purpose I/O and CP1 (+SL). (See Note 5.) When used as a CP1 (+SL) terminal, it outputs a signal while establishing the conditions (within +SL) of comparator 1. The output logic of CP1 (+SL) as well the selection of input or output functions can be changed using software.

Signal name	Terminal No.	Input/ output	Logic	Description
P4x/CP2x (-SLx) P4y/CP2y (-SLy)	75 114	Input/ Output *	Positive	Common terminal for general purpose I/O and CP2 (-SL). When used as a CP2 (-SL) terminal, it outputs a signal while establishing the conditions (within -SL) of comparator 2. The output logic of CP2 (-SL) as well as the selection of input or output functions can be changed using software. (See Note 5.)
P5x/CP3x P5y/CP3y	76 115	Input/ Output *	Positive	Common terminal for general purpose I/O and CP3. (See Note 5.) When used as a CP3 terminal, it outputs a signal while establishing the conditions of comparator 3. The output logic of CP3 as well as the selection of input or output functions can be changed using software.
P6x/CP4x P6y/CP4y	77 116	Input/ Output *	Positive	Common terminal for general purpose I/O and CP4. (See Note 5.) When used as a CP4 terminal, it outputs a signal while establishing the conditions of comparator 4. The output logic of CP4 as well as the selection of input or output functions can be changed using software.
P7x/CP5x P7y/CP5y	78 117	Input/ Output *	Positive	Common terminal for general purpose I/O and CP5. (See Note 5.) When used as a CP5 terminal, it outputs a signal while establishing the conditions of comparator 5. The output logic of CP5 as well as the selection of input or output functions can be changed using software.

Note 1: "Input U" refers to an input with a pull up resistor. The internal pull up resistance (50 K to 100 K-ohms) is only used to keep a terminal from floating. If you want to use the LSI with an open collector system, an external pull up resistor (5k to 10 K-ohms) is required. As a noise prevention measure, pull up unused terminals to VDD5 using an external resistor (5 k to 10 K-ohms), or connect them directly to VDD5.

- Note 2: "Input/Output *" refers to a terminal with a pull up resistor. The internal pull up resistor (50 K to 100 K-ohms) is only used to keep a terminal from floating. If it is connected in a wired OR circuit, an external pull up resistor (5 k to 10 K-ohms) is required. As a noise prevention measure, pull up unused terminals to VDD5 using an external resistor (5 k to 10 K-ohms).
- Note 3: If an output terminal is not being used, leave it open.
- Note 4: "Positive" refers to positive logic. "Negative" refers to negative logic. "#" means that the logic can be changed using software. "%" means that the logic can be changed by the setting on another terminal. The logic shown refers only to the initial status of the terminal. The DIR terminal is initially in a 2-pulse mode.
- Note 5: Use the RENV2 register to select an output signal.

When P0 to P7 are set up as output terminals, they can be controlled simultaneously as 8 bits or one bit at a time using output bit control commands, depending on what is written to the output port (OTPB).

When P0 and P1 are set up as one shot pulse output terminals, they will output a one shot signal (T = Approx. 26 msec) using the output bit control command.

Note 6: When a deceleration stop is selected, latch the input signal ON until the PCL stops operation.

5. Block Diagram



6. CPU Interface

6-1. Setting up connections to a CPU

This LSI can be connected to four types of CPUs by changing the hardware settings. Use the IF0 and IF1 terminals to change the settings and connect the CPU signal lines as follows.

Setting status		CPU type	CPU signal to connect to the 6025B terminals								
IF1	IF0		#RD terminal	#WR terminal	A0 terminal	# WRQ terminal					
L	L	68000	+5V	R/#W	#LDS	#DTACK					
L	Н	H8	#RD	#HWR	(GND)	#WAIT					
Н	L	8086	#RD	#WR	(GND)	READY					
Н	Н	Z80	#RD	#WR	A0	#WAIT					

6-2. Precautions for designing hardware

- Apply a CMOS level clock to the CLK terminal.
- To reset the LSI, hold the #RST signal LOW, and input the CLK signal for at least 8-clock cycles.
- Connect unused P0 to P7 terminals to VDD5 through a pull up resistor (5 k to 10 K-ohms).
- When connecting a CPU with an 8-bit bus, pull up terminals D8 to D15 to VDD5 using an external resistor (5 k to 10k-ohms). (Shared use of one resister for the 8 lines is available.)
- Use the ELL terminal to change the ±EL signal input logic.
- To supply and shut down the power, turn both the 5 V and 3.3 V power supplies ON and OFF simultaneously, if possible.

Turning ON only one power supply may feed current to the other side, which can shorten the life of the LSI if this condition continues over time.

6-3. CPU interface circuit block diagram



2) 8086 interface



3) H8 interface







Note: For the 8086, H8, and 68000 interfaces, only word (16-bit) access is available. Byte (8-bit) access is not available.

6-4. Address map

6-4-1. Axis arrangement map

In this LSI, the control address range for each axis is independent. It is selected by using address input terminal A3, as shown below.

A3	Detail
0	X axis control address range
1	Y axis control address range

6-4-2.Internal map of each axis

The internal map of each axis is defined by A0, A1 and A2 address line inputs.

<When used with the Z80 I/F>

1) Write cycle

A0 to A2	Address signal	Processing detail
000	COMB0	Write a control command
001	COMB1	Assign the axis (specify a control command for execution)
010	ОТРВ	Change the status of the general-purpose output port (only bits as outputs are effective)
011		(Invalid)
100	BUFB0	Write to the input/output buffer (bits 0 to 7)
101	BUFB1	Write to the input/output buffer (bits 8 to 15)
110	BUFB2	Write to the input/output buffer (bits 16 to 23)
111	BUFB3	Write to the input/output buffer (bits 24 to 31)

2) Read cycle

A0 to A2	Address signal	Processing detail
000	MSTSB0	Read the main status (bits 0 to 7)
001	MSTSB1	Read the main status (bits 8 to 15)
010	IOPB	Read the general-purpose input/output port
011	SSTSB	Read the sub status
100	BUFB0	Read from the input/output buffer (bits 0 to 7)
101	BUFB1	Read from the input/output buffer (bits 8 to 15)
110	BUFB2	Read from the input/output buffer (bits 16 to 23)
111	BUFB3	Read from the input/output buffer (bits 24 to 31)

<When used with the 8086 I/F>

1) Write cycle

A1 to A2	Address signal	Processing detail					
00	COMW	Write the axis assignment and control command					
01	OTPW	Change the status of the general-purpose output port (only bits assigned as outputs are effective)					
10	BUFW0	Write to the input/output buffer (bits 0 to 15)					
11	BUFW1	Write to the input/output buffer (bits 16 to 31)					

2) Readout cycle

A1 to A2	Address signal	Processing detail
00	MSTSW	Read the main status (bits 0 to 15)
01	SSTSW	Read the sub status or general-purpose input/output port
10	BUFW0	Read from the input/output buffer (bits 0to 15)
11	BUFW1	Read from the input/output buffer (bits 16 to 31)

<When used with the H8 or 68000 I/F>

1) Write cycle

A1 to A2 Address signal			Processing detail
I	11	COMW	Write the axis assignment and control command
	10	OTPW	Change the status of the general-purpose output port (only bits as outputs are effective)
I	01	BUFW0	Write to the input/output buffer (bits 0 to 15)
I	00	BUFW1	Write to the input/output buffer (bits 16 to 31)

2) Readout cycle

I	A1 to A2	Address signal	Processing detail
I	11	MSTSW	Read the main status (bits 0 to 15)
I	10	SSTSW	Read the sub status or general-purpose input/output port
I	01	BUFW0	Read from the input/output buffer (bits 0 to 15)
I	00	BUFW1	Read from the input/output buffer (bits 16 to 31)

6-5. Description of the map details

- 6-5-1. Write the command code and axis selection (COMW, COMB) Write the commands for reading and writing to registers and the start and stop control commands for each axis.
 - COMB0: Set the command code. For details, see 7. "Command (Operation and Control commands)."
 - SELx to y: Select an axis for executing the command. If all of the bits are 0, only this axis (selected by A3) is selected. To write the same command to more than one axis, set the bits of the selected axes to 1. When you write to a register, the details of the input/output buffer are written into the register for its axis. When you read from a register, the details in the register are written into the input/output buffer for its axis.

	COMW														
	COMB1 COMB0														
15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
0	0	0	0	0	0	SELy	SELx								

6-5-2. Write to an output port (OTPW, OTPB)

Specify output terminal status from the general purpose I/O terminals P0 to P7.

Bits corresponding to terminals not set as outputs are ignored.

When writing a word, the upper 8 bits are ignored. However, they should be set to 0 for future compatibility.

OTP0 to 7: Specify the status of output terminals P7n to P0n (n = x, y). A HIGH is output when the bit is set to 1.

	OTPW														
		ОТРВ								I					
15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
0	0	0	0	0	0	0	0	OTP7	OTP6	OTP5	OTP4	OTP3	OTP2	OTP1	OTP0

6-5-3. Write/read the input/output buffer (BUFW, BUFB)

When you want to write data into a register, after placing the data in the input/output buffer, write a "register write command" into COMB0. The data in the input/output buffer will be copied into the register.

When you want to write data into the input/output buffer, write a "register read command" into COMB0. The data in the register will be copied to the input/output buffer. Then you can read the data from the input/output buffer.

The order for writing and reading buffers BUFW0 to 1 (BUFB0 to 3) is not specified. The data written in the input/output buffer can be read at any time.

BUF	FW1	BUF	W0
BUFB3	BUFB2	BUFB1	BUFB0
31 30 29 28 27 26 25 24	23 22 21 20 19 18 17 16	15 14 13 12 11 10 9 8	7 6 5 4 3 2 1 0

6-5-4. Reading the main status (MSTSW, MSTSB)

		MSTSW														
MSTSB1									MST	SB0			I			
	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
	SPDF	SPRF	SEOR	SCP5	SCP4	SCP3	SCP2	SCP1	SSC1	SSC0	SINT	SERR	SEND	SENI	SRUN	SSCM

Bit	Bit name	Details
0	SSCM	Set to 1 by writing a start command. Set to 0 when the operation is stopped.
1	SRUN	Set to 1 by the start pulse output. Set to 0 when the operation is stopped.
2	SENI	Stop interrupt flag
		When IEND in RENV2 is 1, the PCL turns ON the INT output when the status
		changes from operating to stop, and the SENI bit becomes 1. (After the main status
		is read, it returns to 0.) When IEND is set to 0, this flag will always be 0.
3	SEND	Set to 0 by writing start command. Set to 1 when the operation is stopped.
4	SERR	Set to 1 when an error interrupt occurs. Set to 0 by reading the RESET.
5	SINT	Set to 1 when an event interrupt occurs. Set to 0 by reading the RIST.
6 to 7	SSC0 to 1	Sequence number for execution or stopping.
8	SCP1	Set to 1 when the COMPARATOR 1 comparison conditions are met.
9	SCP2	Set to 1 when the COMPARATOR 2 comparison conditions are met.
10	SCP3	Set to 1 when the COMPARATOR 3 comparison conditions are met.
11	SCP4	Set to 1 when the COMPARATOR 4 comparison conditions are met.
12	SCP5	Set to 1 when the COMPARATOR 5 comparison conditions are met.
13 SEOR When a positioning override cannot be executed (writing the RMV		When a positioning override cannot be executed (writing the RMV register while
		stopped), this signal changes to 1. After the main status is read, it changes to 0.
14	SPRF	Set to 1 when the pre-register for the subsequent operation data is full.
15	SPDF	Set to 1 when the pre-register for comparator 5 is full.

Status change timing chart

1) When the continuous mode (MOD=00h, 08h) is selected.



2) When the PA/ PB continuous mode (MOD=01h) is selected.



3) When the DR continuous mode (MOD=02h) is selected.



4) When the auto stop mode is selected such as positioning operation mode (MOD=41h).



6-5-5. Reading the sub status and input/output port. (SSTSW, SSTSB, IOPB)

	SSTSW														
	SSTSB						IOPB								
15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
SSD	SORG	SMEL	SPEL	SALM	SFC	SFD	SFU	IOP7	IOP6	IOP5	IOP4	IOP3	IOP2	IOP1	IOP0

Bit	Bit name	Description
0 to 7	IOP0 to 7	Read the status of P0 to 7 (0: L level, 1: H level)
8	SFU	Set to 1 while accelerating.
9	SFD	Set to 1 while decelerating.
10	SFC	Set to 1 while feeding at constant speed.
11	SALM	Set to 1 when the ALM input is ON.
12	SPEL	Set to 1 when the +EL input is ON.
13	SMEL	Set to 1 when the -EL input is ON.
14	SORG	Set to 1 when the ORG input is ON.
15	SSD	Set to 1 when the SD input is ON. (Latches the SD signal.)

Note: When the backlash or slip correction function is used, SFU, SFD, and SFC will all be 0. The main status SRUM will be 1, even if this correction is used.

7. Commands (Operation and Control Commands)

7-1. Operation commands

After writing the axis assignment data to COMB1 (address 1 when a Z80 I/F is used), write the command to COMB0 (address 0 when a Z80 I/F is used), the LSI will start and stop, as well as change the speed of the output pulses.

When an 8086, H8, or 68000 I/F is used, write 16-bit data, which combines the axis assignment and operation command data.

7-1-1. Procedure for writing an operation command (the axis assignment is omitted)

Write a command to COMB0 (address 0 when a Z80 I/F is used).

A waiting time of 4 register reference clock cycles (approximately 0.2 µsec when CLK = 19.6608 MHz) is required for the interval between "writing a command" and "writing the next command," "writing a register" and "writing the I/O buffer," and between "reading a register" and "reading the I/O buffer." When the #WRQ output signal is used by connecting it to the CPU, the CPU automatically ensures this waiting time.

If you want to use a CPU that does not have this waiting function, arrange the program sequence so that access is only allowed after confirming that the #IFB output signal is HIGH.



7-1-2. Start command

1) Start command

If this command is written while stopped, the motor will start rotating. If this command is written while the motor is operating, it is taken as the next start command.

COMB0	Symbol	Description
50h	STAFL	FL constant speed start
51h	STAFH	FH constant speed start
52h	STAD	High speed start 1 (FH constant speed -> deceleration stop) Note. 1
53h	STAUD	High speed start 2 (Acceleration -> FH constant speed -> Deceleration stop) Note. 1

Note 1: For details, see section 10-1, "Speed patterns."

2) Residual pulses start command

Write this command after the motor is stopped on the way to a positioning, it will continue movement for the number of pulses left in the positioning counter.

COMB0 Symbol		Description				
54h	CNTFL	Residual pulses FL constant speed start				
55h	CNTFH	Residual pulses FH constant speed start				
56h	CNTD	Residual pulses high speed start 1 (FH constant speed start without				
		acceleration, with deceleration)				
57h CNTUD Residual pulses high speed start 2 (With acceleration and deceleration						

3) Simultaneous start command

By setting the RMD register, the LSI will start an axis which is waiting for #CSTA signal.

COMB0	Symbol	Description				
06h	CMSTA	Output one shot of the start pulse from the #CSTA terminal.				
2Ah	SPSTA	Only this axis will process the command, the same as when the #CSTA signal is input.				

7-1-3. Speed change command

Write this command while the motor is operating, the motor on that axis will change its feed speed. If this command is written while stopped it will be ignored.

COMB0 Symbol		Description			
40h	FCHGL	Change to the FL speed immediately.			
41h	FCHGH	Change to the FH speed immediately.			
42h	FSCHL	Decelerate and change to the FL speed.			
43h	FSCHH	Accelerate and change to the FH speed.			

7-1-4. Stop command

1) Stop command

Write this command to stop feeding while operating.

COMB0	Symbol	Description
49h	STOP	Write this command while in operation to stop immediately.
4Ah	SDSTP	Write this command while feeding at FH constant speed or high speed, the motor on that axis will decelerate to the FL constant speed and stop. If this command is written while the axis is being fed at FL constant speed, the motor on that axis will stop immediately.

2) Simultaneous stop command

Stop the motor on any axis whose #CSTP input stop function has been enabled by setting the RMD register.

COMB0 Symbol			Description					
			Description					
	07h	CMSTP	Outputs one shot of pulses from the #CSTP terminal to stop movement on th					
			axis.					

3) Emergency stop command

 Stops an axis in an emergency
 Description

 COMB0
 Symbol
 Description

 05h
 CMEMG
 Emergency stop (same as a #CEMG signal input)

7-1-5. NOP (do nothing) command

	5/	
COMB0	Symbol	Description
00h	NOP	This command does not affect the operation.

7-2. General-purpose output bit control commands

These commands control the individual bits of output terminals P0 to P7.

When the terminals are designated as outputs, the LSI will output signals from terminals P0 to P7. Commands that have not been designated as outputs are ignored.

The write procedures are the same as for the Operation commands.

In addition to this command, by writing to a general-purpose output port (OTPB: Address 2 when a Z80 I/F is used), you can set 8 bits as a group. See section 7-5, "General-purpose output port control."

, · · ·		0 1		1	1 1 1
COMB0	Symbol	Description	COMB0	Symbol	Description
10h	PORST	Make P0 LOW.	18h	P0SET	Make P0 HIGH.
11h	P1RST	Make P1 LOW.	19h	P1SET	Make P1 HIGH.
12h	P2RST	Make P2 LOW.	1Ah	P2SET	Make P2 HIGH.
13h	P3RST	Make P3 LOW.	1Bh	P3SET	Make P3 HIGH.
14h	P4RST	Make P4 LOW.	1Ch	P4SET	Make P4 HIGH.
15h	P5RST	Make P5 LOW.	1Dh	P5SET	Make P5 HIGH.
16h	P6RST	Make P6 LOW.	1Eh	P6SET	Make P6 HIGH.
17h	P7RST	Make P7 LOW.	1Fh	P7SET	Make P7 HIGH.

The P0 and P1 terminals can be set for one shot output (T = approx. 26 msec.) using the RENV2 (Environment setting 2) register, and the output logic can be selected.

To use them as one shot outputs, set the P0 terminal to P0M (bits 0 and 1) = 11, or, set the P1 terminal to P1M (bits 2 and 3) = 11. To change the output logic, set P0L (bit 16) on the P0 terminal and P1L (bit 17) on the P1 terminal.

In order to perform a one-shot output from the P0 and P1 terminals, a bit control command should be written. However, the command you need to write will vary, depending on the output logic selected. See the table below for the details.

Torminal	Logic sotting	Bit control	Torminal	Logic sotting	Bit control	
Terrinia	Logic setting	command	Terminar	Logic setting	command	
P0	Negative logic (P0L = 0)	P0RST (10h)	D1	Negative logic (P1L = 0)	P1RST (11h)	
	Positive logic (P0L = 1)	P0SET (18h)	ГТ	Negative logic (P1L = 1)	P1SET (19h)	

When writing control commands to output ports (OTPB: address 2 for the Z80 interface), the P0 and P1 terminals will not change.

7-3. Control command

Set various controls, such as the reset counter. The procedures for writing are the same as the operation commands.

7-3-1. Software reset command

Used to re	Jsed to reset this LSI.						
COMB0	Symbol	Description					
04h	SRST	Software reset. (Same function as making the #RST terminal LOW.)					
Note: After writing this command, do not access the LSI for at least 12 clock (CLK) cycles.							

7-3-2. Counter reset command

Reset counters to zero.

COMB0	Symbol	Description
20h	CUN1R	Reset COUNTER1 (command position).
21h	CUN2R	Reset COUNTER2 (mechanical position).
22h	CUN3R	Reset COUNTER3 (deflection counter).
23h	CUN4R	Reset COUNTER4 (general-purpose counter).

7-3-3. ERC output control command

Control the ERC signal using commands.

_	
Symbol	Description
ERCOUT	Outputs the ERC signal.
ERCRST	Resets the output when the ERC signal output is specified to a level type output.
	Symbol ERCOUT ERCRST

7-3-4. Pre-register control command

Cancel the pre-register settings and transfer the pre-register data to a register.

See section "8-2. Pre-register" in this manual for details about the pre-register.

COMB0	Symbol	Description
26h	PRECAN	Cancel the operation pre-register.
27h	PCPCAN	Cancel the RCMP5 operation pre-register (PRCP5).
2Bh	PRESHF	Shift the operation pre-register data.
2Ch	PCPSHF	Shift the RCMP5 operation pre-register data.
4Fh	PRSET	Use the pre-register operation for speed pattern change data using a
		comparator.

7-3-5. PCS input command

Entering this command has the same results as inputting a signal on the PCS terminal.

COMB0	Symbol	Description
28h	STAON	Alternative to a PCS terminal input.

7-3-6. LTCH input (counter latch) command

Entering this command has the same result as inputting a signal on the LTC terminal.

COMB0	Symbol	Description
29h	LTCH	Alternative to an LTC (latch counter) terminal input.

7-4. Register control command

By writing a Register Control command to COMB0 (Address 0 when a Z80 I/F is used), the LSI can copy data between a register and the I/O buffer.

When using the I/O buffer while responding to an interrupt, a precaution is required, reading the I/O buffer contents before using it and returning it to its original value after use.

- 7-4-1. Procedure for writing data to a register (the axis assignment is omitted)
 - 1) Write the data that will be written to a register into the I/O buffer (addresses 4 to 7 when a Z80 I/F is used). The order in which the data is written does not matter. However, secure two reference clock cycles between these writings.
 - 2) Then, write a "register write command" to COMB0 (address 0 when a Z80 I/F is used). After writing one set of data, wait at least four cycles (approx. 0.2 µsec when CLK = 19.6608 MHz) before writing the next set of data.

In both case1) and case 2), when the #WRQ output is connected to the CPU, the CPU wait control function will provide the waiting time between write operations automatically.



- 7-4-2. Procedure for reading data from a register (the axis assignment is omitted)
 - 1) First, write a "register read out command" to COMB0 (address 0 when a Z80 I/F is used).
 - Wait at least four reference clock cycles (approx. 0.2 µsec when CLK = 19.6608 MHz) for the data to be copied to the I/O buffer.
 - 3) Read the data from the I/O buffer (addresses 4 to 7 when a Z80 I/F is used). The order for reading data from the I/O buffer does not matter. There is no minimum time between read operations.

When the #WRQ output is connected to the CPU, the CPU wait control function will provide the waiting time between write operations automatically.



7-4-3. Table of register control commands

		Register			2nd pre-register						
No.	Detail		Read c	ommand	Write c	ommand		Read co	mmand	Write command	
		Name	COMB0	Symbol	COMB0	Symbol	Name	COMB0	Symbol	COMB0	Symbol
1	Feed amount, target position	RMV	D0h	RRMV	90h	WRMV	PRMV	C0h	RPRMV	80h	WPRMV
2	Initial speed	RFL	D1h	RRFL	91h	WRFL	PRFL	C1h	RPRFL	81h	WPRFL
3	Operation speed	RFH	D2h	RRFH	92h	WRFH	PRFH	C2h	RPRFH	82h	WPRFH
4	Acceleration rate	RUR	D3h	RRUR	93h	WRUR	PRUR	C3h	RPRUR	83h	WPRUR
5	Deceleration rate	RDR	D4h	RRDR	94h	WRDR	PRDR	C4h	RPRDR	84h	WPRDR
6	Speed magnification rate	RMG	D5h	RRMG	95h	WRMG	PRMG	C5h	RPRMG	85h	WPRMG
7	Ramping-down point	RDP	D6h	RRDP	96h	WRDP	PRDP	C6h	RPRDP	86h	WPRDP
8	Operation mode	RMD	D7h	RRMD	97h	WRMD	PRMD	C7h	RPRMD	87h	WPRMD
9	Circular interpolation center	RIP	D8h	RRIP	98h	WRIP	PRIP	C8h	RPRIP	88h	WPRIP
10	Acceleration S-curve	RUS	D9h	RRUS	99h	WRUS	PRUS	C9h	RPRUS	89h	WPRUS
11	Deceleration S-curve range	RDS	DAh	RRDS	9Ah	WRDS	PRDS	CAh	RPRDS	8Ah	WPRDS
12	Feed amount correction speed	RFA	DBh	RRFA	9Bh	WRFA					
13	Environment setting 1	RENV1	DCh	RRENV1	9Ch	WRENV1					
14	Environment setting 2	RENV2	DDh	RRENV2	9Dh	WRENV2					
15	Environment setting 3	RENV3	DEh	RRENV3	9Eh	WRENV3					
16	Environment setting 4	RENV4	DEh	RRENV4	0Eh	WRENV4					
17	Environment setting F		EOh		3111 A0b						
17	Environment setting 5				AUII						
10	Environment setting 6	REINVO	EIII	RREINVO	AIII	WRENVO					
19	Environment setting /	RENV/	E2n	RRENV/	A2n	WRENV/					
20	(command position)	RCUN1	E3h	RRCUN1	A3h	WRCUN1					
21	COUNTER2 (mechanical position)	RCUN2	E4h	RRCUN2	A4h	WRCUN2					
22	COUNTER3 (deflection counter)	RCUN3	E5h	RRCUN3	A5h	WRCUN3					
23	COUNTER4 (general purpose)	RCUN4	E6h	RRCUN4	A6h	WRCUN4					
24	Data for comparator 1	RCMP1	E7h	RRCMP1	A7h	WRCMP1					
25	Data for comparator 2	RCMP2	E8h	RRCMP2	A8h	WRCMP2					
26	Data for comparator 3	RCMP3	E9h	RRCMP3	A9h	WRCMP3					
27	Data for comparator 4	RCMP4	EAh	RRCMP4	AAh	WRCMP4					
28	Data for comparator 5	RCMP5	EBh	RRCMP5	ABh	WRCMP5	PRCP5	CBh	RPRCP5	8Bh	WPRCP5
29	Event INT setting	RIRQ	ECh	RRIRQ	ACh	WRIRQ					
30	COUNTER1 latched data	RLTC1	EDh	RRLTC1							
31	COUNTER2 latched data	RLTC2	EEh	RRLTC2							
32	COUNTER3 latched data	RLTC3	EFh	RRLTC3							
33	COUNTER4 latched data	RLTC4	F0h	RRLTC4							
34	Extension status	RSTS	F1h	RRSTS							
35	Error INT status	REST	F2h	RREST							
36	Event INT status	RIST	F3h	RRIST							
37	Positioning counter	RPLS	F4h	RRPI S							
38	EZ counter, speed	RSPD	F5h	RRSPD							
39	Ramping-down point	PSDC	F6h	RESDC						-	
40	Circular interpolation	RCI	FCh	RRCI	BCh	WRCI	PRCI	CCh	RPRCI	8Ch	WPRCI
41	Circular interpolation	RCIC	FDh	RRCI							
42	Interpolation status	RIPS	FFh	RRIPS							

7-5. General-purpose output port control command

By writing an output control command to the output port (OTPB: Address 2 when using a Z80 interface), the PCL will control the output of the P0 to P7 terminals.

When the I/O setting for P0 to P7 is set to output, the PCL will output signals from terminals P0 to P7 to issue the command.

When writing words to the port, the upper 8 bits are discarded. However, they should be set to zero to maintain future compatibility.

The output status of terminals P0 to P7 are latched, even after the I/O setting is changed to input. The output status for each terminal can be set individually using the bit control command.

7-5-1. Command writing procedures

Write control data to output port (OTPB: Address 2h when a Z80 I/F is used).

To continue with the next command, the LSI must wait for four reference clock cycles (approx. 0.2 µsec when CLK = 19.6608 MHz). The #WRQ terminal outputs a wait request signal.



8. Registers

8-1. Table of registers

The following registers are available for each axis.

	Dogistor	Dit			
No.	Register	Dil	R/W	Details	pre-register
	name	length			name
1	RMV	28	R/W	Feed amount, target position	PRMV
2	RFL	16	R/W	Initial speed	PRFL
3	RFH	16	R/W	Operation speed	PRFH
4	RUR	16	R/W	Acceleration rate	PRUR
5	RDR	16	R/W	Deceleration rate	PRDR
6	RMG	12	R/W	Speed magnification rate	PRMG
7	RDP	24	R/W	Ramping-down point	PRDP
8	RMD	28	R/W	Operation mode	PRMD
9	RIP	28	R/W	Circular interpolation center position, master axis feed	PRIP
				amount with linear interpolation and with multiple chips	
10	RUS	15	R/W	S-curve acceleration range	PRUS
11	RDS	15	R/W	S-curve deceleration range	PRDS
12	RFA	16	R/W	Speed at amount correction	
13	RENV1	32	R/W	Environment setting 1 (specify I/O terminal details)	
14	RENV2	32	R/W	Environment setting 2 (specify general-purpose port	
				details)	
15	RENV3	32	R/W	Environment setting 3 (specify zero return and counter	
				details)	
16	RENV4	32	R/W	Environment setting 4 (specify details for comparators 1 to	
				4)	
17	RENV5	28	R/W	Environment setting 5 (specify details for comparator 5)	
18	RENV6	32	R/W	Environment setting 6 (specify details for feed amount	
_	_	_		correction)	
19	RENV7	32	R/W	Environment setting 7 (specify vibration reduction control	
				details)	
20	RCUN1	28	R/W	COUNTER1 (command position)	
21	RCUN2	28	R/W	COUNTER2 (mechanical position)	
22	RCUN3	16	R/W	COUNTER3 (deflection counter)	
23	RCUN4	28	R/W	COUNTER4 (general-purpose counter)	
24	RCMP1	28	R/W	Comparison data for comparator 1	
25	RCMP2	28	R/W	Comparison data for comparator 2	
26	RCMP3	28	R/W	Comparison data for comparator 3	
27	RCMP4	28	R/W	Comparison data for comparator 4	
28	RCMP5	28	R/W	Comparison data for comparator 5	PRCP5
29	RIRQ	19	R/W	Specify event interruption cause	
30	RI TC1	28	R	COUNTER1 (command position) latch data	
31	RITC2	28	R	COUNTER2 (mechanical position) latch data	
32	RITC3	16	R	COUNTER3 (deflection counter) latch data	
33	RITC4	28	R	COUNTER4 (general-purpose) latch data	
34	RSTS	22	R	Extension status	
35	REST	18	R	Error INT status	
36	RIST	20	R	Event INT status	
37	RPLS	28	R	Positioning counter (number of residual nulses to feed)	
38	RSPD	23	R	F7 counter current speed monitor	
30	RSDC	20	P	Automatically calculated ramping_down point	
10	PCI	24	P///	Number of stens for interpolation	PRCI
11	RCIC	31	P	Circular interpolation step counter	
41		24		Interpolation status	
44		2 4	17		

8-2. Pre-registers

The following registers and start commands have pre-registers:

RMV, RFL, RFH, RUR, RDR, RMG, RDP, RMD, RIP, RUS, RDS, RCI, and RCMP5. The term pre-register refers to a register which contains the next set of operation data while the current step is executing. This LSI has the following 2-layer structure and executes FIFO operation. The pre-registers consist of two groups: the operation pre-registers (PRMV, PRFL, PRFH, PRUR,

PRDR, PRMG, PRDP, PRMD, PRIP, PRUS, PRDS, PRCI) and the comparator pre-register (PRCP5).



8-2-1. Writing to the operation pre-registers

The pre-registers have a two layer structure and each register can contain up to two pieces of operation data. Write the data to a pre-register (P register name). Registers that don't need to be changed do not need to be rewritten.

When the PCL stops its current operation, the data you wrote to the pre-registers is shifted into the working registers and used as the current data.

When the PCL is operating, the data remains stored as pre-register data.

The data will be transferred into the pre-registers when a start command is issued. When the current operation completes, the data will be shifted into the working registers and the PCL starts the new operation automatically. The status of the pre-registers can be checked by reading PFM in the RSTS register. When the PFM is value is "11," SPRF in the main status register (MSTSW) changes to "1". Writing data while the pre-register is full is not allowed.

To change the current operating status before the operation is complete, such as when you want to change the speed, write the new data directly to the working register.

The relationship between the write status of the pre-registers and the possible PFM values are as follows.										
Procedure	2nd pre-register	1st pre-register	Working register	PFM	SPR					
	-	-	-							

Procedure	2nd pre-register	1st pre-register	Working register	PFM	SPRF
Initial status	0 Undetermined	0 Undetermined	0 Undetermined	00	0
Write Operation Data 1	Data 1 is undetermined	Data 1 is undetermined	Data 1 is undetermined	00	0
Write a Start command	Data 1 is undetermined	Data 1 is undetermined	Data 1 is set	01	0
Write Operation Data 2 and a Start command while in operation	Data 2 is undetermined	Data 2 is set	Data 1 is set	10	0
Write Operation Data 3 and Start command while in operation	Data 3 is set	Data 3 is set	Data 1 is set	11	1
The operation using Operation Data 1 is complete	Data 3 is undetermined	Data 3 is set	Data 2 is set	10	0

Also, by setting an event interrupt cause in the RIRQ register (IRNM), the PCL can be set to output an #INT signal as the 2nd pre-register changes from "set" to "undetermined" status when the operation is complete.

For details, see 11-3-2. "Control the output pulse width and operation completion timing."

8-2-2. Cancel the pre-register operations

Use a pre-register Cancel command (26h) and a Stop command (49h, 4Ah) to cancel all the data in the pre-registers, and their status then becomes undetermined.

The pre-register data are also cancelled if the PCL stops with an error.

Note: When you want the next operation to start automatically using the pre-registers, set the operation completion timing to "cycle completion (METM = 0 on RMD)." When pulse completion (METM = 1 on RMD)" is set, the time between the last pulse and next operation start pulse will be as little as 15x T_{CLK} (T_{CKL}: Reference clock cycle).
8-2-3. Writing to the comparator pre-registers

Comparator 5 has a pre-register. To overwrite the current data, write directly to RCMP5. To write to the pre-register, write to PRCP5.

The comparator data will only be set by writing to PRCP5.

The status of the comparator pre-register can be checked by reading PFC in the RSTS register. When the PFC value is 11, SPDF in the main status register (MSTSW) will be 1.

Writing data to the pre-register when it is full is not allowed.

After the conditions have been established, the comparator data in the pre-register will be shifted when the condition changes from false to true.

Comparator data can be written regardless of the PCL mode (stopped/operating).

The relationship between the pre-register writing status and the PFC values are as follows.

Procedure	2nd pre-register	1st pre-register	Working register	PFC	SPDF
Initial status	0	0	0	00	0
	Undetermined	Undetermined	Undetermined		
Write Data 1 to PPCP5	Data 1 is	Data 1 is	Data 1 is	01	0
WHILE DAILA I TO FILCES	undetermined	undetermined	undetermined	01	0
Write Data 2 to PPCP5	Data 2 is	Data 2 is	Data 1 is set	10	0
White Data 2 to FIGF5	undetermined	undetermined		10	0
Write Data 3 to PRCP5	Data 3 is	Data 2 is set	Data 1 is set	11	1
	undetermined		Data 1 15 Set		•
Comparison result for Data 1 changes from true to false	Data 3 is undetermined	Data 3 is undetermined	Data 2 is set	10	0

Also, by setting an event interrupt cause in the RIRQ register (IRND), the PCL can be set to output an #INT signal as the 2nd pre-register changes from "set" to "undetermined" status when the operation is complete.

8-2-4. Cancel the comparator pre-register data

The pre-register cancel command (27h) will cancel the pre-register data and its status becomes undetermined. However, please note that the register will not change to the undetermined status.

8-3.Description of the registers

The initial value of all the registers and pre-registers is "0." Please note that with some registers, a value of "0" is outside the allowable setting range.

8-3-1. PRMV (RMV) registers

These registers are used to specify the target position for positioning operations. The set details change with each operation mode. PMV is the register for PRMV.

31	30 2	9 28	3 27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	& {	88																												

Setting range: -134,217,728 to +134,217,727.

By changing the RMV register while in operation, the feed length can be overridden.

8-3-2. PRFL (RFL) registers

These pre-registers are used to set the initial speed (stop seed) for high speed (with acceleration /deceleration) operations.

RFL is the register for PRFL.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*																

The setting range is 1 to 65,535. However, the actual speed [pps] may vary with the speed magnification rate setting in the PRMG register.

8-3-3. PRFH (RFH) registers

These pre-registers are used to specify the operation speed. RFH is the working register for PRFH. Write to this register to override the current speed.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*																

The setting range is 1 to 65,535. However, the actual speed [pps] may vary with the speed magnification rate set in the PRMG register.

8-3-4. PRUR (RUR) registers

These pre-registers are used to specify the acceleration rate. RUR is the register for PRUR.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*																
-																															

Setting range is 1 to 65,535.

8-3-5. PRDR (RDR) registers

These pre-registers are used to specify the deceleration rate. RDR is the register for PRDR.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*															1	

The normal setting range is 1 to 65,535.

When PRDR = 0, the deceleration rate will be the value set by PRUR.

Note 1: Bits marked with an "*" (asterisk) will be ignored when written and are 0 when read. Note 2: Bits marked with an "&" symbol will be ignored when written and will be the same value as the upper most bit among the non-marked bits. (Sign extension)

8-3-6. PRMG (RMG) registers

These pre-registers are used to set the speed magnification rate. RMG is the register for PRMG.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*												

The setting range is 2 to 4,095.

Sets the relationship between the speed register PRFL (RFL), PRFH (RFH), RFA values and the operation speeds.

The actual operation speed [pps] is a product of the speed magnification rate and the speed register setting.

[Setting example when the reference clock is 19.6608 MHz]

Setting	Speed magnification rate	Operation speed setting range [pps]	Setting	Speed magnification rate	Operation speed setting range [pps]
2999	0.1x	0.1 to 6,553.5	59	5x	5 to 327,675
1499	0.2x	0.2 to 13,107.0	29	10x	10 to 655,350
599	0.5x	0.5 to 32,767.5	14	20x	20 to 1,310,700
299	1x	1 to 65,535	5	50x	50 to 3,276,750
149	2x	2 to 131,070	2	100x	100 to 6,553,500

8-3-7. PRDP (RDP) registers

These pre-registers are used to set a ramping-down point (deceleration start point) for positioning operations.

RDP is the 2nd register for PRDP.

31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0

 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #
 #

MSDP	Setting details	bit #
0	Offset for automatically set values. When a positive value is entered, the PCL will start deceleration earlier and the FL speed range will be used longer. When a negative value is entered, the PCL will start deceleration later and will not reach the FL speed.	Same as bit 23.
1	When number of pulses left drops to less than a set value, the motor on that axis starts to decelerate.	0

Note 1: Bits marked with an "*" (asterisk) will be ignored when written and are 0 when read. Note 2: Bits marked with an "&" symbol will be ignored when written and will be the same value as the upper most bit among the non-marked bits. (Sign extension.)

8-3-8. PRMD (RMD) registers These pre-registers are used to set the operation mode. RMD is the register for PRMD.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
MIPF	MPCS	MSDP	METM	MCCE	MSMD	MINP	MSDE	MENI				MOD			
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	MPIE	MADJ	MSPO	MSPE	0	0	MAX1	MAX0	MSY1	MSY0	MSN1	MSN0

Bits	Bit name	Description
Setting b	asic operatio	n mode
0 to 6	MOD	Set operation mode. 000 0000 (00h): Continuous positive rotation controlled by command control. 000 1000 (08h): Continuous negative rotation controlled by command control. 000 0001 (01h): Continuous operation controlled by pulsar (PA/PB) input. 000 0010 (02h): Continuous operation controlled by external signal (+DR/-DR) input.
		001 0000 (10h): Positive rotation zero return operation. 001 1000 (18h): Negative rotation zero return operation. 001 0010 (12h): Positive feed leaving from the zero position. 001 1010 (1Ah): Negative feed leaving from the zero position. 001 0101 (15h): Zero search in the positive direction 001 1101 (1Dh): Zero search in the negative direction
		010 0000 (20h): Feed to +EL or +SL position. 010 1000 (28h): Feed to -EL or -SL position. 010 0010 (22h): Move away from the -EL or -SL position. 010 1010 (2Ah): Move away from the +EL or +SL position. 010 0100 (24h): Feed in the positive direction for a specified number of EZ counts. 010 1100 (2Ch): Feed in the negative direction for a specified number of EZ counts.
		100 0001 (41h): Positioning operation (specify the incremental target position) 100 0010 (42h): Positioning operation (specify the absolute position in COUNTER1) 100 0011 (43h): Positioning operation (specify the absolute position in COUNTER2) 100 0100 (44h): Zero return of command position (COUNTER1).
		100 0101 (45h): Zero return of mechanical position (COUNTER2). 100 0110 (46h): Single pulse operation in the positive direction. 100 1110 (4Eh): Single pulse operation in the negative direction. 100 0111 (47h): Timer operation
		 101 0001 (51h): Positioning operation controlled by pulsar (PA/PB) input. 101 0010 (52h): Positioning operation is synchronized with PA/PB (specify the absolute position of COUNTER1) 101 0011 (53h): Positioning operation is synchronized with PA/PB (specify the absolute position of COUNTER2) 101 0100 (54h): Zero return to the specified position controlled by pulsar (PA/PB)
		101 0101 (55h): Zero return to a mechanical position controlled by pulsar (PA/PB) input.
		110 0000 (60h): Continuous linear interpolation 1 (continuous operation with linear interpolation 1)
		110 0001 (61h): Linear interpolation 1 110 0010 (62h): Continuous linear interpolation 2 (continuous operation with linear interpolation 2)
		 110 0011 (63h): Linear interpolation 2 110 0100 (64h): CW circular interpolation operation 110 0101 (65h): CCW circular interpolation operation. 110 1000 (68h): Continuous linear interpolation 1, synchronized with PA/PB 110 1001 (69h): Linear interpolation 1, synchronized with PA/PB 110 1010 (6Ah): Continuous linear interpolation 2, synchronized with PA/PB. 110 1011 (6Bh): Linear interpolation 2, synchronized with PA/PB. 110 1010 (6Ch): Clockwise circular interpolation, synchronized with PA/PB 110 1101 (6Dh): Counter-clockwise circular interpolation, synchronized with PA/PB

Dito	Ditnomo	Description
	Bit Hame	
(MENI	1: When the pre-register is set, the PCL will not output an INT signal, even if IEND
		becomes 1.
Optical se	etting items	
8	MSDE	0: SD input will be ignored. (Checking can be done with RSTS in sub status)
		1: Decelerates (deceleration stop) by turning ON the SD input.
9	MINP	0: Delay using an INP input will be possible. (Checking can be done with RSTS in sub
		status)
		1: Completes operation by turning ON the INP input.
10	MSMD	Specify an acceleration/deceleration type for high speed feed. (0: Linear accel/decel.
		1: S-curve accel/decel.)
11	MCCE	1: Stop COUNTER1 (command position)
		This is used to move a mechanical part without changing the PCL control position
12	METM	Specify the operation complete timing (0: End of cycle 1: End of pulse)
		When using the vibration reduction function select "End of pulse"
13	MSDP	Specify the ramping down point for high speed feed (0: Automatic setting 1: Manual
10	MODI	setting)
		Effective for positioning operations and linear interpolation feeding
14	MDCS	1: While in automatic operation, control the number of pulses after the PCS input is
14	NIF CS	turned ONL (Override 2 for the torget position)
45		tumed ON. (Overnue 2 for the target position.)
10		11: make a constant, synthetic speed while performing interpolation regaing.
16 to 17	MSNU to 1	when you want to control an operation block, specify a sequence number using 2 bits.
		By reading the main status (MSTSW), a sequence number currently being executed
		(SSCU to 1) can be checked. Setting the sequence number does not affect the
		operation.
18 to 19	MSY0 to 1	After writing a start command, the LSI will start an axis synchronization operation
		based on other timing.
		00: Start immediately.
		01: The PCL starts on a STA input (#CSTA, #STA or command 06h, 2Ah).
		10: Start with an internal synchronous start signal.
		11: Start when a specified axis stops moving.
20 to 21	MAX 0 to 1	Specify an axis to check for an operation stop when the value of MSY 1 to 0 is 11.
		Setting examples
		01: Starts when the X axis stops.
		10: Starts when the Y axis stops.
		11: Starts when both the X and Z axes stop.
22 to 23	Not defined	(Always set to 0.)
24	MSPE	1:Deceleration stop or immediate stop by #CSTP input.
		This is used for a simultaneous stop with another axis when this other axis stops
		with an error.
25	MSPO	1: Outputs a CSTP (simultaneous stop) signal when stopping due to an error.
26	MADJ	Specify an FH correction function. (0: ON, 1: OFF.)
		When S-shaped deceleration is selected (MSMD = 1) and the operation is set to use
		linear interpolation 1 (MOD = 61h) with a constant synthesized speed control (MIPE =
		1), make sure to turn this bit ON.
27	MPIE	1: After the circular interpolation operation is complete the PCI will draw to the end
<u>_</u> '		noint automatically
28 to 31	Not defined	(Always set to 0.)

8-3-9. PRIP (RIP) registers

These pre-registers are used to set the center position for circular interpolation or a master axis feed amount for linear interpolation 2.

RIP is the register for PRIP.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	&	&	&																												

When MOD (bits 0 to 6) of the PRMD register are set as shown below, the register is enabled.

110 0010 (62h): Continuous linear interpolation 2 (continuous operation with the linear interpolation 2). 110 0011 (63h): Linear interpolation 2.

110 0100 (64h): Circular interpolation in a CW direction.

110 0101 (65h): Circular interpolation in a CCW direction.

With Continuous linear interpolation 2 and Linear interpolation 2, specify the feed amount on the master axis using an incremental value.

With circular interpolation, enter a circular center position using an incremental value. Setting range: -134,217,728 to +134,217,727

8-3-10. PRUS (RUS) registers

These pre-registers are used to specify the S-curve range of the S-curve acceleration. RUS is the register for PRUS.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*															

The normal setting range is 1 to 32,767.

When 0 is entered, the value of (PRFH - PRFL)/2 will be calculated internally and applied.

8-3-11. PRDS (RDS) registers

These pre-registers are used to specify the S-curve range of the S-curve deceleration. RDS is the register for PRDS.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*															

The normal setting range is 1 to 32,767. When 0 is entered, the value of (PRFH - PRFL)/2 will be calculated internally and applied.

8-3-12. RFA register

This register is used to specify the constant speed for backlash correction or slip correction. This is also used as a reverse constant speed for a zero return operation.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*																

Although the setting range is 1 to 65,535, the actual speed [pps] varies with the speed magnification rate setting in the RMG register.

Note 1: Bits marked with an "*" (asterisk) will be ignored when written and are 0 when read. Note 2: Bits marked with an "&" symbol will be ignored when written and will be the same value as the upper most bit among the non-marked bits. (Sign extension)

8-3-13. RENV1 register This register is used for Environment setting 1. This is mainly used to set the specifications for input/output terminals.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
ERCL	EPW2	EPW1	EPW0	EROR	EROE	ALML	ALMM	ORGL	SDL	SDLT	SDM	ELM	PMD2	PMD1	PMD0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
PDTC	PCSM	INTM	DTMF	DRF	FLTR	DRL	PCSL	LTCL	INPL	CLR1	CLR0	STPM	STAM	ETW1	ETW0

Bits	Bit name			Descriptio	n	
0 to 2	PMD0 to 2	Specify OUT	output pulse de	tails		
		PMD0 to 2	Positive	direction	Negativ	e direction
			OUT output	DIR output	OUT output	DIR output
		000		High		Low
		001		High		Low
		010		Low		High
		011		Low		High
		100		High	High	
		101				
		110				
3		stop. 1: Dece	leration stop.) N	when the ⊏∟ in lote 1, <u>2</u>		1. (0: Immediate
4	SDM	Specify the p	rocess to occur	when the SD in	put is turned ON	N. (0: Deceleration
5	SDLT	Specify the la	atch function of t	be SD input. (0	· OFF. 1: ON.)	
-	0221	Turns ON v	vhen the SD sigr	nal width is sho	rt.	
		When the S	D input is OFF	while starting, the	he latch signal is	s reset.
6		The latch si	gnal is also rese	et when SDL1 is	s 0.	() legie)
0 7		Specify the C	D SIGNAL INPULIO	<u>)GIC. (U: INEGauv</u> Logic (O: Nega	<u>'e logic. 1. rusin</u>	IVE logic.)
8		Specify the p	rocess to occur	when the ALM	input is turned (NI (0. Immediate
0		stop. 1: Dece	leration stop.) N	lote 2		
9		Specify the A	LM signal input	logic. (0: Negat	tive logic. 1: Pos	sitive logic.)
10	EROE	1: Automatica	ally outputs an E	RC signal wher	the axis is stop	ped immediately b
		a +EL, -EL	, ALM, or #CEM	1G input signal.	However, the E	RC signal is not
		output whe	en a deceleration	n stop occurs or	n the axis. When	n the EL signal is
		specified in	or a normal stop	, by setting MU ter the FRC sic	D = "UTUXUUU is output if :	(feed to the ⊨L an immediate stop
		occurs.	The Nine region			
11	EROR	1: Automatica	ally output the El	RC signal wher	the axis compl	etes a zero return.
12 to 14	EPW0 to 2	Specify the p	ulse width of the	ERC output si	gnal.	
		000: 12 µse 100: 13 ms	c 001: 102 µ ec 101: 52 m	µsec 010: 4 isec 110: 1	409 µsec 01 104 msec 11	11:1.6 msec 11: Level output
15	ERCL	Specify the E	RC signal outpu	It loaic. (0: Neg	ative logic. 1: Pr	ositive logic.)
16 to 17	ETW0 to 1	Specify the E	RC signal OFF	timer time.		
l		00: 0 µsec	10: 1.6 ms	sec		
		01: 12 µsec	; 11: 104 m	ISEC		
18	STAM	Specify the #	CSTA signal inp	out type. (0: Lev	el trigger. 1: Ed	ge trigger.)
19	STPM	Specify a sto	p method using	#CSTP input. /	(0: Immediate s	top. 1: Deceleratio
		stop.) Note 2				

Bits	Bit name	Description
20 to 21	CLR0 to 1	Specify a CLR input.
		00: Clear on the falling edge 10: Clear on a LOW.
		01: Clear on the rising edge 11: Clear on a HIGH.
22	INPL	Specify the INP signal input logic. (0: Negative logic. 1: Positive logic.)
23	LTCL	Specify the operation edge for the LTC signal. (0: Falling. 1: Rising)
24	PCSL	Specify the PCS signal input logic. (0: Negative logic. 1: Positive logic.)
25	DRL	Specify the +DR, -DR signal input logic. (0: Negative logic. 1: Positive logic.)
26	FLTR	1: Apply a filter to the +EL, -EL, SD, ORG, ALM, or INP inputs.
		When a filter is applied, signal pulses shorter than 4 µsec are ignored.
27	DRF	1: Apply a filter on the +DR, -DR, or PE inputs.
		When a filter is applied, signals pulses shorter than 32 msec are ignored.
28	DTMF	1: Turn OFF the direction change timer (0.2 msec) function.
29	INTM	1: Mask an INT output. (Changes the interrupt circuit.)
30	PCSM	1: Only allow the PCS input on the local axis #CSTA signal.
31	PDTC	1: Keep the pulse width at a 50% duty cycle.

- Note1: When a deceleration stop (ELM = 1) has been specified to occur when the EL input turns ON, the axis will start the deceleration when the EL input is turned ON. Therefore, the axis will stop by passing over the EL position. In this case, be careful to avoid collisions of mechanical systems.
- Note 2: When deceleration stop is selected, this bit remains ON until the PCL decelerates and stops. The PCL determines whether it has stopped normally or not according to the stop timing. Therefore, if an error stop signal is input while decelerating with high speed positioning, the PCL may determine whether the stop was normal. In this case, the PCL will continue to the next operation without canceling the data stored in the pre-registers. If a constant error stop signal is input, the PCL will not continue to the next operation and it will stop with an error.

8-3-14. RENV2 register This is a register for the Environment 2 settings. Specify the function of the general-purpose port, EA/EB input, and PA/PB input.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
P7M1	P7M0	P6M1	P6M0	P5M1	P5M0	P4M1	P4M0	P3M1	P3M0	P2M1	P2M0	P1M1	P1M0	P0M1	P0M0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
POFF	EOFF	SMAX	PMSK	IEND	PDIR	PIM1	PIM0	EZL	EDIR	EIM1	EIM0	PINF	EINF	P1L	P0L

Bits	Bit name	Description
0 to 1	P0M0 to 1	Specify the operation of the P0/FUP terminals
		00: General-purpose input
		01: General-purpose output
		10: Output the FUP (acceleration) signal.
		11: General-purpose one shot signal output (T = 26 msec) Note: 1
2 to 3	P1M0 to 1	Specify the operation of the P1/FDW terminals
		00: General-purpose input
		01: General-purpose output
		10: Output the FDW (deceleration) signal.
		11: General-purpose one shot signal output (1 = 26 msec) Note: 1
4 to 5	P2M0 to 1	Specify the operation of the P2/MVC terminal.
		00: General-purpose input
		01: General-purpose output
		10: Output the MVC (constant speed feeding) signal with negative logic.
0.44 7		11: Output the MVC (constant speed feeding) signal with positive logic.
6 10 7	P31010 10 1	Specify the operation of the P3/CP1 (+SL) terminals.
		00: General-purpose input
		10: Output the CP1 (satisfied the Comparator 1 conditions) signal with negative
		11: Output the CP1 (satisfied the Comparator 1 conditions) signal with positive
8 to 9	P4M0 to 1	Specify the operation of the P4/CP2 (-SL) terminals
0.00		00: General-purpose input
		01: General-purpose output
		10: Output the CP2 (satisfied the Comparator 2 conditions) signal with negative
		logic.
		11: Output the CP2 (satisfied the Comparator 2 conditions) signal with positive
		logic.
10 to 11	P5M0 to 1	Specify the operation of the P5/CP3 terminals.
		00: General-purpose input
		01: General-purpose output
		10: Output the CP3 (satisfied the Comparator 3 conditions) signal with negative
		logic.
		11: Output the CP3 (satisfied the Comparator 3 conditions) signal with positive
40.1 40		
12 to 13	P6M0 to 1	Specify the operation of the P6/CP4/ID terminals.
		00: General-purpose input
		101: General-purpose output
		11: Output the CP4 (satisfied the Comparator 4 conditions) signal with positive
1/1 to 15	P7M0to 1	Specify the operation of the P7/CP5 terminals
14 10 13		00. General-nurnose innut
		01: General-purpose output
		10: Output the CP5 (satisfied the Comparator 5 conditions) signal with negative
		logic.
		11: Output the CP5 (satisfied the Comparator 5 conditions) signal with positive
		logic.

Bits	Bit name	Description
16	P0L	Specify the output logic when the P0 terminal is used for FUP or as a one shot.
	l	(0: Negative logic. 1: Positive logic.)
17	P1L	Specify the output logic when the P1 terminal is used for FDW or as a one shot.
	I	(0: Negative logic. 1: Positive logic.)
18	EINF	1: Apply a noise filter to EA/EB/EZ input. Note 3.
		Ignores pulse inputs less than 3 CLK signal cycles long.
19	PINF	1: Apply a noise filter to PA/PB input. Note 3.
	ļ	Ignore pulse inputs less than 3 CLK signal cycles long.
20 to 21	EIM0 to 1	Specify the EA/EB input operation.
	1	00: Multiply a 90° phase difference by 1 (Count up when the EA input phase is
	1	anead.)
	l	ohood)
	1	alleau.) 10: Multiply 2 90° phase difference by 4 (Count up when EA input phase is
	1	ahead)
	l	11: Count up when the EA signal rises, count down when the EB signal falls.
22	EDIR	1. Reverse the counting direction of the FA/FB inputs.
23	EZL	Specify FZ signal input logic. (0: Falling edge. 1: Rising edge.)
24 to 25	PIM0 to 1	Specify the PA/PB input operation.
		00: Multiply a 90° phase difference by 1 (Count up when the PA input phase is
l I	l	ahead.)
l l	l	01: Multiply a 90° phase difference by 2 (Count up when the PA input phase is
l l	l	ahead.)
	l	10: Multiply a 90° phase difference by 4 (Count up when PA input phase is
l I	l	ahead.)
	ļ	11: Count up when the PA signal rises, count down when the PB signal falls.
26	PDIR	1: Reverse the counting direction of the PA/PB inputs.
27	IEND	1: Outputs an INT signal when stopping, regardless of whether the stop was normal
		or due to an error.
28	PMSK	1: Masks output pulses.
29	SMAX	1: Enable a start operation that is triggered by stop on the same axis.
30	EOFF	1: Disable EA/EB input.
21	POFF	1: Disable PA/PB input.

Note 1: For details about outputting a general-purpose one shot signal, see 7-2 "General-purpose output bit control commands."

8-3-15. RENV3 register This is a register for the Environment 3 settings. Zero return methods and counter operation specifications are the main function of this register.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
0	BSYC	CI41	CI40	CI31	CI30	CI21	CI20	EZD3	EZD2	EZD1	EZD0	ORM3	ORM2	ORM1	ORM0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
CU4F	I CU3H	CU2H	0	CU4B	CU3B	CU2B	CU1B	CU4R	CU3R	CU2R	CU1R	CU4C	CU3C	CU2C	CU1C

Bit	Bit name	Description
0 to 3	ORM0 to 3	Specify a zero return method.
		0000: Zero return operation 0
		- Stops immediately (deceleration stop when feeding at high speed) by
		changing the ORG input from OFF to ON.
		 COUNTER reset timing: When the ORG input is turned ON.
		0001: Zero return operation 1
		- Stops immediately (deceleration stop when feeding at high speed) by
		changing the ORG input from OFF to ON, and feeds in the opposite
		direction at RFA constant speed until ORG input is turned OFF. Then, feeds
		in the original direction at RFA speed. While doing so, it will stop
		immediately when the ORG input is turned ON again.
		- COUNTER reset timing: When ORG input is turned ON.
		0010: Zero return operation 2
		- When feeding at constant speed, movement on the axis stops immediately
		by counting the EZ signal after the ORG input is turned ON. When feeding
		at high speed, movement on the axis decelerates when the ORG input is
		turned ON and stops immediately by counting the EZ counts.
		- COUNTER reset timing: when counting the EZ signal.
		When feeding at constant around, movement on the axis stone immediately
		- when recording at constant speed, movement on the axis stops immediately by counting the EZ signal after the OPC input is turned ON. When feeding
		at high speed, the axis will decelerate and stop by counting the EZ signal
		after the ORG input is turned ON
		- COUNTER reset timing: When counting the E7 signal
		0100. Zero return operation 4
		- Stops immediately (deceleration stop when feeding at high speed) by
		turning the ORG input ON, and feeds in the reverse direction at RFA
		constant speed. Stops immediately by counting the EZ signal.
		- COUNTER reset timing: When counting the EZ signal.
		0101: Zero return operation 5
		- Stop immediately (deceleration stop when feeding at high speed) and
		reverse direction when the ORG input is turned ON. Then, stop immediately
		when counting the EZ signal.
		 COUNTER reset timing: When counting the EZ signal.
		0110: Zero return operation 6
		 Stop immediately (deceleration stop when ELM = 1) by turning ON the EL
		input, and reverse at RFA constant speed. Then stop immediately by
		turning OFF the EL input.
		- COUNTER reset timing: When EL input is OFF.
		0111: Zero return operation 7
		- Stop Immediately (deceleration stop when ELM = 1) by turning ON the EL
		input, and reverse direction at KFA constant speed. Then stop immediately
		COLINTED reset timing: When stonned by counting the EL input
		1000: Zero return operation 8
		- Stop immediately (deceleration stop when $EIM = 1$) and reverse direction
		by turning ON the FL signal. Then stop immediately (deceleration stop
		when feeding at high speed) when counting the F7 signal
		- COUNTER reset timing: When counting the EZ signal

Bit	Bit name	Description
0 to 3	ORM0 to 3	1001: Zero return operation 9
		- After executing a Zero return operation 0, move back to the zero position
		(operate until COUNTER2 = 0).
		1010: Zero return operation 10
		- After executing a Zero return operation 3, move back to the zero position
		(operate until COUNTER2 = 0).
		1011: Zero return operation 11
		- After executing a Zero return operation 5, move back to the zero position
		(operate until COUNTER2 = 0).
		1100: Zero return operation 12
		- After executing a Zero return operation 8, move back to the zero position
4 10 7		(operate until COUNTERZ = 0).
4 to 7	EZDU IO 3	Specify the EZ count up value that is used for zero return operations.
Q to Q	C120 to 21	Select the input count source for COUNTER2 (mechanical position)
0109		Select the input count source for COONTER2 (mechanical position). $00 \cdot EA/ER$ input
l I		00. LA/LD Input
		10 [°] PA/PR input
10 to 11	CI30 to 31	Select the input count source for COUNTER3 (deflection counter)
		00: Output pulse and EA/EB input (deflection counter)
l I		01: Output pulse and PA/PB input (deflection counter)
		10: EA/EB input and PA/PB input (deflection counter)
12 to 13	CI40 to 41	Select the input count source for COUNTER4 (general-purpose)
		00: Output pulse
l I		01: EA/EB input
		10: PA/PB input
		11: Divide the CLK count by 2
14	BSYC	1: Operate COUNTER4 only while LSI is operating (#BSY is low).
15	Not defined	(Always set to 0.)
16	CU1C	1: Reset COUNTER1 (command position) when the CLR input turns ON.
17	CU2C	1: Reset COUNTER2 (mechanical position) when the CLR input turns ON.
18	CU3C	1: Reset COUNTER3 (deflection counter) when the CLR input turns ON.
19	CU4C	1: Reset COUNTER4 (general-purpose) when the CLR input turns ON.
20	CU1R	1: Reset COUNTER1 (command position) when the zero return is complete.
21	CU2R	1: Reset COUNTER2 (mechanical position) when the zero return is complete.
22	CU3R	1: Reset COUNTER3 (deflection counter) when the zero return is complete.
23	CU4R	1: Reset COUNTER4 (general-purpose) when the zero return is complete.
24	CU1B	1: Operate COUNTER1 (command position) while in backlash/slip correction
		mode.
25	CU2B	1: Operate COUNTER2 (mechanical position) while in backlash/slip correction mode.
26	CU3B	1: Operate COUNTER3 (deflection counter) while in backlash/slip correction mode.
27	CU4B	1: Operate COUNTER4 (general-purpose) while in backlash/slip correction mode.
28	Not defined	(Always set to 0.)
29	CU2H	1: Stop the counting operation on COUNTER2 (mechanical position). Note 1.
30	CU3H	1: Stop the counting operation on COUNTER3 (deflection counter).
31	CU4H	1: Stop the counting operation on COUNTER4 (general-purpose).

Note 1: To stop the counting on COUNTER1 (command position), change MCCE (bit 11) in the RMD register.

8-3-16. RENV4 register This register is used for Environment 4 settings. Set up comparators 1 to 4.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
C2RM	C2D	1 C2D0	C2S	2 C2S1	C2S0	C2C1	C2C0	C1RM	C1D1	C1D0	C1S2	C1S1	C1S0	C1C1	C1C0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
C4D1	C4D	0 C4S3	C4S	2 C4S1	C4S0	C4C1	C4C0	IDXM	C3D1	C3D0	C3S2	C3S1	C3S0	C3C1	C3C0
Bit		Bit nar	ne						Descri	ntion					
0 to	1	C1C0 t	0 1	Select a	compa	arison	counte	er for co	mpara	ator 1. I	Note 1				
				00: CC	DUNTE	R1 (cc	omman	nd posit	ion)						
				01: CC		R2 (m	echani	ical pos	sition)						
				10. CC		R3 (ae	eneral-	purpos	e)						
2 to	4	C1S0 t	o 2	Select a	compa	arison	metho	d for co	mpara	ator 1. I	Note 2				
				001: R	CMP1	data =	Comp	oarison	count	er (rega	ardless	s of co	unting	directio	on)
				010: R		data =	= Comp = Comr	parison	count	er (wni er (whi	le cour le cour	nting u	p) own)		
				100: R	CMP1	data >	· Comp	oarison	count	er data		nung u	own)		
				101: R	CMP1	data <	Comp	oarison	count	er data					
				110: U	lse as	positive	e end s	softwar	e limit	(RCMF	P1< C(DUNTE	ER1) fied N	oto 1	
5 to	6	C1D0 t	o 1	Select a	proce	ss to e	xecute	when	the Co	mpara	tor 1 c	onditio	ns are	met.	
0.0	•	0.201	• •	00: No	ne (us	e as ai	n #INT	, termir	nal out	put, or	interna	al sync	hronou	us start	t)
				01: Im	mediat	e stop									
				10: De	celera	tion sto	on data	a to pre	regie	tor data) (char		(hae		
7		C1RM	N	1: Use (ER1 f	or ring	counte	r oper	ation b	v usino	a Com	parato	r 1.	
				See "11	-11-5.	Ring c	ounter	functio	n."			, I			
8 to	9	C2C0 t	o 1	Select a	compa	arison	counte	er for C	ompar	ator 2.	Note 1				
						:R1 (CC :R2 (m	omman echani	ical nos	ion)						
				10: CC	DUNTE	R3 (de	eflectio	n coun	ter)						
				11: CC	DUNTE	R4 (ge	eneral	purpos	e) ́						
10 to	12	C2S0 t	o 2	Select a	compa	arison	metho	d for C	ompar	ator 2.	Note 2). 		ماليم مال	
				0012 R		data =	= Comp = Comr	parison	count	er (rega er (whi	ardiess le cour	s or cou ntina u	unting n)	airectio	on)
				011: R	CMP2	data =	= Comp	oarison	count	er (whi	le cour	nting d	own)		
				100: R	CMP2	data >	· Comp	barison	count	er data					
				101: R	CMP2	> data data	Comp	softwa	count	er data + (RCM	P2>C		=R1)		
				Others	: Treat	ts that	the coi	mparis	on con	ditions	do no	t meet.	Note	4.	
13 to	14	C2D0 t	o 1	Select a	proce	ss to e	xecute	when	the Co	mpara	tor 2 c	onditio	ns are	met.	
				00: No	ne (us	e as ai	n #INT	, termir	nal out	put, or	interna	al sync	hronou	us star	t)
				101: Im	mediat	tion stop	ממ								
				11: Ch	ange o	perati	on data	a to pre	-regis	ter data	a (char	nge spe	eed).		
15		C2RN	N	1: Use (COUNT	ER2 f	or ring	counte	r oper	ation b	y using	g Com	parato	r 2.	
16 to	17	C2C0 +	0.1	See "11	-11-5.	Ring c	ounter	functio	n."	ator 2	Noto 1				
10 10	17	C3C0 I	01		DUNTE	R1 (cc	omman	nd posit	ion)	ator 5.	note i				
				01: CC	DUNTE	R2 (m	echani	ical pos	sition)						
				10: CC	DUNTE	R3 (de	eflectio	n coun	ter)						
10.15	00	00001		11: CC	JUNIE	:R4 (ge	eneral-	purpos	e)						
18 to	20	C3S0 t	02	Select a		arison data =	metho	d for co Darison	ompara	ator 3. I er (reg:	Note 2 ardless	s of co	untina	directio	n)
				010: R	CMP3	data =	= Comp	barison	count	er (whi	le cour	nting u	p)	uncour	511)
				011: R	CMP3	data =	Comp	oarison	count	er (whi	le cour	nting d	own)		
				100: R	CMP3	data >	Comp	oarison	count	er data					
				101: R 110: P	CIVIP3	> Bisu ttee he	ina ina	Jarison	count	er data					
				Others	: Treat	ts that	the coi	mparise	on con	ditions	do no	t meet.			

Bit	Bit name	Description
21 to 22	C3D0 to 1	Select a process to execute when the Comparator 3 conditions are met.
		00: None (use as an #INT, terminal output, or internal synchronous start)
		01: Immediate stop.
		10: Deceleration stop.
		11: Change operation data to pre-register data (change speed).
23	IDXM	0: Outputs an IDX signal while COUNTER4 = RCMP2.
		1: When COUNTER4 reaches 0 by counting, the PCL outputs an IDX signal for
		two CLK cycles.
		(This is only possible when the values in C4S0 to C4S3 are 1000 to 1010.)
24 to 25	C4C0 to 1	Select a comparison counter for Comparator 4. Note 1.
		00: COUNTER1 (command position)
		01: COUNTER2 (mechanical position)
		10: COUNTER3 (deflection counter)
		11: COUNTER4 (general purpose)
26 to 29	C4S0 to 3	Select a comparison method for Comparator 4. Note 3.
		0001: RCMP4 data = Comparison counter (regardless of counting direction)
		0010: RCMP4 data = Comparison counter (while counting up)
		0011: RCMP4 data = Comparison counter (while counting down)
		0100: RCMP4 data > Comparison counter data
		0101: RCMP4 data < Comparison counter data
		0111: Treats that the comparison conditions do not meet.
		1000: Use as IDX (synchronous) signal output (regardless of counting
		airection)
		1001: Use as IDX (synchronous) signal output (while counting up)
		Othere: Treate that the comparison conditions do not most
20 to 21		Cillers. Treats that the comparison conditions do not meet.
30 10 3 1	C4D0 10 1	Select a process to execute when the Comparator 4 conditions are met.
		00. None (use as an #INT, terminal output, or internal synchronous start)
		10: Decoloration aton
		10. Deceleration stop.
		IT: Change operation data to pre-register data (change speed).

- Note 1: When COUNTER3 (deflection counter) is selected as the comparison counter, the LSI compares the counted absolute value and the comparator data. (Absolute value range: 0 to 32,767.)
- Note 2: When you specify C1S0 to 2 = 110 (positive software limit) or C2S0 to 2 = 110 (negative software limit), select COUNTER1 (command position) as the comparison counter.
- Note 3: When C4S0 to 3 is set to 1000 to 1010 (synchronous signal output), select COUNTER4 (general-purpose) for the comparison counter. The other counters cannot be selected. To set the comparator, select a positive value.
- Note 4: When this bit is used as software limit, the PCL stops operation regardless of the settings for selecting a process when the conditions are satisfied. However, when the PCL is operating and "10: Deceleration stop" is selected, it only uses a deceleration stop when operating at high speed. In all other cases, it stops immediately.

8-3-17. RENV5 register This is a register for the Environment 5 settings. Settings for Comparator 5 are its main use.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
LTOF	LTFD	LTM1	LTM0	0	IDL2	IDL1	IDL0	C5D1	C5D0	C5S2	C5S1	C5S0	C5C2	C5C1	C5C0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	CU4L	CU3L	CU2L	CU1L	0	0	SYI1	SYI0	SYO3	SYO2	SY01	SYO0

Bit	Bit name	Description
0 to 2	C5C0 to 2	Select a comparison counter for comparator 5.
		000: COUNTER1 (command position) 011: COUNTER4 (general-purpose)
		001: COUNTER2 (mechanical position) 100: Positioning counter
		010: COUNTER3 (deflection counter) 101: Current speed data
3 to 5	C5S0 to 2	Select a comparison method for comparator 5.
		001: RCMP5 data = Comparison counter (regardless of counting direction)
		010: RCMP5 data = Comparison counter (while counting up)
		011: RCMP5 data = Comparison counter (while counting down)
		100: RCMP5 data > Comparison counter
		101: RCMP5 data < Comparison counter
		Others: Treats that the comparison conditions are not met.
6 to 7	C5D0 to 1	Select a process to execute when the Comparator 5 conditions are met.
		00: None (use as an INT, terminal output, or internal synchronous start)
		01: Immediate stop.
		10: Deceleration stop.
		11: Change operation data to pre-register data (change speed).
8 to 10	IDL0 to 2	Enter the number of idling pulses. (0 to 7 pulses)
11	Not defined	(Always set to 0.)
12 to 13	LTM0 to 1	Specify the latch timing for a counter (COUNTER1 to 4).
		00: When the LTC input turns ON.
		01: On an ORG input
		10: When the Comparator 4 conditions are met.
		11: When the Comparator 5 conditions are met.
14	LTFD	1: Latch the current speed in place of COUNTER3.
15	LTOF	1: Stop the latch by timing of a hardware operation. (Only used by software.)
16 to 19	SYO0 to 3	Select the output timing of the internal synchronous signal.
		0001: When the Comparator 1 conditions are met.
		0010: When the Comparator 2 conditions are met.
		0011: When the Comparator 3 conditions are met.
		0100: When the Comparator 4 conditions are met.
		0101: When the Comparator 5 conditions are met.
		1000: When starting acceleration.
		1001: When ending acceleration.
		1010. When starting deceleration.
		Othere Internel synchroneus signal systemitic OFF
00 to 04	0)/10 to 1	Others: Internal synchronous signal output is OFF.
20 to 21	SYIU to 1	Select an input source when starting with an internal synchronous signal.
		00: Internal synchronous signal output from the X axis.
00 to 00	Natdafinad	
22 10 23		(Always set to 0.)
24		1: Resets COUNTERT at the same time COUNTERT is latched.
25		1: Resets COUNTER2 at the same time COUNTER2 is latched.
26		IT: RESELS COUNTERS AT THE SAME TIME COUNTERS IS LATCHED.
2/	CU4L	1: Resets COUNTER4 at the same time COUNTER4 is latched.
28 to 31	Not defined	(Always set to 0.)

8-3-18. RENV6 register

This is a register for the Environment 6 settings. It is primarily used to set feed amount correction data.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
PSTP	0	ADJ1	ADJ0	BR11	BR10	BR9	BR8	BR7	BR6	BR5	BR4	BR3	BR2	BR1	BR0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
PMG4	PMG	3 PMG2	PMG1	PMG0	PD10	PD9	PD8	PD7	PD6	PD5	PD4	PD3	PD2	PD1	PD0

Bit	Bit name	Description
0 to 11	BR0to 11	Enter a backlash correction amount or a slip correction amount. (0 to 4095)
12 to 13	ADJ0 to 1	Select a feed amount correction method. 00: Turn OFF the correction function.
		01: Backlash correction 10: Slip correction
14	Not defined	(Always set to 0.)
15	PSTP	 Even if a stop command is written, the PCL will operate for the number of pulses that are already input on PA/PB. Note 1.
16 to 26	PD0 to 10	Specifies the division ratio for pulses on the PA/PB input. The number of pulses are divided using the set value/2048. When 0 is entered, the division circuit will be OFF. (= 2048/2048)
27 to 31	PMG0 to 4	Specifies the magnification rate for pulses on the PA/PB input. The number of pulses are multiplied by the set value + 1.

Note 1: When PSTP is 1, the Stop command will be ignored when #BSYn = H (OFF), regardless of the operation mode.

Before writing a Stop command, check the main status register. When SRN = 0, change PSTP to 0 and then write a Stop command.

8-3-19. RENV7 register

This is a register for the Environment 7 settings. It is primarily used to enter the time for the vibration reduction function. If both RT and FT data are other than zero, the vibration reduction function is turned ON.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
RT15	RT14	RT13	RT12	RT11	RT10	RT9	RT8	RT7	RT6	RT5	RT4	RT3	RT2	RT1	RT0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
FT15	FT14	FT13	FT12	FT11	FT10	FT9	FT8	FT7	FT6	FT5	FT4	FT3	FT2	FT1	FT0

Bit	Bit name	Description
0 to 15	RT0 to 15	Enter the RT time shown in the figure below.
		The units are 32 ticks of the reference clock (approx. 1.6 µsec).
16 to 31	FT0 to 15	Enter the FT time shown in the figure below.
1		The units are 32 ticks of the reference clock (approx. 1.6 µsec).

The dotted lines in the figure below are pulses added by the vibration reduction function.



8-3-20. RCUN1 register

This is a register used for COUNTER1 (command position counter). This is a counter used exclusively for command pulses. Setting rage: -134,217,728 to +134,217,727.

31	30) 29	/ 28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	&	. &	&																												

8-3-21. RCUN2 register

This is a register used for COUNTER2 (mechanical position counter). It can count three types of pulses: Command pulses, encoder signals (EA/EB input), pulsar inputs (PA/PB input). Setting range: -134,217,728 to +134,217,727.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	&	&	&																												

8-3-22. RCUN3 register

This is a register used for COUNTER3 (deflection counter).

It can count three types of deflections: Between command pulses and encoder signals, between command pulses and pulsar signals, and between encoder signals and pulsar signals. Setting range: -32,768 to +32,767.

31 30 29 28	27 26 25 24	23 22 21 20	19 18 17 16	15 14 13 12	11 10 9 8	7 6 5 4	3 2 1 0
& & & &	& & & &	& & & &	& & & &				

8-3-23. RCUN4 register

This is a register used for COUNTER4 (general-purpose counter).

It can count four types of signals: Command pulses, encoder signals (EA/EB input), pulsar signals (PA/PB input), and 1/2 ticks of the reference clock.

Setting range. $-154, 217, 720$ to $+154, 217, 727$.	

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	&	&	&																												

For details about the counters, see section 11-10, "Counters."

Note 1: Bits marked with an "*" (asterisk) will be ignored when written and are 0 when read. Note 2: Bits marked with an "&" symbol will be ignored when written and will be the same value as the upper most bit among bits having no marks when read. (Sign extension)

8-3-24. RCMP1 register

Specify the comparison data for Comparator 1. Setting range: -134,217,728 to +134,217,727.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	&	&	&																												

8-3-25. RCMP2 register

Specify the comparison data for Comparator 2. Setting range: -134,217,728 to +134,217,727.

31 30 29 28	27 26	25 24	23 22	21 20	19 18	17 16	15 14	13 12	11 10	98	76	54	3	2	1	0
& & & &																

8-3-26. RCMP3 register

Specify the comparison data for Comparator 3. Setting range: -134,217,728 to +134,217,727.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	&	&	&																												

8-3-27. RCMP4 register

Specify the comparison data for Comparator 4. Setting range: -134,217,728 to +134,217,727.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	&	&	&																												

8-3-28. RCMP5 (PRCP5) register

Specify the comparison data for Comparator 5. PRCP5 is the 2nd pre-register for RCMP5. Normally, use RCMP5. To use the comparator pre-register function, use PRCP5. Setting range: -134,217,728 to +134,217,727.

31 30 29 2	28 27	26 25	5 24	23 22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
& & &	&																									

For details about the comparators, see section 11-11, "Comparator."

Note 1: Bits marked with an "*" (asterisk) will be ignored when written and are 0 when read. Note 2: Bits marked with an "&" symbol will be ignored when written and will be the same value as the upper most bit among bits having no marks when read. (Sign extension)

8-3-29. RIRQ register

Enables event interruption cause.

Bits set to 1 that will enable an event interrupt for that event.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
IROL	IRLT	IRCL	IRC5	IRC4	IRC3	IRC2	IRC1	IRDE	IRDS	IRUE	IRUS	IRND	IRNM	IRN	IREN
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	0	0	0	0	0	0	0	0	0	IRSA	IRDR	IRSD

Bit	Bit name	Description
0	IREN	Stopping normally.
1	IRN	The next operation starts continuously.
2	IRNM	Available to write operation to the 2nd pre-register.
3	IRND	Available to write operation to the 2nd pre-register for Comparator 5.
4	IRUS	Starting acceleration.
5	IRUE	Ending acceleration.
6	IRDS	Starting deceleration.
7	IRDE	Ending deceleration.
8	IRC1	The comparator 1 conditions were met.
9	IRC2	The comparator 2 conditions were met.
10	IRC3	The comparator 3 conditions were met.
11	IRC4	The comparator 4 conditions were met.
12	IRC5	The comparator 5 conditions were met.
13	IRCL	The count value was reset by a CLR input.
14	IRLT	The count value was latched by an LTC input.
15	IROL	The count value was latched by an ORG input.
16	IRSD	The SD input turned ON.
17	IRDR	The ±DR input changed.
18	IRSA	The #STA input turned ON. (The #CSTA and #STA signals are ORed)
31 to 19	Not defined	(Always set to 0.)

8-3-30. RLTC1 register

Latched data for COUNTER1 (command position). (Read only.)

The contents of COUNTER1 are copied when triggered by the LTC, an ORG input, or an LTCH command.

Data range: -134,217,728 to +134,217,727.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	&	&	&																												

8-3-31. RLTC2 register

Latched data for COUNTER2 (mechanical position). (Read only.)

The contents of COUNTER2 are copied when triggered by the LTC, an ORG input, or an LTCH command.

Data range: -134,217,728 to +134,217,727.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	&	&	&																												

8-3-32. RLTC3 register

Latched data for COUNTER3 (deflection counter) or current speed. (Read only.) The contents of COUNTER3 or the current speed are copied when triggered by the LTC, an ORG input, or an LTCH command. When the LTFD in the RENV5 register is 0, the register latches the COUNTER3 data. When the LTFD is 1, the register latches the current speed. When the LTFD is 1 and movement on the axis is stopped, the latched data will be 0. Data range when LTFD is 0: -32,768 to +32,767.

Data range when LTDF is 1:0 to 65535.

31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0

 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$
 \$

8-3-33. RLTC4 register

Latched data for COUNTER4 (general-purpose). (Read only.)

The contents of COUNTER4 are copied when triggered by the LTC, an ORG input, or an LTCH command.

Data range: -134,217,728 to +134,217,727.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
&	&	&	&																												

For details about the counter data latch, see section 11-10, " Counter."

Note 1: Bits marked with an "*" (asterisk) will be ignored when written and are 0 when read. Note 2: Bits marked with an "&" symbol will be ignored when written and will be the same value as the upper most bit among bits having no marks when read. (Sign extension)

8-3-34. RSTS register The extension status can be checked. (Read only.)

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
SDIN	SLTC	SCLR	SDRM	SDRP	SEZ	SERC	SPCS	SEMG	SSTP	SSTA	SDIR	CND3	CND2	CND1	CND0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	0	0	0	0	0	0	PFM1	PFM0	PFC1	PFC0	SEST	SINP

Bit	Bit name	Descrip	otion
0 to 3	CND0 to 3	Reports the operation status.	
		0000: Under stopped condition	1000: Waiting for PA/PB input
		0001: Waiting for DR input	1001: Feeding at FA constant speed.
		0010: Waiting for #CSTA input	1010: Feeding at FL constant speed.
		0011: Waiting for an internal	1011: Accelerating
		synchronous signal	1100: Feeding at FH constant speed.
		0100: Waiting for another axis to stop.	1101: Decelerating
		0101: Waiting for a completion of ERC	1110: Waiting for INP input.
		timer	1111: Others (controlling start)
		0110: Waiting for a completion of	
		direction change timer	
	-	0111: Correcting backlash	
4	SDIR	Operation direction (0: Positive direction. 1	: Negative direction.)
5	SSTA	Becomes 1 when the #STA input signal tu	rns on. (The #CSTA and #STA signals
		are ORed)	
6	SSTP	Becomes 1 when the #CSTP input signal t	urns on.
7	SEMG	Becomes 1 when the #CEMG input signal	turns on.
8	SPCS	Becomes 1 when the PCS input signal turr	ns on.
9	SERC	Becomes 1 when the ERC input signal turn	ns on.
10	SEZ	Becomes 1 when the EZ input signal turns	on.
11	SDRP	Becomes 1 when the +DR input signal turr	ns on.
12	SDRM	Becomes 1 when the -DR input signal turn	s on.
13	SCLR	Becomes 1 when the CLR input signal turr	ns on.
14	SLTC	Becomes 1 when the LTC input signal turn	is on.
15	SDIN	Becomes 1 when the SD input signal turns	s on. (Status of SD input terminal.)
16	SINP	Becomes 1 when the INP input signal turn	s on.
17	SEST	Becomes 1 when the #STA input signal tur	rns on.
18 to 19	PFC0 to 1	Used to monitor the condition of the RCMF	P5 pre-register.
20 to 21	PFM0 to 1	Used to monitor the condition of the opera	tion pre-registers (other than RCMP5).
22 to 31	Not defined	(Always set to 0.)	

8-3-35. REST register

Used to check the error interrupt cause. (Read only.)

The corresponding bit will be "1" when that item has caused an error interrupt. This register is reset when read.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
ESAO	ESPO	ESIP	ESDT	0	ESSD	ESEM	ESSP	ESAL	ESML	ESPL	ESC5	ESC4	ESC3	ESC2	ESC1
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	0	0	0	0	0	0	0	0	0	0	ESPE	ESEE

Bit	Bit name	Description
0	ESC1	Stopped when Comparator 1 conditions were met. (+SL)
1	ESC2	Stopped when Comparator 2 conditions were met. (-SL)
2	ESC3	Stopped when Comparator 3 conditions were met.
3	ESC4	Stopped when Comparator 4 conditions were met.
4	ESC5	Stopped when Comparator 5 conditions were met.
5	ESPL	Stopped by the +EL input being turned ON.
6	ESML	Stopped by the -EL input being turned ON.
7	ESAL	Stopped by the ALM input being turned ON.
8	ESSP	Stopped by the #CSTP input being turned ON.
9	ESEM	Stopped by the #CEMG input being turned ON.
10	ESSD	Decelerated and stopped by the SD input being turned ON.
11	Not defined	(Always set to 0.)
12	ESDT	Stopped by an operation data error. (Note 1)
13	FSIP	Simultaneous stop with another axis due to an error stop on the other axis
	LOIP	during interpolation.
14	ESPO	An overflow occurred in the PA/PB input buffer counter.
15	ESAO	An out of range count occurred in the positioning counter during interpolation.
16	ESEE	An EA/EB input error occurred. (Does not stop)
17	ESPE	A PA/PB input error occurred. (Does not stop)
18 to 31	Not defined	(Always set to 0.)

Note 1: In any of the following cases, ESDT will be 1.

- 1) Write a Start command using linear interpolation 1 mode (MOD = 60h, 61h, 68h, and 69h) on only one axis.
- 2) Write a Start command using circular interpolation mode (MOD = 64h, 65h, 6Ch, and 6Dh) on only one axis.
- 3) Write a Start command using the circular interpolation mode after setting PRIP (arc center coordinates) to (0, 0).
- 4) Write a Start command using linear interpolation 2 mode (MOD = 62h, 63h, 6Ah, and 6Bh) while RIP is 0.

8-3-36. RIST register

This register is used to check the cause of event interruption. (Read only.) When an event interrupt occurs, the bit corresponding to the cause will be set to 1. This register is reset when read.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
ISOL	ISLT	ISCL	ISC5	ISC4	ISC3	ISC2	ISC1	ISDE	ISDS	ISUE	ISUS	ISND	ISNM	ISN	ISEN
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	0	0	0	0	0	0	0	0	ISSA	ISMD	ISPD	ISSD

Bit	Bit name	Description
0	ISEN	Stopped automatically.
1	ISN	The next operation starts continuously.
2	ISNM	Available to write operation to the 2nd pre-register.
3	ISND	Available to write operation to the 2nd pre-register for Comparator 5.
4	ISUS	Starting acceleration.
5	ISUE	Ending acceleration.
6	ISDS	Starting deceleration.
7	ISDE	Ending deceleration.
8	ISC1	The comparator 1 conditions were met.
9	ISC2	The comparator 2 conditions were met.
10	ISC3	The comparator 3 conditions were met.
11	ISC4	The comparator 4 conditions were met.
12	ISC5	The comparator 5 conditions were met
13	ISCL	The count value was reset by a CLR signal input.
14	ISLT	The count value was latched by an LTC input.
15	ISOL	The count value was latched by an ORG input.
16	ISSD	The SD input turned ON.
17	ISPD	The +DR input changed.
18	ISMD	The -DR input changed.
19	ISSA	The #STA input turned ON.
20 to 31	Not defined	(Always set to 0.)

8-3-37. RPLS register

This register is used to check the value of the positioning counter (number of pulses left for feeding). (Read only.)

At the start, this value will be the absolute value in the RMV register. Each pulse that is output will decrease this value by one.

31 30 29 28	27 26 2	25 24	23 22	21 20	19	18 17	16	15 1	4 13	12	11	10	9	8	7	6	5	4	3	2	1	0
0 0 0 0																						

8-3-38. RSPD register

This register is used to check the EZ count value and the current speed. (Read only.)

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
AS15	AS14	4 AS13	AS12	AS11	AS10	AS9	AS8	AS7	AS6	AS5	AS4	AS3	AS2	AS1	AS0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	0	0	0	0	0	IDC2	IDC1	IDC0	ECZ3	ECZ2	ECZ1	ECZ0

Bit	Bit name	Description
0 to 15	AS0 to 15	Read the current speed as a step value (same units as for RFL and RFH).
		When stopped the value is 0.
16 to 19	ECZ0 to 3	Read the count value of EZ input that is used for a zero return.
20 to 22	IDC0 to 2	Read the idling count value.
23 to 31	Not defined	(Always set to 0.)

8-3-39. RSDC register

This register is used to check the automatically calculated ramping-down point value for the positioning operation. (Read only.)

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
0	0	0	0	0	0	0	0																								

8-3-40. PRCI (RCI) registers

These registers are used to set circular interpolation stepping number.

PRCI is the pre-register for the RCI.

These registers only exist for the X axis. They do not exist for the Y axis because the Y axis cannot be used as a control axis in circular interpolation.

To decelerate during a circular interpolation, enter the number of steps (number of operations) required for the circular interpolation. Entering a number other than 0 can decelerate the speed by using an automatic ramping-down point.

Setting range: 0 to 2,147,483,648.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
*																															

8-3-41. RCIC register

This register is used to read the count of the number of circular interpolation steps that have been completed. (Read only.)

The RCI register value is loaded when a circular interpolation is started. This value is decreased by one for each circular interpolation step. However, if the counter value is 0, the PCL will not decrease it further.

The counter value at the completion of a circular interpolation is held in the PCL memory until the start of the next circular interpolation operation. The range for this value is 0 to 2,147,483,647. This register is shared by all axes, and the value is same when read from any axis.

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
0																															

8-3-42. RIPS register This register is used to check the interpolation setting status and the operation status. (Read only.) This register is shared by all axes, and the value is same when read from any axis.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
0	0	IPFy	IPFx	0	0	IPSy	IPSx	0	0	IPEy	IPEx	0	0	IPLy	IPLx
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	0	0	0	0	SED1	SED0	SDM1	SDM0	IPCC	IPCW	IPE	IPL

Bit	Bit name	Description
0	IPLx	1: X axis is in linear interpolation 1 mode.
1	IPLy	1: Y axis is in linear interpolation 1 mode.
2 to 3	Not defined	(Always set to 0.)
4	IPEx	1: X axis is in linear interpolation 2 mode.
5	IPEy	1: Y axis is in linear interpolation 2 mode.
6 to 7	Not defined	(Always set to 0.)
8	IPSx	1: X axis is in circular interpolation mode.
9	IPSy	1: Y axis is in circular interpolation mode.
10 to 11	Not defined	(Always set to 0.)
12	IPFx	1: X axis is specified for constant synthetic speed.
13	IPFy	1: Y axis is specified for constant synthetic speed.
14 to 15	Not defined	(Always set to 0.)
16	IPL	1: Executing linear interpolation 1.
17	IPE	1: Executing linear interpolation 2.
18	IPCW	1: Executing a CW directional circular interpolation.
19	IPCC	1: Executing a CCW directional circular interpolation.
20 to 21	SDM0 to 1	Current phase of a circular interpolation
		(00: 1st phase, 01: 2nd phase, 10: 3rd phase, 11: 4th phase)
22 to 23	SED0 to 1	Final phase in a circular interpolation
		(00: 1st phase, 01: 2nd phase, 10: 3rd phase, 11: 4th phase)
24 to 31	Not defined	(Always set to 0.)

9. Operation Mode

Specify the basic operation mode using the MOD area (bits 0 to 6) in the RMD (operation mode) register.

9-1. Continuous operation mode using command control

This is a mode of continuous operation. A start command is written and operation continues until a stop command is written.

MOD	Operation method	Direction of movement
00h	Continuous operation from a command	Positive direction
08h	Continuous operation from a command	Negative direction

Stop by turning ON the EL signal corresponding to the direction of operation.

When operation direction is positive, +EL can be used. When operation direction is negative, -EL is used.

In order to start operation in the reverse direction after stopping the motion by turning ON the EL signal, a new start command must be written.

9-2. Positioning operation mode

The following seven operation types are available for positioning operations.

MOD	Operation method	Direction of movement
41h	Positioning operation (specify target	Positive direction when $PRMV \ge 0$
	increment position)	Negative direction when PRMV < 0
42h	Positioning operation (specify the	Positive direction when PRMV ≥ COUNTER1
	absolute position in COUNTER1)	Negative direction when PRMV < COUNTER1
43h	Positioning operation (specify the	Positive direction when PRMV \geq COUNTER2
	absolute position in COUNTER2)	Negative direction when PRMV < COUNTER2
44h	Return to command position 0	Positive direction when COUNTER1 ≤ 0
	(COUNTER1)	Negative direction when COUNTER1 > 0
45h	Return to machine position 0	Positive direction when COUNTER2 ≤ 0
	(COUNTER2)	Negative direction when COUNTER2 > 0
46h	One pulse operation	Positive direction
4Eh	One pulse operation	Negative direction
47h	Timer operation	

9-2-1. Positioning operation (specify a target position using an incremental value) (MOD: 41h) This is a positioning mode used by placing a value in the PRMV (target position) register. The feed direction is determined by the sign set in the PRMV register.

When starting, the RMV register setting is loaded into the positioning counter (RPLS). The PCL instructs to feed respective axes to zero direction. When the value of the positioning counter drops to 0, movement on the axes stops. When you set the PRMV register value to zero to start a positioning operation, the LSI will stop outputting pulses immediately.

9-2-2. Positioning operation (specify the absolute position in COUNTER1) (MOD: 42h)

This mode only uses the difference between the PRMV (target position) register value and COUNTER1.

Since the COUNTER1 value is stored when starting to move, the PCL cannot be overridden by changing the COUNTER1 value. But, the target position can be overridden by changing the RMV value.

The direction of movement can be set automatically by evaluating the relative relationship between the PRMV register setting and the value in COUNTER1.

At start up, the difference between the RMV setting and the value stored in COUNTER1 is loaded into the positioning counter (RPLS). The PCL moves toward the zero position. When the positioning counter value reaches zero, it stops operation.

If the PRMV register value is made equal to the COUNTER1 value and the positioning operation is started, the PCL will immediately stop operation without outputting any command pulses.

9-2-3. Positioning operation (specify the absolute position in COUNTER2) (MOD: 43h)

This mode only uses the difference between the PRMV (target position) register setting and the value in COUNTER2.

Since the COUNTER2 value is stored when starting a positioning operation, the PCL cannot be overridden by changing the value in COUNTER2; However, it can override the target position by changing the value in RMV.

The direction of movement can be set automatically by evaluating the relationship between the PRMV register setting and the value in COUNTER2.

At start up, the difference between the RMV setting and the value stored in COUNTER2 is loaded into the positioning counter (RPLS). The PCL moves in the direction to the zero position. When the positioning counter value reaches zero, it stops operation.

If the PRMV register value is made equal to the COUNTER2 value and the positioning operation is started, the PCL will immediately stop operation without outputting any command pulses.

9-2-4. Command position 0 return operation (MOD: 44h)

This mode continues operation until the COUNTER1 (command position) value becomes zero. The direction of movement is set automatically by the sign for the value in COUNTER1 when starting. This operation is the same as when positioning (specify the absolute position in COUNTER1) by entering zero in the PRMV register; however, there is no need to specify the PRMV register.

9-2-5. Machine position 0 return operation (MOD: 45h)

This mode is used to continue operations until the value in COUNTER2 (mechanical position) becomes zero.

The number of output pulses and feed direction are set automatically by internal calculations based on the COUNTER2 value when starting.

This operation is the same as when positioning (specify the absolute position in COUNTER2) by entering zero in the PRMV register. However, there is no need to specify the PRMV register.

9-2-6. One pulse operation (MOD: 46h, 4Eh)

This mode outputs a single pulse.

This operation is identical to a positioning operation (incremental target positioning) that writes a "1" (or "-1") to the PRMV register. However, with this operation, you do need not to write a "1" or "-1" to the PRMV register.

9-2-7. Timer operation (MOD: 47h)

This mode allows the internal operation time to be used as a timer.

The internal effect of this operation is identical to the positioning operation. However, the LSI does not output any pulses (they are masked).

Therefore, the internal operation time using the constant speed start command will be a product of the frequency of the output pulses and the RMV register setting. (Ex.: When the frequency is 1000 pps and the RMS register is set to 120 pulses, the internal operation time will be 120 msec.) Write a positive number (1 to 134,217,727) into the RMV register.

The ±EL input signal, SD input signal, and software limits are ignored. (These are always treated as OFF.)

The ALM input signal #CSTP input signal, and #CEMG input signals are effective.

The backlash/slip correction, vibration restriction function, and when changing direction, this timer function is disabled.

The LSI stops counting from COUNTER1 (command position).

Regardless of the MINP setting (bit 9) in the RMD (operation mode) register, an operation complete delay controlled by the INP signal will not occur.

In order to eliminate deviations in the internal operation time, set the METM (bit 12) in the PRMD register to zero and use the cycle completion timing of the output pulse as the operation complete timing.

9-3. Pulsar (PA/PB) input mode

This mode is used to allow operations from a pulsar input.

In order to enable pulsar input, bring the #PE terminal LOW. Set POFF in the RENV2 register to zero. It is also possible to apply a filter on the #PE input.

After writing a start command, when a pulsar signal is input, the LSI will output pulses to the OUT terminal.

Use an FL constant speed start (STAFL: 50h) or an FH constant speed start (STAFH: 51h). Four methods are available for inputting pulsar signals through the PA/PB input terminal by setting the RENV2 (environmental setting 2) register.

- Supply a 90° phase difference signal (1x, 2x, or 4x).
- Supply either positive or negative pulses.

Note: The backlash correction function is available with the pulsar input mode. However, reversing pulsar input while in the backlash correction is unavailable.

Besides the above 1x to 4x multiplication, the PCL has a multiplication circuit of 1x to 32x and division circuit of (1 to 2048)/2048. For setting the multiplication from 1x to 32x, specify the PMG0 to 4 in the RENV6 and for setting the division of n/2048, specify the PD0 to 10 in the RENV6.



The timing of the UP1 and DOWN1 signals will be as follows by setting of the PIM0 to PIM1 in the RENV2.

1) When using 90° phase difference signals and 1x input (PIM = 00)

PA				
PB				
UP1				
DOWN1				
2) When u	sing 90° phase difference signals and 2x inp	ut (PIM = 0	1)	
PA				
PB				
UP1				
DOWN				
3) When u	sing 90° phase difference signals and 4x inp	ut (PIM = 1	0)	
PA				
PB				
UP1				
DOWN				
4) When u	sing two pulse input.			
PA				
PB				
UP1			-	
DOWN1				

When the 1x to 32x multiplication circuit is set to 3x (PMG = 2 on the RENV6), operation timing will be as follows.

UP1	 _∩		
DOWN1		Π	
UP2			
DOWN2			

When the n/2048 division circuit is set to 512/2048 (PD =512 on the RENV6), operation timing will be as follows.

UP2				
DOWN2				
UP3	 			
DOWN3				

The pulsar input mode is triggered by an FL constant speed start command (50h) or by an FH constant speed start command (51h).

Pulsar input causes the PCL to output pulses with some pulses from the FL speed or FH speed pulse outputs being omitted. Therefore, there may be a difference in the timing between the pulsar input and output pulses, up to the maximum internal pulse frequency.

The maximum input frequency for pulsar signals is restricted by the FL speed when an FL constant speed start is used, and by the FH speed when an FH constant speed start is used. The LSI outputs #INT signals as errors when both the PA and PB inputs change simultaneously, or when the input frequency is exceeded, or if the input/output buffer counter (deflection adjustment 16-bit counter for pulsar input and output pulse) overflows. This can be monitored by the REST (error interrupt factor) register.

FP < (speed) / (input I/F phase value) / (PMG setting value + 1) / (PD setting value /2048), PD setting value ≠ 0 FP < (speed) / (input I/F phase value), PD setting value = 0

<Examples of the relationship between the FH (FL) speed [pps] and the pulsar input frequency FP [pps]>

PA/PB input method	PMG setting value	PD setting value	Usable range
	0 (1x)	0	FP < FH (FL)
2 pulse input	0 (1x)	1024	FP < FH (FL) x 2
	2 (3x)	0	FP < FH (FL) / 3
	0 (1x)	0	FP < FH (FL)
90° phase difference 1x	0 (1x)	1024	FP < FH (FL) x 2
	2 (3x)	0	FP < FH (FL) / 3
	0 (1x)	0	FP < FH (FL) / 2
90° phase difference 2x	0 (1x)	1024	FP < FH (FL)
	2 (3x)	0	FP < FH (FL) / 6
	0 (1x)	0	FP < FH (FL) / 4
90° phase difference 4x	0 (1x)	1024	FP < FH (FL) / 2
	2 (3x)	0	FP < FH (FL) / 6



Note: When the PA/ PB input frequency fluctuates, take the shortest frequency, not average frequency, as "Frequency of FP" above.

Setting relationship of PA/PB input>	
Specify the PA/PB input <set (bit="" 1="" 24="" 25)="" in="" pim0="" renv2="" to=""></set>	[RENV2] (WRITE)
00: 90° phase difference, 1x 10: 90° phase difference, 4x	31 24
01: 90° phase difference, 2x 11: 2 sets of up or down input pulses	n n
Specify the PA/PB input count direction <set (bit="" 26)="" in="" pdir="" renv2="" to=""></set>	[RENV2] (WRITE)
0: Count up when the PA phase is leading. Or, count up on the rising edge of PA.	31 24 n
1: Count up when the PB phase is leading. Or, count up on the rising edge of PB.	
Enable/disable PA/PB input <set (bit="" 31)="" in="" poff="" renv2=""></set>	[RENV2] (WRITE)
0. Enable PA/PB input	31 24
1: Disable PA/PB input.	n
Set the +/- DR, #PE input filter <set (bit="" 27)="" drf="" in="" renv1=""></set>	[RENV1] (WRITE)
1: Insert a filter on +/- DR input and #PE input	31 24
By setting the filter, the PCL ignores signals shorter than 32 msec.	n
Reading operation status <cnd (bit="" 0="" 3)="" in="" rsts="" to=""></cnd>	[RSTS] (READ)
1000 : wait for PA/ PB input.	7 0
	n n n n
Reading PA/PB input error <espe (bit="" 17)="" in="" rest=""></espe>	[REST] (READ)
ESPE (bit 17) = 1: Occurs a PA/PB input error	23 16
	000000n-
Reading PA/PB input buffer counter status <esp0 (bit="" 14)="" in="" rest=""></esp0>	[REST] (READ)
ESPO(DIT 14) = 1: Occurs an overriow.	15 8
	- n

* In the descriptions in the right hand column, "n" refers to the bit position. "0" refers to bit positions where it is prohibited to write any value except zero and the bit will always be zero when read.

The pulsar input mode has the following 12 operation types.

The direction of movement for continuous operation can be changed by setting the RENV2 register, without changing the wiring connections for the PA/PB inputs.

MOD	Operation mode	Direction of movement
01h	Continuous operation using pulsar input	Determined by the PA/PB input.
51h	Positioning operation using pulsar input	Determined by the sign of the PRMV value.
•	(absolute position)	
52h	Positioning operation using pulsar input	Determined by the relationship of the RMV and
	(COUNTER1 absolute position)	COUNTER1 values.
53h	Positioning operation using pulsar input	Determined by the relationship of the RMV and
551	(COUNTER2 absolute position)	COUNTER2 values.
51h	Command position (COUNTER1) zero	Determined by the sign of the value in
3411	point return operation using pulsar input	COUNTER1.
<i></i>	Command position (COUNTER2) zero	Determined by the sign of the value in
000	point return operation using pulsar input	COUNTER2.
69h	Continuous linear interpolation 1 using	Determined by the sign of the value in PRMV.
0011	pulsar input	
69h	Linear interpolation 1 using pulsar input	Determined by the sign of the value in PRMV.
6 A b	Continuous linear interpolation 2 using	Determined by the sign of the value in PRMV.
0A11	pulsar input	
6Bh	Linear interpolation 2 using pulsar input	Determined by the sign of the value in PRMV.
	CW circular interpolation using pulsar	Determined by the circular interpolation
6CN	input	operation
	CCW circular interpolation using pulsar	Determined by the circular interpolation
ъDN	input	operation

9-3-1. Continuous operation using a pulsar input (MOD: 01h)

This mode allows continuous operation using a pulsar input.

When PA/PB signals are input after writing a start command, the LSI will output pulses to the OUT terminal.

PA/PB input method	PDIR	Feed direction	PA/PB input		
00° nhasa difference	0	Positive direction	When the PA phase leads the PB phase.		
so phase unerence	0	Negative direction	When the PB phase leads the PA phase.		
(1x, 2x, and 4x)	1	Positive direction	When the PB phase leads the PA phase.		
	1	Negative direction	When the PA phase leads the PB phase.		
2 pulse input of	0	Positive direction	PA input rising edge.		
2 puise input of	0	Negative direction	PB input rising edge.		
positive and	1	Positive direction	PB input rising edge.		
negative pulses	I	Negative direction	PA input rising edge.		

The feed direction depends on PA/PB signal input method and the value set in PDIR.

The PCL stops operation when the EL signal in the current feed direction is turned ON. But the PCL can be operated in the opposite direction without writing a restart command. When stopped by the EL input, no error interrupt (#INT output) will occur.

To release the operation mode, write an immediate stop command (49h).

- Note: When the "immediate stop command (49h)" is written while the PCL is performing a multiplication operation (caused by setting PIM 0 to 1 and PMG 0 to 4), the PCL will stop operation immediately and the total number of pulses that are output will not be an even multiple of the magnification. When PSTP in RENV6 is set to 1, the PCL delays the stop timing until an even multiple of pulses has been output. However, after a stop command is sent by setting PSTP to 1, check the MSTS. If SRUN is 0, set PSTP to 0. (When SRUN is 0 while PSTP is 1, the PCL will latch the stop command.)
- 9-3-2. Positioning operations using a pulsar input (MOD: 51h)

The PCL positioning is synchronized with the pulsar input by using the PRMV setting as incremental position data.

This mode allows positioning using a pulsar input.

The feed direction is determined by the sign in the RMV register.

When PA/PB signals are input, the LSI outputs pulses and the positioning counter counts down. When the value in the positioning counter reaches zero, movement on the axis will stop and another PA/ PB input will be ignored. Set the PRMV register value to zero and start the positioning operation. The LSI will stop movement on the axis immediately, without outputting any command pulses.

9-3-3. Positioning operation using pulsar input (specify absolute position to COUNTER1) (MOD: 52h) The PCL positioning is synchronized with the pulsar input by using the PRMV setting as the absolute value for COUNTER1.

The direction of movement is determined by the relationship between the value in PRMV and the value in COUNTER1.

When starting, the difference between the values in RMV and COUNTER1 is loaded into the positioning counter. When a PA/PB signal is input, the PCL outputs pulses and decrements the positioning counter.

When the value in the positioning counter reaches "0," the PCL any further ignores PA/PB input. If you try to start with PRMV = COUNTER1, the PCL will not output any pulses and it will stop immediately.

9-3-4. Positioning operation using pulsar input (specify the absolute position in COUNTER2) (MOD: 53h) The operation procedures are the same as MOD= 52h, except that this function uses COUNTER2 instead of COUNTER1.

9-3-5. Command position zero return operation using a pulsar input (MOD: 54h) This mode is used to feed the axis using a pulsar input until the value in COUNTER1 (command position) becomes zero. The number of pulses output and the feed direction are set automatically by internal calculation, using the COUNTER1 value when starting. Set the COUNTER1 value to zero and start the positioning operation, the LSI will stop movement on the axis immediately, without outputting any command pulses.

- 9-3-6. Mechanical position zero return operation using a pulsar input (MOD: 55h)
 Except for using COUNTER2 instead of COUNTER1, the operation details are the same as for MOD = 54h.
- 9-3-7. Continuous linear interpolation 1 using pulsar input (MOD: 68h)
 Performs continuous linear interpolation 1, synchronized with the pulsar input.
 For continuous linear interpolation 1 operation details, see section "9-8. Interpolation operations."
- 9-3-8. Linear interpolation 1 using pulsar input (MOD: 69h)
 Performs linear interpolation 1, synchronized with the pulsar input.
 Any pulsar inputs after operation is complete will be ignored.
 For linear interpolation 1 operation details, see section "9-8. Interpolation operations."
- 9-3-9. Continuous linear interpolation 2 using pulsar input (MOD: 6Ah)
 Performs continuous linear interpolation 2, synchronized with the pulsar input.
 For continuous linear interpolation 2 operation details, see section "9-8. Interpolation operations."
- 9-3-10. Linear interpolation 2 using pulsar input (MOD: 6Bh)
 Performs linear interpolation 2, synchronized with the pulsar input.
 Any pulsar inputs after operation is complete will be ignored.
 For linear interpolation 2 operation details, see section "9-8. Interpolation operations."
- 9-3-11. CW circular interpolation using pulsar input (MOD: 6Ch) Performs CW circular interpolation, synchronized with the pulsar input. Any pulsar inputs after operation is complete will be ignored. For CW circular interpolation operation details, see section "9-8. Interpolation operations."
- 9-3-12. CCW circular interpolation using pulsar input (MOD: 6Dh) Performs CCW circular interpolation, synchronized with the pulsar input. Any pulsar inputs after operation is complete will be ignored. For CCW circular interpolation operation details, see section "9-8. Interpolation operations."

9-4. External switch (±DR) operation mode

This mode allows operations with inputs from an external switch.

To enable inputs from an external switch, bring the #PE terminal LOW.

After writing a start command, when a +DR/-DR signal is input, the LSI will output pulses to the OUT terminal.

Set the RENVI (environment 1) register to specify the output logic of the ±DR input signal. The #INT signal can be set to send an output when ±DR input is changed.

The RSTS (extension status) register can be used to check the operating status and monitor the $\pm DR$ input.

It is also possible to apply a filter to the ±DR or #PE inputs.

Set the input logic of the +DR/-DR signals <set (bit="" 25)="" drl="" in="" renv1=""></set>	[RENV1]	(WRITE)
0: Negative logic	31	24
1: Positive logic		- n -
Applying a ±DR or #EP input filter <set (bit="" 27)="" drf="" in="" renv1=""></set>	[RENV1]	(WRITE)
1: Apply a filter to ±DR input or #PE inputs	31	24
When a filter is applied, pulses shorter than 32 msec will be ignored.	n	
Setting an event interrupt cause <set (bit="" 17)="" in="" irdr="" rirq=""> 1: Output the #INT signal when ±DR signal changed input.</set>	[RIRQ] 23 0 0 0 0 0	(WRITE) 16 - n -
Reading the event interrupt cause <ispd (bit="" 17)="" 18)="" and="" in="" ismd="" rist=""></ispd>	[RIST]	(READ)
ISPD(bit 17) = 1: When the +DR signal input changes.	23	16
ISMD(bit 18) = 1: When the -DR signal input changes.	0 0 0 0 -	n n -
Read operation status < CND (bits 0 to 3) in RSTS> 0001: Waiting for a DR input	[RSTS] 7 n	(READ) 0 n n n
Reading the ±DR signal <sdrp (bit="" 11)="" 12)="" and="" in="" rsts="" sdrm=""></sdrp>	[RSTS]	(READ)
SDRP = 0: +DR signal is OFF SDRP = 1: +DR signal is ON	15	8
SDRM = 0: -DR signal is OFF SDRM = 1: -DR signal is ON	n n	

The external switch operation mode has the following two forms

MOD	Operation mode	Direction of movement
02h	Continuous operation using an external switch.	Determined by +DB, - DR input.
56h	Positioning operation using an external switch.	Determined by +DB, - DR input.

9-4-1. Continuous operation using an external switch (MOD: 02h)

This mode is used to operate an axis only when the DR switch is ON.

After writing a start command, turn the +DR signal ON to feed the axis in the positive direction, turn the -DR signal ON to feed the axis in the negative direction, using a specified speed pattern. By turning ON an EL signal for the feed direction, movement on the axis will stop. However, the axis can be fed in the reverse direction.

An error interrupt (#INT output) will not occur.

To end this operation mode, write an immediate stop command (49h).

If the axis is being fed with high speed commands (52h, 53h), movement on the axis will decelerate and stop when the DR input turns OFF. If the DR input for reverse direction turns ON while decelerating, movement on the axis will decelerate and stop. Then it will resume in the opposite direction.

[Setting example]

- 1) Bring the #PE input LOW.
- 2) Specify RFL, RFH, RUR, RDR, and RMG (speed setting).
- 3) Enter "0000010" for MOD (bits 0 to 6) in the RMD (operation mode) register

4) Write a start command (50h to 53h).

CND (bits 0 to 3) of the RSTS (extension status) register will wait for "0001: DR input."

In this condition, turn ON the +DR or -DR input terminal. The axis will move in the specified direction using the specified speed pattern as long as the terminal is kept ON.

9-4-2. Positioning operation using an external switch (MOD: 56h)

This mode is used for positioning based on the DR input rising timing.

When started, the data in the RMV register is loaded into the positioning counter. When the DR input is ON, the LSI will output pulses and the positioning counter will start counting down pulses. When the positioning counter value reaches zero, the PCL stops operation.

Even if the DR input is turned OFF or ON again during the operation, it will have no effect on the operation. If you make the RMV register value 0 and start a positioning operation, the PCL will stop operation immediately without outputting any command pulses.

Turn ON the +DR signal to feed in the positive direction. Turn ON the -DR signal to feed in the negative direction.

By turning ON the EL signal corresponding to the feed direction, the axis will stop operation and issue an error interrupt (#INT output).

9-5. Zero position operation mode

	The following	six zero	position	operation	modes	are available.
--	---------------	----------	----------	-----------	-------	----------------

MOD	Operation mode	Direction of movement	
10h	Zero return operation	Positive direction	
18h	Zero return operation	Negative direction	
12h	Leaving the zero position operation	Positive direction	
1Ah	Leaving the zero position operation	Negative direction	
15h	Zero position search operation	Positive direction	
1Dh	Zero position search operation	Negative direction	

Depending on the operation method, the zero position operation uses the ORG, EZ, or ±EL inputs. Specify the input logic of the ORG input signal in the RENV1 (environment 1) register. This register's terminal status can be monitored with an SSTSW (sub status) command.

Specify the input logic of the EZ input signal in the RENV2 (environment 2) register. Specify the number for EZ to count up to for a zero return complete condition in the RENV3 (environment 3) register. This register's terminal status can be monitored by reading the RSTS (extension status) register.

Specify the logic for the ±EL input signal using the ELL input terminals. Specify the operation to execute when the signal turns ON (immediate stop/deceleration stop) in the RENV1 register. This register's terminal status can be monitored with an SSTSW (sub status) command.

An input filter can be applied to the ORG input signal and $\pm EL$ input signal by setting the RENV1 register.

Set the ORG signal input logic <set (bit="" 7)="" in="" orgl="" renv1=""></set>	[RENV1] (W	/RITE)
0: Negative logic	7	0
1: Positive logic	n	
Read the ORG signal <sorg (bit14)="" in="" sstsw=""></sorg>	[SSTSW] (F	READ)
0: Turn OFF the ORG signal	15	8
1: Turn ON the ORG signal	- n	
Set the EZ signal input logic <set (bit="" 23)="" ezl="" in="" renv2=""></set>	[RENV2] (W	/RITE)
0: Falling edge	23	16
1: Rising eage	n	
Set the EZ count <set (bits="" 3="" 4="" 7)="" ezd0="" in="" renv3="" to=""></set>	[RENV3] (W	/RITE)
Specify the number for EZ to count up to that will indicate a zero return	7	0
completion.	n n n n	
Enter the value (the count minus 1) in EZDU to 3. Setting range: 0 to 15.		
Read the EZ signal < SEZ (bit 10) in RS15>	[RSTS] (F	READ)
1: Turn ON the EZ signal	15	8
	n	
Set the ±EL signal input logic <ell input="" terminal=""></ell>		
L: Positive logic input		
H: Negative logic input		
Specify a method for stopping when the \pm EL signal turns ON <set (bit="" 3)<="" elm="" td=""><td>[RENV1] (W</td><td>RITE)</td></set>	[RENV1] (W	RITE)
IN RENV1 >	7	0
1: Deceleration stop when the $\pm EL$ signal turns ON.	n -	
Read the +EL signal <spel (bit="" 12)="" 13)="" in="" smel="" sstsw=""></spel>		
SPEL = 0. Turn OFE + EL signal SPEL = 1. Turn ON + EL signal	[5515W] (R	EAD)
SMEL = 0: Turn OFF - EL signal SMEL = 1: Turn ON - EL signal		8
	<u> - - n n - - </u>	
Applying an input filter to the ±EL and ORG inputs <set (bit="" 26)="" fltr="" in<="" td=""><td>[RENV1] (W</td><td>RITE)</td></set>	[RENV1] (W	RITE)
KENV1>	7	0
By applying a filter, pulses shorter than 4 uses will be ignored	n -	
by apprying a filler, puises shorter than 4 psec will be ignored.		

9-5-1. Zero return operation

After writing a start command, the axis will continue feeding until the conditions for a zero return complete are satisfied.

MOD: 10h Positive direction zero return operation

18h Negative direction zero return operation

When a zero return is complete, the LSI will reset the counter and output an ERC (deflection counter clear) signal.

The RENV3 register is used to set the basic zero return method. That is, whether or not to reset the counter when the zero return is complete. Specify whether or not to output the ERC signal in the RENV1 register.

For details about the ERC signal, see 11-6-2, "ERC signal."

Set the zero return method <set (bits="" 0="" 3="" 3)="" in="" orm0="" renv3="" to=""></set>	[RENV3] (WRITE)	
0000: Zero return operation 0 - Stop immediately (deceleration stop when feeding at high speed) when the ORG signal turns ON - COUNTER reset timing: When the ORG input signal turns ON.	7 0 n n n n	
0001: Zero return operation 1 The axis will stop immediately (or make a deceleration stop when feeding at high speed) when the ORG signal turns ON. Then, it will feed in the opposite direction at RFA constant speed until the ORG signal turns OFF. Then, the axis will move back in the original direction at RFA speed and stop instantly when ORG turns ON again.		
 0010: Zero return operation 2 After the ORG signal turns ON when feeding at constant speed, the LSI will start counting EZ pulses. The axis will stop immediately when the LSI finishes counting EZ pulses. After the ORG signal turns ON when feeding at high speed, the axis will start decelerating. At the same time, the LSI will start counting EZ pulses. When the LSI finishes counting EZ pulses, the axis will start counting EZ pulses. 		
 0011: Zero return operation 3 After the ORG signal turns ON when feeding at constant speed, the LSI will start counting EZ pulses. The axis will stop instantly when the LSI finishes counting EZ pulses. After the ORG signal turns ON when feeding at high speed, the LSI will start counting EZ pulses. When the LSI finishes counting EZ pulses, the axis will decelerate and stop. 		
0100: Zero return operation 4 After the ORG signal turns ON when feeding at constant speed, the axis will stop immediately. Then, the axis will start to feed in the opposite direction at FA speed. After the ORG signal turns OFF, the LSI will start counting EZ pulses. After the LSI finishes counting EZ pulses, the axis will stop instantly. After the ORG signal turns ON when feeding at high speed, the axis will decelerate and stop. Then, the axis will start to feed in the opposite direction at FA speed. After the ORG signal turns OFF, the LSI will start counting EZ pulses. After the LSI finishes counting EZ pulses, the axis will start counting EZ pulses.		
0101: Zero return operation 5 After the ORG signal turns ON when feeding at constant speed, the axis will stop immediately. Then, the axis will start feeding in the opposite direction at FL speed. After the ORG signal turns OFF, the LSI will start counting EZ pulses. After the LSI finishes counting EZ pulses, the axis will stop instantly. After the ORG signal turns ON when feeding at high speed, the axis will decelerate and stop. Then, the axis will start to feed in the opposite direction, accelerating from FL to FH speed. After the ORG signal turns OFF, the LSI will start counting EZ pulses. After the LSI finishes counting EZ pulses, the axis will decelerate and stop.		
0110: Zero return operation 6 After the EL signal turns ON when feeding at constant speed, the axis will stop immediately. Then, the axis will start feeding in the opposite direction at FA speed. When the EL signal turns OFF, the axis will stop instantly. After the EL signal turns ON when feeding at high speed, if ELM is 0, the axis will		
 stop immediately. If ELM is 1, the axis will decelerate and stop from that position. Then, from the stopped position, the axis will start to feed in the opposite direction at FA speed. When the EL signal turns OFF, the axis will stop instantly. 0111: Zero return operation 7 After the EL signal turns ON when feeding at constant speed, the axis will stop immediately. Then, the axis will start feeding in the opposite direction at FA speed. After the EL signal turns OFF, the LSI will start counting EZ pulses. After the LSI finishes counting EZ pulses, the axis will stop istantly. After the EL signal turns ON when feeding at high speed, if ELM is 0, the axis will stop immediately. If ELM is 1, the axis will decelerate and stop. Then, from the stopped position, the axis will start to feed in the opposite direction at FA speed. After the EL signal turns OFF, the LSI will start counting EZ pulses. After the EL signal turns ON when feeding at high speed, if ELM is 0, the axis will stop immediately. If ELM is 1, the axis will decelerate and stop. Then, from the stopped position, the axis will start to feed in the opposite direction at FA speed. After the EL signal turns OFF, the LSI will start counting EZ pulses. After the LSI finishes counting EZ pulses, the axis will stop instantly.	[RENV3] 7 	(WRITE) 0 <u>n n n n</u>
---	--------------------------	--------------------------------
1000: Zero return operation 8 After the EL signal turns ON when feeding at constant speed, the axis will stop immediately. Then, the axis will start feeding in the opposite direction at FL speed. After the EL signal turns OFF, the LSI will start counting EZ pulses. After the LSI finishes counting EZ pulses, the axis will stop instantly. After the EL signal turns ON when feeding at high speed, if ELM is 0, the axis will stop immediately. If ELM is 1, the axis will decelerate and stop from that position. Then, from the stopped position, the axis will start to feed in the opposite direction, accelerating from FL to FH speed. After the EL signal turns OFF, the LSI will start counting EZ pulses. After the LSI finishes counting EZ pulses, the axis will stop decelerate and stop.		
 1001: Zero return operation 9 After the process in zero return operation 0 has executed, it returns to zero (operates until COUNTER2 = 0). 		
 1010: Zero return operation 10 - After the process in zero return operation 3 has executed, it returns to zero (operates until COUNTER2 = 0). 		
 1011: Zero return operation 11 After the process in zero return operation 5 has executed, it returns to zero (operates until COUNTER2 = 0). 		
 1100: Zero return operation 12 After the process in zero return operation 8 has executed, it returns to zero (operates until COUNTER2 = 0). 		
Settings after a zero return complete <set (bits="" 20="" 23)="" 4r="" cu1r="" in="" renv3="" to=""> CU1R (bit 20) =1: Reset COUNTER1 (command position) CU2R (bit 21) =1: Reset COUNTER2 (mechanical position) CU3R (bit 22) =1: Reset COUNTER3 (deflection counter) CU4R (bit 23) =1: Reset COUNTER4 (general-purpose)</set>	[RENV3] 23 n n n n	(WRITE) 16
Setting the ERC signal for automatic output <pre>Set EROR (bit 11) in RENV1> 0: Does not output an ERC signal when a zero return is complete. 1: Automatically outputs an ERC signal when a zero return is complete.</pre>	[RENV1] 15 	(WRITE) 8 n

9-5-1-1. Zero return operation 0 (ORM = 0000)

Constant speed operation <Sensor: EL (ELM = 0), ORG>

ORG	OFF	ON	
EI	OFF		
	>	<@	ON
Operation 1			
Operation 2			>Emergency stop
operation 2			Emergency stop
Operation 3			

High speed operation <Sensor: EL (ELM = 0), ORG> Even if the axis stops normally, it may not be at the zero position. However, COUNTER2 (mechanical position) provides a reliable value.



High speed operation <Sensor: EL (ELM = 1), ORG> Even if the axis stops normally, it may not be at the zero position. However, COUNTER2 (mechanical position) provides a reliable value.

ORG				
EL	>			
Operation 1		¥	@	
Operation 2			,	Emergency stop
Operation 3			, >	Emergency stop

High speed operation <Sensor: EL (ELM = 1), SD (SDM = 0, SDLT = 0), ORG>

ORG SD	OFF	ON			
EL					
Operation 1		\searrow	«@		
Operation 2		\rightarrow	<@		
Operation 3					Emergency stop
Operation 4					Emergency stop

Note: Positions marked with "@" reflect the ERC signal output timing when "Automatically output an ERC signal" is selected for the zero stopping position.

9-5-1-2. Zero return operation 1 (ORM=0001)

ORG			
EL			
Operation 1	FA speed		
			Emergency stop
Operation 2			Emergency stop
Operation 3		,	Emergency stop
operation o			

Constant speed operation <Sensor: EL (ELM = 0), ORG>

High speed operation <Sensor: EL, ORG>



9-5-1-3. Zero return operation 2 (ORM = 0010)

```
Constant speed operation <Sensor: EL (ELM = 0), ORG, EZ (EZD = 0001)>
```



Note: Positions marked with "@" reflect ERC signal output timing when "Automatically output an ERC signal" is selected for the zero stopping position.

9-5-1-4. Zero return operation 3 (ORM = 0011)



Constant speed operation <Sensor: EL, ORG, EZ (EZD=0001)>

9-5-1-5. Zero return operation 4 (ORM = 0100)

Constant speed operation <Sensor: EL, ORG, EZ (EZD = 0001)>



Operation 1 Operation 2 Operation 3 Operation 3

Note: Positions marked with "@" reflect the ERC signal output timing when "Automatically output an ERC signal" is selected for the zero stopping position.

9-5-1-6. Zero return operation 5 (ORM = 0101) Constant speed operation <Sensor: EL, ORG, EZ (EZD = 0001)> ORG EZ EL Operation 1 @ Operation 2 Operation 3 High speed operation <Sensor: EL, ORG, EZ (EZD = 0001)> ORG EZ

9-5-1-7. Zero return operation 6 (ORM = 0110) Constant speed operation <Sensor: EL>

@

EL

Operation 1

Operation 2

Operation 3



Emergency stop

Emergency stop



9-5-1-11. Zero return operation 10 (ORM = 1010)

0 1	,	, (1
ORG	 				
EZ					
EL					
Operation 1	(
		@	~		
				>	Emergency stop
Operation 2					Emergency
Operation 3					stop
Operation 3					Emergency stop

High speed operation <Sensor: EL, ORG, EZ (EZD = 0001)>

9-5-1-12. Zero return operation 11 (ORM = 1011)





9-5-1-13. Zero return operation 12 (ORM = 1100)

High speed operation <Sensor: EL, EZ (EZD = 0001)>

EZ	
EL	*
Operation 1	
<u>Note: Posi</u> outp	itions marked with "@" reflect the ERC signal output timing when "Automatically but an ERC signal" is selected for the zero stopping position.

Also, when EROE (bit 10) is 1 in the RENV1 register and ELM (bit 3) is 0, the LSI will output an ERC signal at positions marked with an asterisk (*).

9-5-2. Leaving the zero position operations

After writing a start command, the axis will leave the zero position (when the ORG input turns ON). <u>Make sure to use the "Constant speed start command (50h, 51h)" when leaving the zero position.</u> When you write a start command while the ORG input is OFF, the LSI will stop the movement on the axis as a normal stop, without outputting pulses.

Since the ORG input status is sampled when outputting pulses, if the PCL starts at constant speed while the ORG signal is ON, it will stop operation after outputting one pulse, since the ORG input is turned OFF. (Normal stop)

MOD: 12h Leave the zero position in the positive direction

1Ah Leave the zero position in the negative direction

9-5-3. Zero search operation

This mode is used to add functions to a zero return operation. It consists of the following possibilities. 1) A "Zero return operation" is made in the opposite direction to the one specified.

2) A "Leaving the zero position using positioning operations" is executed in the opposite direction to the one specified.

3) A "Zero return operation" is executed in the specified direction.

Operation 1: If the ORG input is turned ON after starting, movement on the axis will stop normally.

Operation 2: If the ORG input is already turned ON when starting, the axis will leave the zero position using positioning operations, and then begin a "zero return operation."

Operation 3: If movement on the axis is stopped by an EL signal while operating in the specified direction, the axis will execute a "zero return operation (ORM = 0000)" and a "leaving the zero position by positioning" in the opposite direction. Then it will execute a "zero return operation" in the specified direction.

When "leaving the zero position by positioning," the axis will repeat the positioning operation for the number of pulses specified in the RMV (target position) register, until the zero position has been left. Enter a positive number (1 to 134,217,727) in the RMV register.

MOD: 15h Zero search operation in the positive direction

1Dh Zero search operation in the negative direction

9-5-3-1. Zero return operation 0 (ORM=0000)



High speed operation <Sensor: EL, ORG>

Even if the axis stops normally, it may not be at the zero position. However, COUNTER2 (mechanical position) provides a reliable value.



9-6. EL or SL operation mode

The following four modes of EL or SL (soft limit) operation are available.

MOD	Operation mode	Direction of movement
20h	Operate until reaching the +EL or +SL position.	Positive direction
28h	Operate until reaching the -EL or -SL position.	Negative direction
22h	Leave from the -EL or -SL positions.	Positive direction
2Ah	Leave from the +EL or +SL positions.	Negative direction

To specify the \pm EL input signal, set the input logic using the ELL input terminal. Select the operation type (immediate stop / deceleration stop) when the input from that terminal is ON in the RENV1 (Environment setting 1) register. The status of the terminal can be monitored using the SSTSW (sub status).

For details about setting the SL (software limit), see section 11-11-2, "Software limit function."

Select the ±EL signal input logic <ell input="" terminal=""> L: Positive logic input H: Negative logic input</ell>	
Select the stop method to use when the \pm EL signal is turned ON <set< td=""><td>[RENV1] (WRITE)</td></set<>	[RENV1] (WRITE)
	7 0
0: Stop immediately when the ±EL signal turns ON.	
1: Decelerates and stops when the ±EL signal turns ON.	
Reading the ±EL signal <spel (bit="" 12),="" 13)="" in="" smel="" sstsw=""></spel>	[SSTSM] (READ)
SPEL=0: Turn OFF +EL signal SPEL=1: Turn ON +EL signal	15 8
SMEL=0: Turn OFF -EL signal SMEL=1: Turn ON -EL signal	n n
Setting the ±EL input filter <set (bit="" 26)="" fltr="" in="" renv1="" the=""></set>	[RENV1] (WRITE)
1: Apply a filter to the ±EL input.	31 24
After applying a filter, signals shorter than 4 used will be ignored	
Alter applying a litter, signals shorter than 4 psec will be ignored.	n

9-6-1. Feed until reaching an EL or SL position

This mode is used to continue feeding until the EL or SL (soft limit) signal is turned ON and then the operation stops normally.

When a start command is written on the position where the EL or SL signal is turned ON, the LSI will not output pulses and it will stop the axis normally. When a start command is written to the axis while the EL and SL signals are OFF, the axis will stop when the EL or SL signal is turned ON. (Normal stop.)

MOD: 20h Feed until reaching the +EL or +SL position. 28h Feed until reaching the -EL or -SL position.

9-6-2. Leaving an EL or SL position

This mode is used to continue feeding until the EL or SL (software limit) signal is turned OFF. When a start command is written on the position where the EL and SL signals are turned OFF, the LSI will not output pulses and it will stop the axis normally. When starting an operation while the EL input or SL signal is ON, the PCL will stop operation

When starting an operation while the EL input or SL signal is ON, the PCL will stop operation normally when both the EL input and SL signal are OFF.

MOD: 22h Leave from a -EL or -SL position 2Ah Leave from a + EL or +SL position

9-7. EZ count operation mode

This mode is used to count EZ signal of the number (EZD set value +1) written into the RENV3 register. MOD: 24h Feed until the EZ count is complete in positive direction.

2Ch Feed until the EZ count is complete in negative direction.

After a start command is written, the axis stops immediately (or decelerates and stops when feeding at high speed) after the EZ count equals the number stored in the register.

The EZ count can be set from 1 to 16.

Use the constant speed start command (50h, 51h) for this operation. When the high speed start command is used, the axis will start decelerating and stop when the EZ signal turns ON, so that the motion on the axis overruns the EZ position.

Specify logical input for the EZ signal in the RENV2 (environment setting 2) register, and the EZ number to count to in the RENV3 (environment setting 3) register. The terminal status can be monitored by reading the RSTS (extension status) register.

Setting the input logic of the EZ signal <set (bit="" 23)="" ezl="" in="" renv2=""> 0: Falling edge</set>	[RENV2] (WRITE)
1: Rising edge	n
Setting the EZ count number <set (bits="" 3="" 4="" 7)="" ezd0="" in="" renv3="" to=""></set>	[RENV3] (WRITE)
Specify the EZ count number after a zero return complete condition.	7 0
Enter a value (the number to count to minus 1) in EZD 0 to 3. Setting range: 0	
to 15.	
Reading the EZ signal < SEZ (bit 10) in RSTS>	[RSTS] (READ)
0: Turn OFF the EZ signal	15 8
1: Turn ON the EZ signal	n

9-8. Interpolation operations

9-8-1.Interpolation operations

In addition to each independent operation, this LSI can execute the following interpolation operations.

MOD	Operation mode
60h	Continuous linear interpolation 1 for
	2 axes
61h	Linear interpolation 1 for 2 axes
62h	Continuous linear interpolation 2 for
	1 to 2 axes
63h	Linear interpolation 2 for 1 to 2 axes
64h	Circular interpolation (CW)
65h	Circular interpolation (CCW)

MOD	Operation mode
68h	Continuous linear interpolation 1
	synchronized with PA/PB input
69h	Linear interpolation 1 synchronized
	with PA/PB input
6Ah	Continuous linear interpolation 2
	synchronized with PA/PB input.
6Bh	Linear interpolation 2 synchronized
	with PA/PB input
6Ch	CW circular interpolation
	synchronized with PA/PB input
6Dh	CCW circular interpolation
	synchronized with PA/PB input

Continuous linear interpolation is the same as the linear interpolation used to feed multiple axes at specified rates, and to start and stop feeding using commands such as the continuous mode commands.

Interpolation 1 executes an interpolation operation between the two axes in the LSI.

Interpolation 2 is used to control three axes or more using more than one LSI, and to control feeding using linear interpolation.

Independent operation of the un-interpolated axes is also possible.

The interpolation settings and operation status can be monitored by reading the RIPS (interpolation status) register.

The RIPS register is shared by the X and Y axes. Reading from any axis will return the identical information.

Write start and stop commands to both axes by setting SELx and SELy in COMB1.

[Interpolation operations that can be combined with this LSI]

1) Linear interpolation 1 for two axes.

2) Circular interpolation for two axes

3) Linear interpolation 2 for one to two axes.

9-8-2. Interpolation control axis

In Circular interpolation and Linear interpolation 1, specify the speed for one axis only. This axis is referred to as the interpolation control axis. On the PCL6025B, interpolation control is limited to the X axis.

When linear interpolation 2 is selected, each axis will be used to control the interpolation.

[Rela	tionship	between a	an interpolation	operation	and the a	axes used	for inter	rpolation control	

No	Interpolation operation	Interpolation control axis
1)	Linear interpolation 1 of the X and Y axes.	X axis
2)	Circular interpolation of the X and Y axis	X axis

9-8-3. Constant synthesized speed control

This function is used to create a constant synthesized speed for linear interpolation 1 and circular interpolation operations. When linear interpolation 2 is selected, this function cannot be used. To enable this function, set the MIPF (bit 15) in the PRMD (operation mode) register to "1" for the axes that you want to have a constant synthesized speed. When the same interpolation mode is selected, the axes whose MIPF bit is set to "1" will have a longer pulse output interval: multiplied by the square root of two ($\sqrt{2}$) for two axis simultaneous output.

When the synthesized constant speed control bit is turned ON (MIPF = 1), the synthesized speed (while performing interpolation) will be the operation speed (PRFH) or the initial speed (PRFL) of the interpolated axes.

SRUN, SEND, and SERR in MSTSW (main status byte) for the interpolated axis will change using the same pattern.

The RSPD (speed monitor) feature is only available for the interpolation control axes. However, when linear interpolation 2 is used, the value read out will be the main axis speed.

<Precautions for using the composite constant speed control bit (MIPF = 1)>

1) Positioning is only possible at the unit's resolution position for machine operation.

Therefore, even if an interpolation operation is selected, the machine will use the following points to approximate an arc, and the actual feed pattern will be point to point (zigzag feeding). With this feed pattern, the actual feed amount will be longer than the ideal linear line or an ideal arc. The function of the synthesized constant speed control in this LSI is to make constant synthesized speeds for multiple axes in simultaneous operation, which means that the speed through the ideal locus (trajectory) will not be constant.

For example, with linear interpolation in Y (Slave axis) the figure on the right (using the synthesized constant speed feature), the PCL will make a constant synthesized speed in order to feed at a 45° angle by decreasing the speed to $1/\sqrt{2}$.

Therefore, the feeding interval when the feed speed is 1 pps will be 6 + $4\sqrt{2}$ =11.66 seconds.



The length of the ideal line (dotted line) is $\sqrt{(10^2+4^2)} = 10.77$. If the machine can be fed by just following the ideal line, the feed interval will be 10.77 seconds. Please take note of the above when using synthesized constant speed control.

Please take note of the above when using synthesized constant speed control.

2) Acceleration/deceleration operations when the synthesized constant speed control bit is ON (MIPF = 1)

Basically, the operation will have a constant speed when MIPF = 1. (The synthesized speed will vary with the acceleration/deceleration.)

When MIPF = 1 and you select linear interpolation 1 or circular interpolation with acceleration/deceleration, the following limitations apply.

- Make the acceleration rate (PRUP) and deceleration rate (PRDR) for the control axes equal.

- Do not change the speed during S-curve acceleration/deceleration.

Failure to follow these guidelines may cause the PCL to decelerate abnormally.

9-8-4. Continuous linear interpolation 1 (MOD: 60h)

This is the same as linear interpolation 1, and each axis operates at a speed corresponding to the PRMV setting. However, the PCL will continue to output pulses until a stop command is received. This mode only uses the rate from the PRMV setting for all of the interpolated axes. Therefore, if the PRMV setting for the all of the interpolated axes is zero, the PCL will output pulses to all the interpolated axes at the same speed.

9-8-5. Linear interpolation 1 (MOD: 61h)

Linear interpolation 1 is used to allow a single LSI to handle interpolation operations between the X and Y axes.

If only one axis is specified and operation is started, an error (ESDT: Stop due to operation data error) will occur.

After setting the operation speed for the interpolation control axes, specify whether to use or not the synthesized constant speed control in the PRMD registers, or specify an end point position in the PRMV register for all of the interpolated axes.

The direction of operation is determined by the sign of the value in the PRMV register.

Automatically, the axis with the maximum feed amount (maximum absolute value in the PRMV register) will be considered the master axis. The other axis will be the slave axis.

When a start command is written, the LSI will output pulses to the master axis and the slave axis will be supplied a smaller number of pulses than the master axis. Write a start command by setting either the SELx or SELy bits corresponding to the interpolation axes in COMB1 to 1. Writing any of these axes bring the same result.

[Setting example] Use the settings below and write a start command (0351h). The PCL will output pulses with the timing shown in the figure below. Entering values in the blank items will not affect operation

mil flot alloot opplation.				
Setting	X axis	Y axis		
MOD	61h	61h		
MIPF	0 (OFF)	0 (OFF)		
PRMV value	5	10		
Operation speed	1000 pps			
Interpolation control axis	0			
Master axis / slave axis	Slave axis	Master axis		



[Precision of linear interpolation] As shown in the figure on the right, linear interpolation executes an interpolation from the current coordinates to the end coordinates.

The positional precision of a specified line during linear interpolation will be ± 0.5 LSB throughout the interpolation range.



"LSB" refers to the minimum feed unit for the PRMV register setting. It corresponds to the resolution of the mechanical system. (distance between tick marks in the figure on the right.)

9-8-6. Continuous linear interpolation 2 (MOD: 62h)

Same as Linear Interpolation 2: the PCL controls each axis using speeds that correspond to the ratios of the values set in PRIP and PRMV. However, in continuous mode the PCL will continue to output pulses until it receives a stop command.

9-8-7. Linear interpolation 2 (MOD: 63h)

Linear interpolation 2 is used for linear interpolations between 3 or more axes and uses more than one LSI for control.

In this mode, the PCL cannot synchronize the acceleration/deceleration timing between interpolated axes, so this mode cannot be used with acceleration/deceleration.

In order to execute a linear interpolation using multiple LSIs, you must use a simultaneous start signal (#CSTA signal).

For details about the #CSTA signal, see section 11-7, "External start, simultaneous start."

The axis with the maximum amount to be fed is referred to as the master axis during the interpolation and the other axes are slave axes.

Enter the PRMV register setting for the master axis in the PRIP registers of each axis (including the master axis).

In the PRMV registers of the slave axes, enter end point of each axis.

Specify the speed data (PRFL, PRFH, PRUR, PRDR, PRMG, PRDP, PRUS, and PRDS) for the slave axes to be the same as for the master axis.

The feed direction is determined by the sign of the value in the PRMV register.

After writing "01" into MSY (bits 18 and 19) in the PRMD (operation mode) register of the axes, write a start command and set the axes to wait for the #CSTA signal input. By entering a #CSTA signal, all of the axes on all of the LSIs will start at the same time.

The master axis provides pulses constantly. The slave axes provide some of the pulses fed to the master axis, but some are omitted.

[Setting example]

1) Connect the #CSTA signals between LSI-A and LSI-B.

2) Set up the LSIs as shown below. (Set the PRMD to start with an #CSTA input.)

3) Write start commands (LSI-A: 0351h, LSI-B: 0351h).

4) Write a #CSTA signal input command (06h) to the X axis on LSI-A.

After completing steps 1) to 4) above, the LSIs will output pulses using the timing shown in the figure below.



Note: If you start linear interpolation 2 while PRIP = 0, an operation data error (ESDT of REST is "1") will occur.

9-8-8. Circular interpolation

This function provides CW circular interpolation (MOD: 64h) and CCW circular interpolation (MOD: 65h) between the X and Y axes.

If only one axis is specified for circular interpolation and a start command is written, a data setting error will occur.

Circular interpolation takes the current position as the starting point (coordinate 0, 0) regardless of the values in the counters (COUNTER1 to 4).

After specifying the speed for each axis being interpolated, specify whether or not to apply constant synthetic speed control (MIPF in the PRMD register) for each axis, the end points (the PRMV register value), and the center point (the PRIP register value). If the end point is 0 (the starting point), both axes will draw a simple circle.

The synthetic speed used in the circular interpolation will be the speed set for the axes being interpolated (FH/FL) if the constant synthetic speed control is ON (MIPF = 1) for both axes. Write a start command after setting SELx and SELy in COMB1 to 1. Either axis can be used to write a start command.

[Setting example]

As shown in the table below, specify the MOD, MIPF, PRMV, PRIP and operation speed for each axis and write a start command (ex. 0351h) that will be used by both axes. The axes will move as shown on the right.

Step No.	o. A		В		С		D	
Set	Х	Υ	Х	Y	Х	Υ	Х	Y
value	axis	axis	axis	axis	axis	axis	axis	axis
MOD		64h (CW	circu	lar in	terpo	latio	n)
MIPF	1 (turn C		ON constant synthetic spe			peed		
	С	ontro	l)					
PRMV value	0	0	100	100	200	0	100	-100
PRIP value	100	0	10	0	100	0	100	0
			0					
Operation result	Simple circle		90°	arc	180)° arc	270)° arc



This LSI terminates a circular interpolation operation when either of the axes reaches the end point in the last quadrant, and the end point can be specified as the whole number coordinates nearest to the end position. For this reason, even though the circular interpolation operation is complete, the PCL will not be at the end coordinate specified. To move to the coordinates of the specified end point when the circular interpolation operation is complete, set the MPIE bit in the PRMD register to "1" and turn ON the end point draw function.

If the end point of the circular interpolation is set within the shaded areas, the axes will not stop moving (perpetual circular motion).

[Circular interpolation precision]

The circular interpolation function draws a circular from the current position to the end coordinate moving CW or CCW.

The positional deviation from the specified curve is ± 0.5 LSB.

The figure on the right is an example of how to draw a simple circle with a radius of 11 units.

The LSB refers the minimum feeding unit of the PRMV register setting value. It corresponds to the resolution of mechanical system (size of the cells in the figure right.)



[Circular interpolation with acceleration/deceleration]

To use circular interpolation with acceleration/deceleration, you have to enter the number of circular interpolation pulses required (circular interpolation step numbers) in the PRCI register for the control axis.

To calculate the number of pulses required for circular interpolation, break the area covered by the X and Y axes into 8 (0 to 7) sections, using the center coordinate of the circular interpolation as the center point. See the figure below.

The output pulse status of each axis in each area is as follows

Area	X axis output pulse	Y axis output pulse
0	Output according to the interpolation calculation result	Always output
1	Always output	Output according to the interpolation calculation result
2	Always output	Output according to the interpolation calculation result
3	Output according to the interpolation calculation result	Always output
4	Output according to the interpolation calculation result	Always output
5	Always output	Output according to the interpolation calculation result
6	Always output	Output according to the interpolation calculation result
7	Output according to the interpolation calculation result	Always output



The table above shows the PCL output pulses for either of the axes in each area. Therefore, the number of pulses required for circular interpolation (the number of circular interpolation steps) is equal to the number of pulses to move around this side of a square that is surrounded by the circle used for the circular interpolation.

For example, to draw a 90° arc with radius "a," the number of pulses required for circular interpolation will be $(a\sqrt{2}) \times 2$. Enter this value in the PRCI register.

To obtain the number of steps for any start and end points, follow the procedure below.

- First, determine the area that the start point belongs to (area 0 to 7). Then, draw a horizontal (vertical) line to find the contact point with the square inside the circle.
- Next, determine the area that the end point belongs to (area 0 to 7). Then, draw a vertical (horizontal) line to find the contact point with the square inside the circle.
- 3) Find the distance between the two contact points on the square (from 1) and 2) above) and enter this value in the PRCI register.



To continue the end point draw function, set MPIE in the PRMD register to "1." Then enter the value in the PRCI register after adding number of pulses required for the end point draw function.

Note 1: The PRCI register value is used to trigger the start of the deceleration timing. When a smaller value is entered, the PCL will start deceleration sooner and the FL constant time will apply. When a larger value is entered, the PCL will delay the beginning of deceleration and then will have to stop suddenly.

However, the interpolation trajectory is equal to the constant speed circular interpolation.

- Note 2: To specify a ramp down point manually, think of the PRCI setting as a number of output pulses, so that the PRDP calculation formula for the positioning operation can be used. However, this formula cannot be used when the synthesized constant speed operation is ON. In this case, there is no other way to obtain a ramp down point except by changing the RICI value and conducting a test.
- 9-8-9. Interpolation operation synchronized with PA/PB

This function uses the PA/PB input signal (after magnification or division) instead of the internal clock.

Any PA/PB input after the interpolation operation is complete will be ignored.

9-8-10. Operation during interpolation

Acceleration/deceleration operations

Acceleration and deceleration (linear and S-curve) can be used with Linear interpolation 1 and circular interpolation operations. However, set the MSDP and MADJ in the PRMD register the same for all of the interpolated axes.

To control the ramp down point while using linear interpolation1, the PCL executes a comparison of RPLS and RSDC for the longest axis. The RSDC setting for any shorter axes will be invalid. However, if more than one axis has the same length and they are the longest axes, to specify a ramp down point manually you must enter the same value for all of the interpolated axes.

To control the ramp down point while using circular interpolation, the PCL executes a comparison of RCIC and RSDC on the control axis. Therefore, to specify a ramp down point manually, write to RSD on the control axis.

Error stop

If any of the axes stops with an error, all of the axes being interpolated will stop (SERR = 1). By reading the REST (error stop cause) register, you can determine which axis actually stopped with an error.

SD input

When SD input is enabled (MSDE (bit 8) in the PRMD register is set to 1), and if the SD input turns ON either of the axes, both axes will decelerate or decelerate and stop.

- Idling control If any axis is in idling range, none of the axes being interpolated will accelerate.
- Correction function

When phases are changed during circular interpolation, backlash correction and slip correction control cannot be used.

• Continuous interpolation

The PCL can use the pre-register to make a continuous linear interpolation or circular interpolation. However, when the axes being interpolated change during a continuous interpolation, requires special care.

An example of the settings for continuous interpolation using the pre-register is shown in section 11-14-1, "Start triggered by another axis."

10. Speed patterns

10-1. Speed patterns

Speed pattern	Continuous mode	Positioning operation mode
FL constant speed operation	 Write an FL constant speed start command (50h). 	 Write an FL constant speed start command (50h).
FLt	 Stop feeding by writing an immediate stop (49h) or deceleration stop (4Ah) command. 	 Stop feeding when the positioning counter reaches zero, or by writing an immediate stop (49h) or deceleration stop (4Ah) command.
1) 2)		
FH constant speed operation	 Write an FH constant speed start command (51h). 	 Write an FH constant speed start command (51h).
	2) Stop feeding by writing an immediate stop command (49h).	 Stop feeding when the positioning counter reaches zero, or by writing an immediate stop (49h) command.
1) 2)	* When the deceleration stop comm PCL starts deceleration.	and (4Ah) is written to the register, the
High speed operation 1)	1) Write high speed start command	1) Write high speed start command 1
f FH	1 (52h). 2) Start deceleration by writing a deceleration stop command (4Ah).	 (52h). 2) Start deceleration when a ramping-down point is reached or by writing a deceleration stop command
FL	* When the deceleration stop command (49h) is written to the register, the PCL immediately stops	 * When positioning with a high speed start command 1 (52h), <u>the</u> <u>ramping-down point is fixed to the</u> <u>manual setting,</u> regardless of the
1) 2)	* When idling pulses are added by setting IDL in RENV5 to a non-zero value, after outputting idling pulses at FL speed, the PCL will accelerate to FH speed.	setting for MSDP (bit 13) in the PRMD. If the ramping-down point setting (PRDP) is zero, the axis will stop immediately.
High speed operation 2)	 Write high speed command 2 (53h). 	 Write high speed start command 2 (53h).
f FH	 Start deceleration by writing a deceleration stop command (4Ah). 	 Start deceleration when a ramping-down point is reached or by writing a deceleration stop command (4Ah).
FLt	* When the deceleration stop command (49h) is written to the register, the PCL starts deceleration.	* If the ramping-down point is set to manual (MSDP = 1 in the PRMD), and the ramping-down value (PRDP) is zero, the axis will stop immediately.

10-2. Speed pattern settings

Specify the speed pattern using the registers (pre-registers) shown in the table below. If the next register setting is the same as the current value, there is no need to write to the register again.

Pre-register	Description	Bit length setting range	Setting range	register
PRMV	Positioning amount	28	-134,217,728 to 134,217,727 (8000000h) (7FFFFFh)	RMV
PRFL	Initial speed	16	1 to 65,535 (0FFFFh)	RFL
PRFH	Operation speed	16	1 to 65,535 (0FFFFh)	RFH
PRUR	Acceleration rate	16	1 to 65,535 (0FFFFh)	RUR
PRDR	Deceleration rate Note 1	16	0 to 65,535 (0FFFFh)	RDR
PRMG	Speed magnification rate	12	2 to 4,095 (0FFFh)	RMG
PRDP	Ramping-down point	24	0 to 16,777,215 (0FFFFFFh)	RDP
PRUS	S-curve acceleration range	15	0 to 32,767 (7FFFh)	RUS
PRDS	S-curve deceleration range	15	0 to 32,767 (7FFFh)	RDS

Note 1: If PRDR is set to zero, the deceleration rate will be the value set in the PRUR.

[Relative position of each register setting for acceleration and deceleration factors]



operation: Set in PRDP or set automati-

PRFL: FL speed setting register (16-bit)

Specify the speed for FL constant speed operations and the start speed for high speed operations (acceleration/deceleration operations) in the range of 1 to 65,535 (0FFFFh). The speed will be calculated from the value in PRMG.

PRFH: FH speed setting register (16-bit)

Specify the speed for FH constant speed operations and the start speed for high speed operations (acceleration/deceleration operations) in the range of 1 to 65,535 (0FFFFh). When used for high speed operations (acceleration/deceleration operations), specify a value larger than PRFL. The speed will be calculated from the value placed in PRMG.

Reference clock frequency [Hz] FH speed [pps] = PRFH x

• PRUR: Acceleration rate setting register (16-bit)

Specify the acceleration characteristic for high speed operations (acceleration/deceleration operations), in the range of 1 to 65,535 (0FFFFh) Relationship between the value entered and the acceleration time will be as follows:

1) Linear acceleration (MSMD = 0 in the PRMD register) Acceleration time [s] = $\frac{(PRFH - PRFL) \times (PRUR + 1) \times 4}{Reference clock frequency [Hz]}$

2) S-curve acceleration without a linear range (MSMD=1 in the PRMD register and PRUS register =0)

Acceleration time [s] = $\frac{(PRFH - PRFL) \times (PRUR + 1) \times 8}{Reference clock frequency [Hz]}$

- 3) S-curve acceleration with a linear range (MSMD=1 in the PRMD register and PRUS register >0) Acceleration time [s] = $\frac{(PRFH - PRFL + 2 \times PRUS) \times (PRUR + 1) \times 4}{\text{Reference clock frequency [Hz]}}$
- PRDR: Deceleration rate setting register (16-bit)

Normally, specify the deceleration characteristics for high speed operations (acceleration/deceleration operations) in the range of 1 to 65,535 (0FFFFh). Even if the ramping-down point is set to automatic (MSDP = 0 in the PRMD register), the value placed in the PRDR register will be used as the deceleration rate. <u>However, when PRDR = 0, the deceleration rate will be the value placed in the PRUR.</u> When the ramping-down point is set to automatic, there are the following restrictions.

- While in the Linear interpolation 1 or circular interpolation, and when the synthetic speed constant control function is applied (MIPF = 1 in the PRMD), arrange that (deceleration time) = (acceleration).

- For other operations, arrange (deceleration time) \leq (acceleration time x 2). If setting otherwise, <u>the axis may not decrease the speed to the specified FL speed when stopping</u>. In this case, use a manual ramping-down point (MSDP = 1 in the PRMD register).

< When (deceleration time) ≤ (acceleration time x 2) using an automatic ramping-down point >



< When (deceleration time) > (acceleration time x 2) using an automatic ramping-down point>



The relationship between the value entered and the deceleration time is as follows.

- 1) Linear deceleration (MSMD = 0 in the PRMD register) Deceleration time [s] = $\frac{(PRFH - PRFL) \times (PRDR + 1) \times 4}{Reference clock frequency [Hz]}$
- 2) S-curve deceleration without a linear range (MSMD=1 in the PRMD register and PRDS register = 0)
 (PRFH PRFL) x (PRDR + 1) x 8

Deceleration time [s] = $\frac{(PRFH - PRFL) \times (PRDR + 1) \times 8}{Reference clock frequency [Hz]}$

- 3) S-curve deceleration with a linear range (MSMD=1 in the PRMD register and PRDS register >0) Deceleration time [s] = $\frac{(PRFH - PRFL + 2 x PRDS) x (PRDR + 1) x 4}{Reference clock frequency [Hz]}$
- PRMG: Magnification rate register (12-bit)

Specify the relationship between the PRFL and PRFH settings and the speed, in the range of 2 to 4,095 (0FFFh). As the magnification rate is increased, the speed setting units will tend to be approximations. Normally set the magnification rate as low as possible.

The relationship between the value entered and the magnification rate is as follows.

Magnification rate =
$$\frac{\text{Reference clock frequency [Hz]}}{(\text{PRMG + 1}) \times 65536}$$

[Magnification rate setting example, when the reference clock =19.6608 MHz] (Output speed unit: pps)

Setting	Magnification rate	Output speed range	Setting	Magnification rate	Output speed range
2999 (0BB7h)	0.1	0.1 to 6,553.5	59 (3Bh)	5	5 to 327,675
1499 (5DBh)	0.2	0.2 to 13,107.0	29 (1Dh)	10	10 to 655,350
599 (257h)	0.5	0.5 to 32,767.5	14 (0Eh)	20	20 to 1,310,700
299 (12Bh)	1	1 to 65,535	5 (5h)	50	50 to 3,276,750
149 (95h)	2	2 to 131,070	2 (2h)	100	100 to 6,553,500

PRDP: Ramping-down point register (24-bits)

Specify the value used to determine the deceleration start point for positioning operations that include acceleration and deceleration.

The meaning of the value specified in the PRDP changes with the "ramping-down point setting method", (MSDP) in the PRMD register.

<When set to manual (MSDP=1 in the PRMD register)>

The number of pulses at which to start deceleration, set in the range of 0 to16,777,215 (0FFFFFh). The optimum value for the ramping-down point can be calculated as shown in the equation below.

1) Linear deceleration (MSMD=0 of the PRMD register)

Optimum value [Number of pulses] = $\frac{(PRFH^2 - PRFL^2) \times (PRDR + 1)}{(PRMG + 1) \times 32768}$

However, the optimum value for a triangle start, without changing the value in the PRFH register while turning OFF the FH correction function (MADJ = 1 in the PRMD register) will be calculated as shown the equation below.

(When using idling control, modify the value for PRMV in the equation below by deducting the number of idling pulses from the value placed in the PRMV register. The number of idling pulses will be "1 to 6" when IDL = 2 to 7 in RENV5.)

Optimum value [Number of pulses] = $\frac{PRMV x (PRDR + 1)}{PRUR + PRDR + 2}$

2) S-curve deceleration without a linear range (MSMD=1 in the PRMD register and the PRDS register =0)

Optimum value [Number of pulses] = $\frac{(PRFH^2 - PRFL^2) \times (PRDR + 1) \times 2}{(PRMG + 1) \times 32768}$

3) S-curve deceleration with a linear range (MSMD=1 in the PRMD register and the PRDS register >0)

Optimum value [Number of pulses] = $\frac{(PRFH + PRFL) \times (PRFH - PRFL + 2 \times PRDS) \times (PRDR + 1)}{(PRMG + 1) \times 32768}$

Start deceleration at the point when the (positioning counter value) \leq (PRDP set value).

<When set to automatic (MSDP = 0 in the PRMD register)>

This is an offset value for the automatically set ramping-down point. Set in the range of -8,388,608 (800000h) to 8,388,607 (7FFFFFh).

When the offset value is a positive number, the axis will start deceleration at an earlier stage and will feed at the FL speed after decelerating. When a negative number is entered, the deceleration start timing will be delayed. If the offset is not required, set to zero.

When the value for the ramping-down point is smaller than the optimum value, the speed when stopping will be faster than the FL speed. On the other hand, if it is larger than the optimum value, the axis will feed at FL constant speed after decelerating.

PRUS: S-curve acceleration range register (15-bit)

Specify the S-curve acceleration range for S-curve acceleration/deceleration operations in the range of 1 to 32,767 (7FFFh).

The S-curve acceleration range S_{SU} will be calculated from the value placed in PRMG.

 $S_{SU}[pps] = PRUS x$ <u>Reference clock frequency [Hz]</u> (PRMG + 1) x 65536

In other words, speeds between the FL speed and (FL speed + S_{SU}), and between (FH speed - S_{SU}) and the FH speed, will be S-curve acceleration operations. Intermediate speeds will use linear acceleration.

However, if zero is specified, "(PRFH - PRFL)/2" will be used for internal calculations, and the operation will be an S-curve acceleration without a linear component.

PRDS: S-curve deceleration range setting register (15-bit)

Specify the S-curve deceleration range for S-curve acceleration/deceleration operations in the range of 1 to 32,767 (7FFFh).

The S-curve acceleration range S_{SD} will be calculated from the value placed in PRMG.

 $S_{SD}[pps] = PRDS \times \frac{\text{Reference clock frequency [Hz]}}{(PRMG + 1) \times 65536}$

In other words, speeds between the FH speed and (FH speed - S_{SD}), and between (FL speed + S_{SD}) and the FL speed, will be S-curve deceleration operations. Intermediate speeds will use linear deceleration.

However, if zero is specified, "(PRFH - PRFL)/2" will be used for internal calculations, and the operation will be an S-curve deceleration without a linear component.

10-3. Manual FH correction

When the FH correction function is turned ON (MADJ = 0 in the PRMD register), and when the feed amount is too small for a normal acceleration and deceleration operation, the LSI will automatically lower the FH speed to eliminate triangle driving.

However, if values in the PRUR and PRDR registers are set so that <u>the (deceleration time) ></u> (acceleration time x 2), do not use the FH correction function.

In order to eliminate triangle driving without using the FH correction function (MADJ = 1 in the PRMD register), lower the FH speed before starting the acceleration/deceleration operation. When using idling control, enter a value for PRMV in the equation below after deducting the number of idling pulses. The number of idling pulses will be 1 to 6 when IDL = 2 to 7 in RENV5.



Automatic correction of the maximum speed for changing the feed amount.

- < To execute FH correction manually>
- 1) Linear acceleration/deceleration speed (MSMD=0 in the PRMD register)

When

 $PRMV \leq \frac{(PRFH^2 - PRFL^2) \times (PRUR + PRDR + 2)}{(PRMG + 1) \times 32768}$

 $\mathsf{PRFH} \leq \sqrt{\frac{(\mathsf{PRMG} + 1) \times 32768 \times \mathsf{PRMV}}{\mathsf{PRUR} + \mathsf{PRDR} + 2}} + \mathsf{PRFL}^2$

2) S-curve acceleration without linear acceleration (MSMD=1 in the PRMD and the PRUS registers = 0, PRDS register = 0)

When

 $\mathsf{PRMV} \leq \frac{(\mathsf{PRFH}^2 - \mathsf{PRFL}^2) \times (\mathsf{PRUR} + \mathsf{PRDR} + 2) \times 2}{(\mathsf{PRMG} + 1) \times 32768}$

$$\mathsf{PRFH} \leq \sqrt{\frac{(\mathsf{PRMG} + 1) \times 32768 \times \mathsf{PRMV}}{(\mathsf{PRUR} + \mathsf{PRDR} + 2) \times 2}} + \mathsf{PRFL}^2$$

3) S-curve acceleration/deceleration with linear acceleration/deceleration (MSMD = 1 in the PRMD register and the PRUS register > 0, PRDS register > 0)
 (3)-1. When PRUS = PRDS

(i) Set up a small linear acceleration range When

$$PRMV \leq \frac{(PRFH + PRFL) \times (PRFH - PRFL + 2 \times PRUS) \times (PRUR + PRDR + 2)}{(PRMG + 1) \times 32768}$$
 and

$$\mathsf{PRFH} \leq -\mathsf{PRSU} + \sqrt{(\mathsf{PRUS} - \mathsf{PRFL})^2 + \frac{(\mathsf{PRMG} + 1) \times 32768 \times \mathsf{PRMV}}{(\mathsf{PRUR} + \mathsf{PRDR} + 2)}}$$

(ii) Eliminate the linear acceleration/deceleration range

When

 $\mathsf{PRMV} \leq \frac{(\mathsf{PRUS} + \mathsf{PRFL}) \times \mathsf{PRUS} \times (\mathsf{PRUR} + \mathsf{PRDR} + 2) \times 8}{(\mathsf{PRMG} + 1) \times 32768}$

Change to S-curve acceleration/deceleration without a linear acceleration/deceleration range (PRUS = 0, PRDS = 0),

$$\mathsf{PRFH} \leq \sqrt{\frac{(\mathsf{PRMG}+1) \times 32768 \times \mathsf{PRMV}}{(\mathsf{PRUR}+\mathsf{PRDR}+2) \times 2}} + \mathsf{PRFL}^2$$

PRMV: Positioning amount	PRFL: Initial speed	PRFH: Operation speed
PRUR: Acceleration rate	PRDR: Deceleration rate	PRMG: Speed magnification rate
PRUS: S-curve acceleration range	PRDS: S-curve deceleration ra	nge

(3)-2. When PRUS < PRDS

(i) Set up a small linear acceleration/deceleration range When

 $\mathsf{PRMV} \leq \frac{(\mathsf{PRFH} + \mathsf{PRFL}) \times \{(\mathsf{PRFH} - \mathsf{PRFL}) \times (\mathsf{PRUR} + \mathsf{PRDR} + 2) + 2 \times \mathsf{PRUS} \times (\mathsf{PRUR} + 1) + 2 \times \mathsf{PRDS} \times (\mathsf{PRDR} + 1)\}}{(\mathsf{PRMG} + 1) \times 32768}$

and

PRMV > (PRDS+PRFL) x {PRDS x (PRUR + 2 x PRDR + 3) + PRUS x (PRUR + 1)} x 4 (PRMG + 1) x 32768

 $\mathsf{PRFH} \leq \frac{-\mathsf{A} + \sqrt{\mathsf{A}^2 + \mathsf{B}}}{\mathsf{PRUR} + \mathsf{PRDR} + 2}$

However, A = PRUS x (PRUR + 1) + PRDS x (PRDR + 1) B= {(PRMG + 1) x $32768 \times PRMV - 2 \times A \times PRFL + (PRUR + PRDR + 2) \times PRFL^{2} \times (PRUR + PRDR + 2)$

(ii) Eliminate the linear acceleration/deceleration range and set up a small linear acceleration section. When

 $\mathsf{PRMV} \leq \frac{(\mathsf{PRDS} + \mathsf{PRFL}) \times \{\mathsf{PRDS} \times (\mathsf{PRUR} + 2 \times \mathsf{PRDR} + 3) + \mathsf{PRUS} \times (\mathsf{PRUR} + 1)\} \times 4}{(\mathsf{PRMG} + 1) \times 32768}$ and

PRMV > (PRUS + PRFL) x PRUS x (PRUR + PRDR + 2) x 8 (PRMG + 1) x 32768

Change to S-curve acceleration/deceleration without any linear acceleration/deceleration (PRUS>0, PRDS=0)

$$\mathsf{PRFH} \leq \frac{-\mathsf{A} + \sqrt{\mathsf{A}^2 + \mathsf{B}}}{\mathsf{PRUR} + 2 \, \mathsf{x} \, \mathsf{PRDR} + 3}$$

However, A = PRUS x (PRUR + 1) B= {(PRMG + 1) x 32768 x PRMV - 2 x A x PRFL + (PRUR + 2 x PRDR + 3) x PRFL²} x (PRUR + 2 x PRDR + 3)

(iii) Eliminate the linear acceleration/deceleration range

When

 $\mathsf{PRMV} \leq \frac{(\mathsf{PRUS} + \mathsf{PRFL}) \times \mathsf{PRUS} \times (\mathsf{PRUR} + \mathsf{PRDR} + 2) \times 8}{(\mathsf{PRMG} + 1) \times 32768}$

Change to S-curve acceleration/deceleration without any linear acceleration/deceleration (PRUS=0, PRDS=0),

 $\mathsf{PRFH} \leq \sqrt{\frac{(\mathsf{PRMG} + 1) \times 32768 \times \mathsf{PRMV}}{(\mathsf{PRUR} + \mathsf{PRDR} + 2) \times 2}} + \mathsf{PRFL}^2$

PRMV: Positioning amount	PRFL: Initial speed	PRFH: Operation speed
PRUR: Acceleration rate	PRDR: Deceleration rate	PRMG: Speed magnification rate
PRUS: S-curve acceleration range	PRDS: S-curve deceleration rai	nge

(i) Set up a small linear acceleration/deceleration range When

 $\mathsf{PRMV} \leq \frac{(\mathsf{PRFH} + \mathsf{PRFL}) \times \{(\mathsf{PRFH} - \mathsf{PRFL}) \times (\mathsf{PRUR} + \mathsf{PRDR} + 2) + 2 \times \mathsf{PRUS} \times (\mathsf{PRUR} + 1) + 2 \times \mathsf{PRDS} \times (\mathsf{PRDR} + 1)\}}{(\mathsf{PRMG} + 1) \times 32768}$

and

 $\mathsf{PRFH} \le \frac{-\mathsf{A} + \sqrt{\mathsf{A}^2 + \mathsf{B}}}{\mathsf{PRUR} + \mathsf{PRDR} + 2}$

However, A = PRUS x (PRUR + 1) + PRDS x (PRDR + 1) B= { (PRMG + 1) x $32768 x PRMV - 2 x A x PRFL + (PRUR + PRDR + 2) x PRFL² } x (PRUR + PRDR + 2)$

(ii) Eliminate the linear acceleration section and set up a small linear deceleration range. When

$$\mathsf{PRMV} \leq \frac{(\mathsf{PRUS} + \mathsf{PRFL}) \times \{ \mathsf{PRUS} \times (2 \times \mathsf{PRUR} + \mathsf{PRDR} + 3) + \mathsf{PRDS} \times (\mathsf{PRDR} + 1) \} \times 4}{(\mathsf{PRMG} + 1) \times 32768} \text{ and }$$

 $PRMV > \frac{(PRDS + PRFL) \times PRDS \times (PRUR + PRDR + 2) \times 8}{(PRMG + 1) \times 32768}$

Change to S-curve acceleration/deceleration without any linear acceleration (PRUS = 0, PRDS > 0)

$$\mathsf{PRFH} \leq \frac{-\mathsf{A} + \sqrt{\mathsf{A}^2 + \mathsf{B}}}{2 \, \mathsf{x} \, \mathsf{PRUR} + \mathsf{PRDR} + 3}$$

However, A = PRDS x (PRDR + 1) B= {(PRMG + 1) x 32768 x PRMV - 2 x A x PRFL + (2 x PRUR + PRDR + 3) x PRFL²} x (2 x PRUR + PRDR + 3)

(iii) Eliminate the linear acceleration/deceleration range

When

$$\mathsf{PRMV} \leq \frac{(\mathsf{PRDS} + \mathsf{PRFL}) \times \mathsf{PRDS} \times (\mathsf{PRUR} + \mathsf{PRDR} + 2) \times 8}{(\mathsf{PRMG} + 1) \times 32768}$$

Change to S-curve acceleration/deceleration without any linear acceleration/deceleration (PRUS = 0, PRDS = 0),

$$\mathsf{PRFH} \leq \sqrt{\frac{(\mathsf{PRMG}+1) \times 32768 \times \mathsf{PRMV}}{(\mathsf{PRUR}+\mathsf{PRDR}+2) \times 2}} + \mathsf{PRFL}^2$$

PRMV: Positioning amount	PRFL: Initial speed	PRFH: Operation speed
PRUR: Acceleration rate	PRDR: Deceleration rate	PRMG: Speed magnification rate
PRUS: S-curve acceleration range	PRDS: S-curve deceleration ra	nge

10-4. Example of setting up an acceleration/deceleration speed pattern

Ex. Reference clock = 19.6608 MHz When the start speed =10 pps, the operation speed =100 kpps, and the accel/decel time = 300 msec,

- 1) Select the 2x mode for multiplier rate in order to get 100 kpps output PRMG = 149 (95h)
- 2) Since the 2x mode is selected to get an operation speed 100 kpps, PRFH = 50000 (C350h)
- 3) In order to set a start speed of 10 pps, the rate magnification is set to the 2x mode. PRFL = 5 (0005h)
- 4) In order to make the acceleration/deceleration time 300 msec, set PRUR = 28,494, from the equation for the acceleration time and the PRUR value.

Acceleration time [s] = $\frac{(PRFH - PRFL) \times (PRUR + 1) \times 4}{Reference clock frequency [Hz]}$

$$0.3 = \frac{(50000 - 5) \times (PRUR + 1) \times 4}{19.6608 \times 10^6}$$

PRUR = 28.494

However, since only integers can be entered for PRUR, use 28 or 29. The actual acceleration/deceleration time will be 295 msec if PRUR = 28, or 305 msec if PRUR = 29.

An example of the speed pattern when PRUR = 29



10-5. Changing speed patterns while in operation

By changing the RFH, RUR, RDR, RUS, or RDS registers during operation, the speed and acceleration can be changed on the fly. However, if the ramping-down point was set to automatic (MSDP = 0 in the PRMD register) for the positioning mode, do not change the values for RFL, RUR, RDR, RUS, or RDS. The automatic ramping-down point function will not work correctly.

An example of changing the speed pattern by changing the speed, during a linear acceleration/deceleration operation



- 1) Use a small RFH while accelerating or decelerating the axis until it reaches the correct speed.
- 2), 3) Change RFH after the acceleration/deceleration is complete. The axis will continue accelerating or decelerating until it reaches the new speed.

An example of changing the speed pattern by changing the speed during S-curve acceleration/deceleration operation



- 1) Use a small RFH and if ((change speed) < (speed before change)) and the axis will accelerate/decelerate using an S-curve until it reaches the correct speed.
- 5) Use a small RFH and if ((change speed) ≥ (speed before change)) and the axis will accelerate/decelerate without changing the S-curve's characteristic until it reaches the correct speed.
- 4) Use a large RFH while accelerating and the axis will accelerate to the original speed entered without changing the S-curve's characteristic. Then it will accelerate again until it reaches the newly set speed.
- 2), 3) If RFH is changed after the acceleration/deceleration is complete, the axis will accelerate/decelerate using an S-curve until it reaches the correct speed.

11. Description of the Functions

11-1. Reset

After turning ON the power, make sure to reset the LSI before beginning to use it. To reset the LSI, hold the #RST terminal LOW while supplying at least 8 cycles of a reference clock signal.

After a reset, the various portions of the LSI will be configured as follows.

ltem (n = x, y)	Reset status (initial status)
Internal registers, pre-register	0
Control command buffer	0
Axis assignment buffer	0
Input/output buffer	0
#INT terminal	HIGH
#WRQ terminal	HIGH
#IFB terminal	HIGH
D0 to D7 terminals	High Z (impedance)
D8 to D15 terminals	High Z (impedance)
P0n to P7n terminals	Input terminal
#CSTA terminal	HIGH
#CSTP terminal	HIGH
OUTn terminal	HIGH
DIRn terminal	HIGH
ERCn terminal	HIGH
#BSYn terminal	HIGH

11-2. Position override

This LSI can override (change) the target position freely during operation. There are two methods for overriding the target position.

11-2-1. Target position override 1

By rewriting the target position data (RMV register value), the target position can be changed. The starting position is used as a reference to change target position.

- If the new target position is further away from the original target position during acceleration or constant speed operation, the axis will maintain the operation using the same speed pattern and it will complete the positioning operation at the position specified in the new data (new RMV value).
- 2) If the new target position is further away from the original target position during deceleration, the axis will accelerate from the current position to FH speed and complete the positioning operation at the position specified in the new data (new RMV value).

Assume that the current speed is Fu, and when RFL = Fu, a curve of next acceleration will be equal to a normal acceleration curve.

3) If the axis has already passed over the new target position, or the target position is changed to a position that is closer than the original position during deceleration, movement on the axis will decelerate and stop. Then, the movement will reverse and complete the positioning operation at the position specified in the new data (new RMV value).



The axis accelerates/decelerates only when starting in high speed. The target position data (RMV register value) can be rewritten any number of times until the positioning operation is complete.

Note1: If the ramping-down point is set to automatic and the (deceleration time) > (acceleration time $\underline{x \ 2}$), it may be the case that the axis cannot reduce the speed to the FL level, as shown below. In this case, if the target position is set closer than original position and the axis is decelerating, the axis will decelerate along the deceleration curve to the new override position, and then slow to the FL speed and finally stop. Then it will start moving to the new position. Therefore, the axis will overrun the original target position during deceleration (shaded area).



To avoid creating an overrun condition, make sure that <u>the deceleration time is less than two</u> <u>times the acceleration time</u>, or if <u>the deceleration time is more than double the acceleration</u> <u>time</u>, make the ramping-down point a manual setting.

Note 2: The position override is only valid while feeding.

If the LSI starts decelerating by changing the target to a closer position, and if you perform a "position override" to a position further away during this deceleration, the LSI will not re-accelerate. It will feed to the more distant target after decelerating to FL speed. Also, if you overshoot the target position to lower than the initial RMV setting value during deceleration using the automatic ramp down point setting, the LSI will not accelerate using the target position override.

If you change the target position with the "position override" function while decelerating with the auto ramp down function, the LSI will accelerate again.

Note 3: The position override is only valid while feeding.

If you perform a "position override" operation just before stopping, the PCL may not accept the position override command. To see if the position override command was accepted, check the SEOR bit in the main status after issuing the override command. If the PCL has ignored the override command, the SEOR will be 1.

Please note, if an override command is written into the RMV register (90h) while the axis is stopping, the PCL changes SEOR to 1. Therefore, if you write an override command before the axis has started moving, the SEOR will also be changed to 1.

If the PCL ignores the override, the SEOR will become 1 when the axis stops. And, after the main ststus is read, SEOR will go back to 0 within 3 reference clock cycles.

Note 4: A Position Override 1 cannot be executed while performing an interpolation operation.

11-2-2. Target position override 2 (PCS signal)

By making MPCS in the PRMD (operation mode) register "1," the PCL will perform positioning operations for the amount specified in the PRMV register, based on the timing of this command after the operation start (after it starts outputting instruction pulses) or on the "ON" timing of the PCS input signal.

A PCS input signal can change the input logic. The PCS terminal status can be monitored using the RSTS register (extension status).

Setting pulse control using the PCS input <set (bit="" 14)="" in="" mpcs="" prmd=""></set>	[PRMD] (WRITE)
1: Positioning for the number of pulses stored in the PRMV, starting from the	15 8
time at which the PCS input signal is turned ON.	- n
Setting the PCS input logic <set (bit="" 24)="" in="" pcsl="" renv1=""></set>	[RENV1] (WRITE)
0: Negative logic	31 24
1: Positive logic	n
Reading the PCS signal < SPCS (bit 8) in MRSTS>	[RSTS] (READ)
0: Turn OFF PCS	15 8
1: Turn ON PCS	n
PCS substitution input <staon: command="" control=""></staon:>	[Control command]
Perform processes that are identical to those performed by supplying a PCS signal.	28h
-	

Note: A Position Override 2 cannot be executed while performing an interpolation operation.

11-3. Output pulse control

11-3-1. Output pulse mode

There are four types of common command pulse output modes, and two types of 2-pulse modes and two types of 90° phase difference modes.

Common pulse mode:	Outputs operation pulses from the OUT terminal and outputs the direction
	signal from the DIR terminal.
2-pulse mode:	Outputs positive direction operation pulses from the OUT terminal, and
	outputs negative direction operation pulses from the DIR terminal.

The output mode for command pulses is set in PMD (bits 0 to 2) in RENV1 (environment setting 1). If motor drivers using the common pulse mode need a lag time (since the direction signal changes, until receiving a command pulse), use a direction change timer.

When DTMF (bit 28) in the RENV1 (environment setting 1) is set to 0, the operation can be delayed for one direction change timer unit (0.2 msec), after changing the direction identification signal.

o 2) in RENV1> [RENV ²	1] (WRITE)
ding in the 7	0
direction	n n n
DIR output	
Low	
Low	
High	
High	
I MF (bit 28) in [RENV	1] (WRITE)
31	24
	- n - - - -
	to 2) in RENV1> [RENV ² direction 7 DIR output 7 Low High High J <td< td=""></td<>

11-3-2. Control the output pulse width and operation complete timing

In order to increase the stopping speed, this LSI controls the output pulse width. When the output pulse speed is slower than 1/8192 of reference clock (approx. 2.4 Kpps when CLK = 19.6608 MHz), the pulse width is constant and is 4096 cycles of the reference clock (approx. 200 μ sec when CLK = 19.6608 MHz). For faster pulse speeds than this, the duty cycle is kept constant (approx. 50%). By setting PDTC (bit 13) in the RENV1 register (environment setting 1), the output pulse width can be set to make a constant duty cycle (50%).

Also, when setting METM (operation completion timing setting) in the PRMD register (operation mode), the operation complete timing can be changed.

1) When METM = 0 (the point at which the output frequency cycle is complete) in the PRMD register



2) When METM = 1 (when the output pulse is OFF) in the PRMD register



When set to "complete when the output pulse is OFF," the time interval "Min" from the last pulse until the next starting pulse output will be $T_{MIN} = 15 \times T_{CLK}$. (T_{CLK} : Reference clock cycle)

Setting the operation complete timing <set (bit="" 12)="" in="" metm="" prmd=""> 0: At the end of a cycle of a particular output frequency 1: Complete when the output pulse turns OFF.</set>	[PRMD] 15 n	(WRITE) 8
Setting the output pulse width <set (bit="" 31)="" in="" pdtc="" renv1=""></set>	[RENV1]	(WRITE)
0: Automatically change between a constant output pulse and a constant	31	24
duty cycle (approx. 50%) in accord with variations in speed.	n	
1: Keep the output pulse width at a constant duty cycle (approx. 50%).		

11-4. Idling control

When starting an acceleration or a deceleration operation, it can be started after the output of a few pulses at FL speed (idling output). Set the number of pulses for idling in IDL of the RENV5 register (environment setting 5).

If you will not be using this function, enter a value "n" of 0 or 1. The LSI will start the acceleration at the same time it begins outputting pulses. Therefore, the start speed obtained from an initial 2-pulse cycle will be faster than the FL speed.

To use this function, enter a value "n" of 2 to 7. The LSI will start the acceleration by beginning its output on the "n" th pulse. Therefore, the start speed will be the FL speed and the FL speed can be set to self start speed at near the upper limit.

If this function is used with the positioning mode, the total feed amount will not change.

[Setting idling pulses and the acceleration start timing]



Note: While setting the number of idling pulses, when you write a High-Speed Start 1 command (52h or 56h), the PCL will accelerate to FH speed after outputting the specified number of idling pulses at FL speed. Then the operation will be the same as the High-Speed Start 2 command.

11-5. Mechanical external input control

11-5-1. +EL, -EL signal

When an end limit signal (a +EL signal when feeding in the + direction) in the feed direction turns ON while operating, the axis will stop immediately or decelerate and stop. After stopping, even if the EL signal is turned OFF, the axis will remain stopped. For safety, keep the EL signal ON until the axis reaches the end of the stroke.

If the EL signal is ON when writing a start command, the axis cannot start moving in the direction of the particular EL signal that is ON.

By setting ELM in the RENV1 (environment setting 1) register, the stopping pattern for use when the EL signal is turned ON can be set to immediate stop or deceleration stop (high speed start only). The minimum pulse width of the EL signal is 80 reference clock cycles (4 μ sec) when the input filter is ON. When the input filter is turned OFF, the minimum pulse width is two reference clock cycles (0.1 μ sec).

The EL signal can be monitored by reading SSTSW (sub status).

By reading the REST register, you can check for an error interrupt caused by the EL signal turning ON.

When in the timer mode, this signal is ignored. Even in this case, the EL signal can be monitored by reading SSTSW (sub status).

The input logic of the EL signal can be set for each axis using the ELL input terminal.

Set the input logic of the ±EL signal <ell input="" terminal=""></ell>	
L: Positive logic input	
H: Negative logic input	
Stop method to when the ±EL signal turns ON <set (bit="" 3)="" elm="" in="" renv1=""></set>	[RENV1] (WRITE)
0: Immediate stop by turning ON the ±EL signal	7 0
1: Deceleration stop by turning ON the ±EL signal	n
Reading the ±EL signal <spel (bit="" 12),="" 13)="" in="" smel="" sstsw=""></spel>	[SSTSW] (READ)
SPEL = 0:Turn OFF the +EL signal SPEL = 1: Turn ON the +EL signal	15 8
SMEL = 0:Turn OFF the -EL signal SMEL = 1: Turn ON the -EL signal	n n
Reading the stop cause when the \pm EL signal turns on <espl (bit="" (bit<="" 5),="" esml="" td=""><td>[REST] (READ)</td></espl>	[REST] (READ)
6) in REST>	7 0
ESPL = 1: Stop by turning ON the +EL signal	
ESML = 1: Stop by turning ON the -EL signal	
Setting the ±EL input filter <set (bit="" 26)="" fltr="" in="" renv1=""></set>	[RENV1] (WRITE)
1: Apply a filter to the ±EL input	31 24
Apply a filter and any signals shorter than 4 µsec pulse width are ignored.	n

Note 1: Operation after turning ON the EL signal may be different for the zero return operation (9-5-1), the zero search operation (9-5-3), and the EL or SL operation mode (9-6). See the description of each operation mode.

11-5-2. SD signal

If the SD signal input is disabled by setting MSDE in the PRMD register (operation mode), the SD signal will be ignored.

If the SD signal is enabled and the SD signal is turned ON while in operation, the axis will: 1) decelerate, 2) latch and decelerate, 3) decelerate stop, or 4) latch and deceleration stop, according to the setting of SDM and SDLT in the RENV1 register (environment setting 1).

- 1) Deceleration < SDM (bit 4) = 0, SDLT (bit 5) = 0 in RENV1 register>
 - While feeding at constant speed, the SD signal is ignored. While in high speed operation the axis decelerates to the FL speed when the SD signal is turned ON. After decelerating, or while decelerating, if the SD signal turns OFF, the axis will accelerate to the FH speed.
 - If the SD signal is turned ON when the high speed command is written, the axis will operate at FL speed. When the SD signal is turned OFF, the axis will accelerate to FH speed.

[FL constant speed operation] [FH constant speed operation] [High speed operation]



2) Latch and decelerate <SDM (bit 4) = 0, SDLT (bit 5) = 1 in RENV1 register>

- While feeding at constant speed, the SD signal is ignored. While in high speed operation, decelerate to FL speed by turning the SD signal ON. Even if the SD signal is turned OFF after decelerating or while decelerating, the axis will continue moving at FL speed and will not accelerate to FH speed.
- If the SD signal is turned ON while writing a high speed command, the axis will feed at FL speed. Even if the SD signal is turned OFF, the axis will not accelerate to FH speed.

[FL constant speed operation] [FH constant speed operation] [High speed operation]



3) Deceleration stop <SDM (bit 4) = 1, SDLT (bit 5) = 0 in RENV1 register>

- If the SD signal is turned ON while in constant speed operation, the axis will stop. While in high speed operation, the axis will decelerate to FL speed when the SD signal is turned ON, and then stop. If the SD signal is turned OFF during deceleration, the axis will accelerate to FH speed.
- If the SD signal is turned ON after writing a start command, the axis will complete its operation without another start.
- When stopped, the axis will output an #INT signal.

[FL constant speed operation] [FH constant speed operation] [High speed operation]


4) Latch and deceleration stop <SDM (bit 4) = 1, SDLT (bit 5)=1 in RENV1>

- If the SD signal is turned ON while in constant speed operation, the axis will stop. If the SD signal is turned ON while in high speed operation, the axis will decelerate to FL speed and then stop. Even if the SD signal is turned OFF during deceleration, the axis will not accelerate.
- If the SD signal is turned ON while writing a start command, the axis will not start moving and the operation will not be completed.
- While stopped, the LSI outputs an #INT signal.



The input logic of the SD signal can be changed. If the latched input is set to accept input from the SD signal, and if the SD signal is OFF at the next start, the latch will be reset. The latch is also reset when the latch input is set to zero.

The minimum pulse width of the SD signal is 80 reference clock cycles (4.0 μ sec) when the input filter is ON. When the input filter is turned OFF, the minimum pulse width is two reference clock cycles (0.1 μ sec). (When CLK = 19.6608 MHz.)

The latch signal of the SD signal can be monitored by reading SSTSW (sub status). The SD signal terminal status can be monitored by reading RSTS (extension status). By reading the REST register, you can check for an error interrupt caused by the SD signal turning ON.

Enable/disable SD signal input <set (bit="" 8)="" in="" msde="" prmd=""></set>	[PRMD]	(WRITE)
0: Disable SD signal input	15	8
1: Enable SD signal input		n
Input logic of the SD signal <set 6)="" in="" renv1="" sdl(bit=""></set>	[RENV1]	(WRITE)
0: Negative logic	7	0
1: Positive logic	- n	
Set the operation pattern when the SD signal is turned ON <set (bit="" 4)<="" sdm="" td=""><td>[RENV1]</td><td>(WRITE)</td></set>	[RENV1]	(WRITE)
0: Decelerates on receiving the SD signal and feeds at FL constant speed	7	0
1: Decelerates and stops on receiving the SD signal	n -	
Select the SD signal input type <set (bit="" 5)="" in="" renv1="" sdlt=""></set>	[RENV1]	(WRITE)
0: Level input	7	0
1: Latch input	n	
To release the latch, turn OFF the SD input when next start command is		
written or select Level input.		
Reading the latch status of the SD signal <ssd (bit="" 15)="" in="" sstsw=""></ssd>	[SSTSW]	(READ)
0: The SD latch signal is OFF	15	8
1: The SD latch signal is ON	n	
Reading the SD signal < SDIN (bit 15) in the RSTS >	[RSTS]	(READ)
0: The SD signal is OFF	15	8
1: The SD signal is ON	n	
Reading the cause of an #INT when stopped by the SD signal <essd (bit<="" td=""><td>[REST]</td><td>(READ)</td></essd>	[REST]	(READ)
10) in REST>	15	8
1: Deceleration stop caused by the SD signal turning ON	0	n
Apply an input filter to SD <set (bit="" 26)="" fltr="" in="" renv1=""></set>	[RENV1]	(WRITE)
1: Apply a filter to the SD input	31	24
By applying a filter, signals with a pulse width of 4 µsec or less will be		n
ignorea.		

11-5-3. ORG, EZ signals

These signals are enabled in the zero return modes (zero return, leave zero position, and zero position search) and in the EZ count operation modes. Specify the operation mode and the operation direction using the PRMD register (operation mode).

Since the ORG signal input is latched internally, there is no need to keep the external signal ON. The ORG latch signal is reset when stopped.

The minimum pulse width of the ORG signal is 80 reference clock cycles (4 μ sec) when the input filter is ON. When the input filter is turned OFF, the minimum pulse width is two reference clock cycle (0.1 μ sec). (When CLK = 19.6608 MHz.)

The input logic of the ORG signal and EZ signal can be changed using the RENV1 register (environment setting 1).

The ORG terminal status can be monitored by reading SSTSW (sub status). The EZ terminal status can be monitored by reading the RSTS register (extension status).

For details about the zero return operation modes, see 9-5, "Zero position operation mode."

ORG signal and EZ signal timing



(i) When $t \ge 2 \times T_{CLK}$, counts.

- (ii) When $T_{CLK} < t < 2 \times T_{CLK}$, counting is undetermined.
- (iii) When t \leq T_{CLK}, do not count. T_{CLK}: Reference clock cycle

Enabling the ORG and EZ signals <set (bits="" 0="" 6)="" in="" mod="" prmd="" to=""></set>		(WRITE)
001 0000: Zero return in the positive direction		
001 0010: Leave zero position in the positive direction		
001 0101: Zero position search in the positive direction		<u>n n n n</u>
010 0100: EZ counting in the positive direction		
001 1000: Zero return in the negative direction		
001 1010: Leave zero position in the negative direction		
001 1101: Zero position search in the negative direction		
010 1100: EZ count operation in the negative direction		
Set the zero return method <set (bits="" 0="" 3="" 3)="" in="" orm0="" renv3="" to=""></set>	IRENV31	(WRITE)
See the RENV3 register description	7	0
		n n n n
Set the input logic for the ORG signal <set (bit="" 7)="" in="" orgl="" renv1=""></set>	[RENV1]	(WRITE)
0. Negalive logic	7	0
	n	
Read the ORG signal <sorg (bit="" 14)="" in="" sstsw=""></sorg>	[SSTSW]	(READ)
0: The ORG signal is OFF	15	. 8
1: The ORG signal is ON	- n	
Set the FZ count number <pre>Set FZD0 to 3 (bits 4 to 7) in RENV3></pre>		(WRITE)
Set the zero return completion condition and the EZ count number for counting.		(
Specify the value (the number to count to -1) in EZD0 to 3. The setting range		
is 0 to 15.		- - - -
Specify the input logic of the EZ signal <set (bit="" 23)="" ezl="" in="" renv2=""></set>	[RENV2]	(WRITE)
0: Falling edge	23	16
1: Rising edge	n	
Read the EZ signal <sez (bit="" 10)="" in="" rsts=""></sez>	IRSTS1	(READ)
0: The EZ signal is OFF	15	8
1: The EZ signal is ON		
Apply an input filter to E7 <pre>CSet ELTP (bit 26) in PENI/1></pre>		
1. Apply all input littler to the EZ Set FLIR (bit 20) in REINVIZ		
Ry applying a filter signals with a pulse width of 4 usec or less will be ignored		24
	- - - -	- n

11-6. Servomotor I/F (Case in digital servo)

11-6-1. INP signal

The pulse strings input accepting servo driver systems have a deflection counter to count the difference between command pulse inputs and feedback pulse inputs. The driver controls to adjust the difference to zero. In other words, the effective function of servomotors is to delete command pulses and, even after the command pulses stop, the servomotor systems keep feeding until the count in the deflection counter reaches zero.

This LSI can receive a positioning complete signal (INP signal) from a servo driver in place of the pulse output complete timing, to determine when an operation is complete.

When the INP signal input is used to indicate the completion status of an operation, the #BSY signal when an operation is complete, the main status (bits 0 to 5 of the MSTSW, stop condition), and the extension status (CND0 to 3, operation status) will also change when the #INP signal is input.

The input logic of the INP signal can be changed.

The minimum pulse width of the INP signal is 80 reference clock cycles (4 μ sec) when the input filter is ON. If the input filter is OFF, the minimum pulse width will be 2 reference clock cycles (0.1 μ sec). (When CLK = 19.6608 MHz)

If the INP signal is already ON when the PCL is finished outputting pulses, it treats the operation as complete, without any delay.

The INP signal can be monitored by reading the RSTS register (extension status).

Set the operation complete delay using the INP signal <set (bit="" 9)="" in<="" minp="" th=""><th>[PRMD] (WRITE)</th></set>	[PRMD] (WRITE)
PRMD>	15 8
0: No operation complete delay waiting for the INP signal.	
1: Operation complete (status, #BSY) delay until the INP signal turns ON.	
Input logic of the INP signal <set (bit="" 22)="" in="" inpl="" renv1=""></set>	[RENV1] (WRITE)
0: Negative logic	23 16
1: Positive logic	- n
Reading the INP signal <sinp (bit="" 16)="" in="" rsts=""></sinp>	[RSTS] (READ)
0: The INP signal is OFF	23 16
1: The INP signal is ON	
Set the INP input filter <fltr (bit="" 26)="" in="" renv1=""></fltr>	[RENV1] (WRITE)
1: Apply a filter to the INP input.	31 24
By applying a filter, pulses less than 4 μ sec in width are ignored.	n

11-6-2. ERC signal

A servomotor delays the stop until the deflection counter in the driver reaches zero, even after command pulses have stopped being delivered. In order to stop the servomotor immediately, the deflection counter in the servo driver must be cleared.

This LSI can output a signal to clear the deflection counter in the servo driver. This signal is referred to as an "ERC signal." The ERC signal is output as one shot signal or a logic level signal. The output type can be selected by setting the RENV1 register (environment setting 1). If an interval is required for the servo driver to recover after turning OFF the ERC signal (HIGH) before it can receive new command pulses, the ERC signal OFF timer can be selected by setting the RENV1 register.



In order to output an ERC signal at the completion of a zero return operation, set EROR (bit 11) = 1 in the RENV1 register (environment setting 1) to make the ERC signal an automatic output. For details about ERC signal output timing, see the timing waveform in section 9-5-1, "Zero return operation." In order to output an ERC signal for an immediate stop based on the EL signal, ALM signal, or #CEMG signal input, or on the emergency stop command (05h), set EROE (bit 10) = 1 in the RENV1 register, and set automatic output for the ERC signal. (In the case of a deceleration stop, the ERC signal cannot be output, even when set for automatic output.)

The ERC signal can be output by writing an ERC output command (24h).

The output logic of the ERC signal can be changed by setting the RENV1 register. Read the RSTS (extension status) register to monitor the ERC signal.

1: Does not output an ERC signal when stopped by EL, ALM, or #CEMG input. 15 1: Automatically outputs an ERC signal when stopped by EL, ALM, or #CEMG	8 - n
1: Automatically outputs an ERC signal when stopped by EL, ALM, or #CEMG	- n
input.	
Set automatic output for the ERC signal <set (bit="" 11)="" eror="" in="" renv1=""> [RENV1]</set>	(WRITE)
0: Does not output an ERC signal at the completion of a zero return operation. 15	8
1: Automatically outputs an ERC signal at the completion of a zero return	
operation.	
Set the ERC signal output width <set (bits="" 12="" 14)="" 2="" epw0="" in="" renv1="" to=""> [RENV1]</set>	(WRITE)
000: 12 µsec 100: 13 msec 15	. 8
001: 102 µsec 101: 52 msec	, <u>_ _ _ _ </u>
010: 408 µsec 110: 104 msec	
011: 1.6 msec 111: Logic level output	
Select output logic for the ERC signal <set (bit="" 15)="" ercl="" in="" renv1=""> [RENV1]</set>	(WRITE)
0: Negative logic 15	8
1: Positive logic	
$\sum_{n=1}^{n}$	
	(WRITE)
REINV 12 23	16
	n n
Dead the EPC signal \leq SERC (bit 0) in RSTS	
	(READ)
	8
	n -
Emergency stop command <cmemg: command="" operation=""> [Operation</cmemg:>	command]
Output an ERC signal	ihl -

11-6-3. ALM signals

Input alarm (ALM) signal.

When the ALM signal turns ON while in operation, the axis will stop immediately or decelerate and stop.

However, the axis only decelerates and stops on an ALM signal if it was started with a high speed start. When the axis is started at constant speed, the signal on the ALM terminal will cause an immediate stop.

To stop using deceleration, keep the ALM input ON until the axis stops operation.

If the ALM signal is ON when a start command is written, the LSI will not output any pulses.

The minimum pulse width of the ALM signal is 80 reference clock cycles (4 μ sec) if the input filter is ON.

If the input filter is OFF, the minimum pulse width is 2 reference clock cycles (0.1 μ sec). (When CLK = 19.6608 MHz.)

The input logic of the ALM signal can be changed. The signal status of the ALM signal can be monitored by reading SSTSW (sub status).

Stop method when the ALM signal is ON <set (bit="" 8)="" almm="" in="" renv1=""> 0: Stop immediately when the ALM signal is turned ON</set>	[RENV1] (WRITE) 15 8
ON	
Input logic setting of the ALM signal <set (bit="" 9)="" alml="" in="" renv1=""></set>	[RENV1] (WRITE)
	15 8
1: Positive logic	n -
Read the ALM signal <salm (bit="" 11)="" in="" sstsw=""></salm>	[SSTSW] (READ)
U: The ALM signal is OFF	15 8
1: The ALM signal is ON	n
Reading the cause of a stop when the ALM signal is turned ON <esal (bit="" 7)<="" td=""><td>[REST] (READ)</td></esal>	[REST] (READ)
IN REST>	7 0
1: Stop due to the ALM signal being turned ON	n
Set the ALM input filter <set (bit="" 26)="" fltr="" in="" renv1=""></set>	[RENV1] (WRITE)
1: Apply a filter to the ALM input	31 24
When a filter is applied, pulses less than 4 µsec pulse in width will be ignored.	n

11-7. External start, simultaneous start

11-7-1. STA signals (#CSTA, #STA)

This LSI can be started when triggered by an external signal on the #CSTA terminals. Set MSY (bits 18 to 19) in the PRMD register to 01 (operation mode) and the LSI will start feeding when the #CSTA or #STA goes LOW. The #CSTA terminal (bi-directional) is used for simultaneously starting multiple LSIs. The #STA terminal (input) is used to start a single axis using an external signal. The #CSTA is the commoned version of the STA terminal.

When you want to control multiple axes using more than one LSI, connect the #CSTA terminal on each LSI. Then set all of the axes to "waiting for STA input," and they will all start at the same time. In this example a start signal can be output through the #CSTA terminal.

Combined use of the #CSTA and #STA terminals is supported.

The input logic on the #CSTA terminals cannot be changed.

By setting the RIRQ register (event interrupt cause), the #INT signal can be output together with a simultaneous start (when the STA input is ON). By reading the RIST register, the cause of an event interrupt can be checked.

The operation status (waiting for STA input), and status of the STA terminal (OR of the #CSTA and #STA signals) can be monitored by reading the RSTS register (extension status).

<How to make a simultaneous start>

Set MSY0 to 1 (bits 18 to 19) in the PRMD register for the axes you want to start. Write a start command and put the LSI in the "waiting for #CSTA input" status. Then, start the axes simultaneously by either of the methods described below.

- By writing a simultaneous start command, the LSI will output a one shot signal of 8 reference clock cycles (approx. 0.4 µsec when CLK = 19.6608 MHz) from the #CSTA terminal.
- 2) Input hardware signal from outside.
- Supply a hardware signal by driving the terminal with open collector output (74LS06 or equivalent).

STA signals can be supplied as level trigger or edge trigger inputs. However, when level trigger input is selected, if STA is turned on or a start command is written, the axis will start immediately. After connecting the #CSTA terminals on each LSI, each axis can still be started independently using start commands.

To release the "waiting for STA input" condition, write an immediate stop command (49h).

1) To start axes controlled by different LSIs simultaneously, connect the LSIs as follows.



2) To start simultaneously from an external circuit, or use a single axis as an external start, connect the LSIs as follows.



For start signal, supply a one shot input signal with a pulse width of at least 4 reference clock cycles (approx. 0.2μ sec when CLK = 19.6608 MHz).

STA input <msy0 (bits="" 1="" 18="" 19)="" in="" prmd="" to=""> 01: Start by inputting a STA signal (#CSTA or #STA)</msy0>	[PRMD] (WRITE) 23 16
Specify the input specification for the STA signal <set (bit="" 18)="" in<br="" stam="">RENV1> 0: Level trigger input for the #CSTA and #STA signal 1: Edge trigger input for the #CSTA and #STA signal</set>	[RENV1] (WRITE) 23 16 n
Read the STA signal (#CSTA and #STA) <ssta (bit="" 5)="" in="" rsts=""> 0: The STA signal is OFF 1: The STA signal is ON</ssta>	[RSTS] (READ) 7 0 n
Read the #STA signal <sest (bit="" 17)="" in="" rsts=""> 0: The #STA signal is OFF 1: The #STA signal is ON</sest>	[RSTS] (READ) 23 16 n -
Read the operation status <cnd (bits="" 0="" 3)="" in="" rsts="" to=""> 0010: Waiting for STA input</cnd>	[RSTS] (READ) 7 0 n n n n
Set an event interrupt cause <set (bit="" 18)="" in="" irsa="" rirq=""> 1: Output an #INT signal when the STA input is ON.</set>	[RIRQ] (WRITE) 23 16 0 0 0 0 0 n
Reading the event interrupt cause <issa (bit="" 19)="" in="" rist=""> 1: When the STA signal is ON.</issa>	[RIST] (READ) 23 16 0 0 0 0 n
Simultaneous start command <cmsta: command="" operation=""> Output a one shot pulse 8 reference clock cycles long from the #CSTA terminal. (The #CSTA terminal is bi-directional. It can receive signals output from</cmsta:>	[Operation command] 06h
Local axis only, simultaneous start command <spsta: operation<br="">command> Used the same way as when a STA signal is supplied, for a local axis only.</spsta:>	[Operation command]] 2Ah

11-7-2. PCS signal

The PCS input is a terminal originally used for the target position override 2 function. By setting the MSY (bits 18 to 19) to "01" in the PRMD (operation mode) register, the PCS input signal can enable the #CSTA signal for only its own axis. The input logic of the PCS input signal can be changed. The terminal status can be monitored by

reading the RSTS register (extension status).

Specify the function of the PCS signal <set (bit="" 30)="" in="" pcsm="" renv1=""></set>	[RENV1]	(WRITE)
1: Only allow the PCS input the local axis #CSTA signal.	31	24
	- n	
Set the Waiting for #CSTA input <set (bits="" 1="" 18="" 19)="" in="" msy0="" rmd="" to=""></set>	[RMD]	(WRITE)
01: Start on a #CSTA input.	23	16
		n n
Set the input logic of the PCS signal <set (bit="" 24)="" in="" pcsl="" renv1=""></set>	[RENV1]	(WRITE)
0: Negative logic	31	24
1: Positive logic		n
Read the PCS signal <spcs (bit="" 8)="" in="" rsts=""></spcs>	[RSTS]	(READ)
0: The PCS signal is OFF	15	8
1: The PCS signal is ON		n

11-8. External stop / simultaneous stop

This LSI can execute an immediate stop or a deceleration stop triggered by an external signal using the #CSTP terminal. Set MSPE (bit 24) = 1 in the PRMD register (operation mode) to enable a stop from a #CSTP input. The axis will stop immediately or decelerate and stop when the #CSTP terminal is LOW. However, a deceleration stop is only used for a high speed start. When the axis is started at constant speed, the signal on the #CSTP terminal will cause an immediate stop.

The input logic of the #CSTP terminal cannot be changed.

When multiple LSIs are used to control multiple axes, connect all of the #CSTP terminals from each LSI and input the same signal so that the axes which are set to stop on a #CSTP input can be stopped simultaneously. In this case, a stop signal can also be output from the #CSTP terminal.

When an axis stops because the #CSTP signal is turned ON, an #INT signal can be output. By reading the REST register, you can determine the cause of an error interrupt. You can monitor #CSTP terminal status by reading the RSTS register (extension status).

<How to make a simultaneous stop>

Set MSPE (bit 24) = 1 in the PRMD register for each of the axes that you want to stop simultaneously. Then start these axes.

Stop these axes using either of the following three methods.

- By writing a simultaneous stop command, the #CSTP terminal will output a one shot signal 8 reference clock cycles in length (approx. 0.4 μsec when CLK = 19.6608 MHz).
- 2) Supply an external hardware signal Supply a hardware signal using an open collector output (74LS06 or equivalent).
- 3) The #CSTP terminal will output a one shot signal for 8 reference clock cycles (approximately 0.4 µsec when CLK = 19.6608 MHz) when a stop caused by an error occurs on an axis that has MSPO = 1 in the PRMD register.

Even when the #CSTP terminals on LSIs are connected together, each axis can still be stopped independently by using the stop command.

1) Connect the terminals as follows for a simultaneous stop among different LSIs.



2) To start simultaneously using an external circuit, connect as follows.



As a stop signal, supply a one shot signal 4 reference clock cycles or more in length (approx. 0.2 μ sec when CLK = 19.6608 MHz).

Setting to enable #CSTP input <set (bit="" 24)="" in="" mspe="" prmd=""></set>	[PRMD]	(WRITE)
1. Enable a stop from the #CSTP input. (Immediate stop, deceleration stop)	31	24
) n
Auto output setting for the #CSTP signal <set (bit="" 25)="" in="" mspo="" prmd="" the="" to=""></set>	[PRMD]	(WRITE)
1: When an axis stops because of an error, the PCL will output the #CSTP	31	24
signal. (Output signal width: 8 reference clock cycles)	0 0 0 0) n -
Specify the stop method to use when the #CSTP signal is turned ON. <set< td=""><td>[RENV1]</td><td>(WRITE)</td></set<>	[RENV1]	(WRITE)
STPM (bit 19) in RENV1>	23	16
0: Immediate stop when the #CSTP signal is turned ON.		n
1: Deceleration stop when the #CSTP signal is turned ON.		
Read the #CSTP signal <sstp (bit="" 6)="" in="" rsts=""></sstp>	[RSTS]	(READ)
0: The #CSTP signal is OFF	7	0
1: The #CSTP signal is ON	- n	
Read the cause of an error input < ESSP (bit 8) in REST>	[REST]	(READ)
1. When stopped because the #CSTP signal turned ON.	15	8
		n
Simultaneous stop command <cmstp: command="" operation=""></cmstp:>	[Operation	command]
Outputs a one shot pulse of 8 reference clock cycles in length from the #CSTP terminal.	0	7h
(The CSTP terminal is bi-directional. It can receive signals output from other		
PCLs.)		

11-9. Emergency stop

This LSI has a #CEMG input terminal for use as an emergency stop signal.

While in operation, if the #CEMG input goes LOW or if you write an emergency stop command, all the axes will stop immediately. While the #CEMG input remains LOW, no axis can be operated. The logical input of the #CEMG terminal cannot be changed.

When the axes are stopped because the #CEMG input was turned ON, the LSI will output an #INT signal. By reading the REST register, the cause of the error interruption can be determined. The status of the #CEMG terminal can be monitored by reading the REST register (extension status).

Read the #CEMG signal <semg (bit="" 7)="" in="" rsts=""></semg>	[RSTS] (READ)
0: The #CEMG signal is OFF	7 0
1: The #CEMG signal is ON	n
Read the cause of an error interrupt <esem (bit="" 9)="" in="" rest=""> 1. Stopped when the #CEMG signal was turned ON.</esem>	[REST] (READ) 16 8 n -
Emergency stop command <cmemg: command="" operation=""></cmemg:>	[Operation command]
The operation is the same as when a #CEMG signal is input.	05h

Note: In a normal stop operation, the final pulse width is normal. However, in an emergency stop operation, the final pulse width may not be normal. It can be triangular. Motor drivers do not recognize triangle shaped pulses, and therefore only the PCL counter may count this pulse. (Deviation from the instructed position control). Therefore, after an emergency stop, you must perform a zero return to match the instructed position with the mechanical position.

11-10. Counter

11-10-1. Counter type and input method

In addition to the positioning counter, this LSI contains four other counters. These counters offer the following functions.

- Control command position and mechanical position
- Detect a stepper motor that is "out of step" using COUNTER3 (deflection counter) and a comparator.
- Output a synchronous signal using COUNTER4 (general-purpose) and a comparator.

The positioning counter is loaded with an absolute value for the RMV register (target position) with each start command, regardless of the operation mode selected. It decreases the value with each pulse that is output. However, if MPCS (bit 14) of the RMD register (operation mode) is set to 1 and a position override 2 is executed, the counter does will not decrease until the PCS input turned ON. Input to COUNTER1 is exclusively for output pulses. However COUNTERS2 to 4 can be selected as follows by setting the RENV3 register (environment setting 3).

	COUNTER1	COUNTER2	COUNTER3	COUNTER4
Counter name	Command position	Mechanical position	Deflection	General-purpose
Counter type	Lln/down counter	LIn/down counter	Deflection	Up/down
Counter type	op/down counter	Op/down counter	counter	counter
Number of bits	28	28	16	28
Output pulse	Possible	Possible	Possible	Possible
Encoder (EA/EB) input	Not possible	Possible	Possible	Possible
Pulsar (PA/PB) input	Not possible	Possible	Possible	Possible
1/2 of reference clock	Not possible	Not possible	Not possible	Not possible

Note: When using pulsar input, use the internal signal result after multiplying or dividing.

Specify COUNTER2 (mechanical position) input <ci20 (bit="" 21="" 8="" 9)="" in<="" th="" to=""><th>[RENV3] (WRITE)</th></ci20>	[RENV3] (WRITE)
RENV3>	15 8
00: EA/EB input	
01: Output pulses	
10: PA/PB input	
Set COUNTER3 (deflection) input <ci30 (bit="" 10="" 11)="" 31="" in="" renv3="" to=""></ci30>	[RENV3] (WRITE)
00: Measure the deflection between output pulses and EA/EB input	15 8
01: Measure the deflection between output pulses and PA/PB input	
10: Measure the deflection between EA/EB input and PA/PB input	
Set COUNTER4 (general-purpose) input <ci40 (bit="" 12="" 13)="" 41="" in="" renv3="" to=""></ci40>	[RENV3] (WRITE)
00: Output pulses	15 8
01: EA/EB input	
10: PA/PB input	
11: Reference clock (CLK) / 2.	

The EA/EB and PA/PB input terminal, that are used as inputs for the counter, can be set for one of two signal input types by setting the RENV2 (environment setting 2) register.

- 1) Signal input method: Input 90° phase difference signals (1x, 2x, 4x)
- Counter direction: Count up when the EA input phase is leading. Count down when the EB input phase is leading.
- 2) Signal input method: Input 2 sets of positive and negative pulses.
- Counter direction: Count up on the rising edge of the EA input. Count down on the falling edge of the EB input.

The counter direction or EA/EB and PA/PB input signals can be reversed.

The LSI can be set to sense an error when both the EA and EB input, or both the PA and PB inputs change simultaneously, and this error can be detected using the REST (error interrupt cause) register.

Set the input signal filter for EA/EB/EZ <set (bit="" 18)="" einf="" in="" renv2=""></set>	[RENV2]	(WRITE)
0: Turn OFF the filter function	23	16
1: Turn ON the filter function (Input signals shorter than 3 reference clock		n
cycles are ignored.)		
Setting the EA/EB input <set (bit="" 1="" 20="" 21)="" eim0="" in="" renv2="" to=""></set>	[RENV2]	(WRITE)
00: 90° phase difference, 1x 10: 90° phase difference, 4x	23	16
01: 90° phase difference, 2x 11: 2 sets of up or down input pulses	n n -	
Specify the EA/EB input count direction <set (bit="" 22)="" edir="" in="" renv2="" to=""></set>	[RENV2]	(WRITE)
0: Count up when the EA phase is leading. Or, count up on the rising edge of	23	16
EA.	- n	
1: Count up when the EB phase is leading. Or, count up on the rising edge of FB		
Enable/disable EA/EB input <set (bit="" 30)="" eoee="" in="" renv2=""></set>		
0: Enable EA/EB input		(UNIXI) 24
1: Disable EA/EB input. (EZ input is valid.)		24
	- n	
Set the input signal filter for PA/PB <set (bit="" 19)="" in="" pinf="" renv2=""></set>	[RENV2]	(WRITE)
0: Turn OFF the filter function.	23	16
1: Turn ON the filter function (Input signals shorter than 3 reference clock cycles are ignored.)	n	
Specify the PA/PB input <set (bit="" 1="" 24="" 25)="" in="" pim0="" renv2="" to=""></set>	[RENV2]	(WRITE)
00: 90° phase difference, 1x 10: 90° phase difference, 4x	31	、 24
01: 90° phase difference, 2x 11: 2 sets of up or down input pulses		- n n
Specify the PA/PB input count direction <set (bit="" 26)="" in="" pdir="" renv2="" to=""></set>	IRENV21	(WRITE)
0: Count up when the PA phase is leading. Or, count up on the rising edge of	31	、 24
PA.		
 Count up when the PB phase is leading. Or, count up on the rising edge of PB. 		
Enable/disable PA/PB input <set (bit="" 31)="" in="" poff="" renv2=""></set>	[RENV2]	(WRITE)
0: Enable PA/PB input	31	24
1: Disable PA/PB input.	n	
Reading EA/EB, PA/PB input error <esee (bit="" 16),="" 17)="" espe="" in="" td="" the<=""><td>[REST]</td><td>(READ)</td></esee>	[REST]	(READ)
REST>	23	. 16
ESEE (bit 16) = 1: An EA/EB input error occurred.		
ESPE (bit 17) = 1: A PA/PB input error occurred.		

When EDIR is "0," the EA/EB input and count timing will be as follows. For details about the PA/PB input, see section "9-3. Pulsar input mode."

1) When using 90° phase difference signals and 1x input

EA EB COUNTER		
2) When usin EA EB COUNTER	ng 90° phase difference signals and 2x input $n = \frac{1}{n + 1} + \frac{1}{n + 2} + \frac{1}{n + 1}$	 Xn

3) When using 90° phase difference signals and 4x input

of when doing of				ix inp	at			_				_	
EA –]												
EB _													
COUNTER n	(n+1)	n+2	× n+3	X	n+4	χ	n+3	X	n+2	X	n+1	X	n
_													
4) When two puls	es are input	(counted	on the ris	ing ed	lge)								
EA —] []										
EB													
COUNTER	X n+	1	χ	n+2		χ		n+1		_χ_		n	
-2. Counter reset All the counters 1) When the (2) When a zer 3) When a count The PCL can al	can be rese CLR input sig o return is e mmand is wi so be specif	et using an gnal turns xecuted (itten. ied to res	ny of the fo ON (set ir set in REN et automa	ollowir n REN NV3). itically,	ng thr V3). , sooi	ee r n aff	netho er lat	ods. ching	g the c	ounte	er value	9.	
Action when the C CU1C (bit 16) = CU2C (bit 17) = CU3C (bit 18) = CU4C (bit 19) =	Liming can b out is the car LR signal tu 1: Reset CC 1: Reset CC 1: Reset CC 1: Reset CC	e set in R use of an ms ON <s UNTER1 UNTER2 UNTER3 UNTER4</s 	ENV1 (en event inte fet CU1C to (commar (mechan (deflectio (general	vironm rrupt. o 4C (t nd pos nical pr on). -purpo	bit 16 bit 16 bition ositic bse).	to 1). on).	ng 1) 9) in t	the R	≠INTS ENV3>	Ignal [RE1 23 -	can be	e ou: (\ n	WRI n r
CU1R (bit 20) = CU2R (bit 21) = CU3R (bit 22) = CU4R (bit 23) =	=1: Reset C =1: Reset C =1: Reset C =1: Reset C	OUNTER OUNTER OUNTER OUNTER	1 (commai 2 (mechan 3 (deflectio 4 (general	nd pos nical po on) -purpo	sition) osition	n)	.57 111	NEN.	v J~	[REN 23 n	NV3] n n n	(\	//RI
Setting when late CU1L (bit 24) = CU2L (bit 25) = CU3L (bit 26) = CU4L (bit 27) = Action for the CL	:hed <set c<br="">: 1: Reset C : 1: Reset C : 1: Reset C : 1: Reset C : 1: Reset C R signal <s< td=""><th>U4L to 1L OUNTER OUNTER OUNTER OUNTER OUNTER</th><td>. (bits 24 to 1 (comma 2 (machin 3 (deviatic 4 (general o 1 (bit 20</td><td>o 27) ii nd pos e posiⁱ on). I-purpo to 21)</td><td>n RE sition tion). ose).</td><td>NV5). EN\</td><td>/1></td><td></td><td></td><td>[REN 31 0</td><td>₩5] 0 0 0 ₩11</td><td>(\ </td><td>WRI n r</td></s<></set>	U4L to 1L OUNTER OUNTER OUNTER OUNTER OUNTER	. (bits 24 to 1 (comma 2 (machin 3 (deviatic 4 (general o 1 (bit 20	o 27) ii nd pos e posi ⁱ on). I-purpo to 21)	n RE sition tion). ose).	NV5). EN\	/1>			[REN 31 0	₩5] 0 0 0 ₩11	(\ 	WRI n r
00: Clear on th 01: Clear on th	e falling edg e rising edg	e 10:0 e 11:0	Clear on a Clears on	LOW a HIGI	level H lev	el				23	- n n	-	
Reading the CLF 0: The CLR sig 1: The CLR sig	≀ signal <sc nal is OFF nal is ON</sc 	LR (bit 13	3) in RSTS	<u>}></u>						[RS ⁻ 15 -	ΓS] - n -	(RE
Set event interru 1: Output an #I signal ON.	pt cause <s NT signal w</s 	et IRCL (k nen resett	bit 13) in R ting the co	RIRQ> ounter	value	e by	turnir	ng the	e CLR	[RIR 15 -	Q] - n -	()	WRI
Read the event i 1: When you w	nterrupt cau ant to reset	se <iscl the counte</iscl 	(bit 13) in er value b	RIST> y turni	> ng Ol	N th	e CL	R sig	nal.	[RIS 15 -	6T] - n -	((RE#
Counter reset co 20h: Set COUN 21h: Set COUN 22h: Set COUN	mmand <cu ITER1 (com ITER2 (mec ITER3 (defle</cu 	IN1R to C mand pos hanical po ection) to a	CUN4R: Co sition) to zo osition) to zero.	ontrol ero zero.	comr	nan	d>			[C 2	ontrol o 0h 21h	comr 22h	nan 231

Note: In order to prevent incorrect counts, when the count timing and reset timing match, the counter will be +1 or -1, never 0. Please note this operation detail when detecting 0 with the comparator function.

11-10-3. Latch the counter and count condition

All the counters can latch their counts using any of the following methods. The setting is made in RENV5 (environment setting 5) register. The latched values can be output from the RLTC1 to 4 registers.

1) Turn ON the LTC signal.

2) Turn ON the ORG signal.

3) When the conditions for Comparator 4 are satisfied.

4) When the conditions for Comparator 5 are satisfied.

5) When a command is written.

The current speed can also be latched instead of COUNTER3 (deflection). Items 1) to 4) above can also be latched by hardware timing.

The LTC input timing can be set by in RENV1 (environment setting 1). An #INT signal can be output when a counter value is latched by turning ON the LTC signal or the ORG signal. This allows you to identify the cause of an event interrupt.

Specify the latch method for a counter (1 to 4) <set (bit="" 1="" 12="" 13)="" in<="" ltm0="" th="" to=""><th>[RENV5] (WRITE)</th></set>	[RENV5] (WRITE)
RENV5>	15 8
00: Turn ON the LTC signal.	
01: Turn ON the ORG signal.	
10: When the conditions for Comparator 4 are satisfied.	
11: When the conditions for Comparator 5 are satisfied.	
Specify the latch method for the current speed <set (bit="" 14)="" in="" ltfd="" renv5=""></set>	[RENV5] (WRITE)
1: Latch the current speed instead of COUNTER 3 (deflection).	15 8
	- n
Specify latching using hardware <set (bit="" 15)="" in="" ltof="" renv5=""></set>	[RENV5] (WRITE)
1: Do not latch 1) to 4) above with hardware timing.	15 8
	n
Specify the LTC signal mode <set (bit="" 23)="" in="" ltcl="" renv1=""></set>	[RENV1] (WRITE)
0: Latch on the falling edge.	23 16
1: Latch on the rising edge.	n
Set an event interrupt cause <set (bit="" 14)="" 15)="" and="" in="" irlt="" irot="" rirq=""></set>	[RIRQ] (WRITE)
IRLT = 1: Output an #INT signal when the counter value is latched by the LTC	15 8
signal being turned ON.	
IROT = 1: Output an #INT signal when the counter value is latched by the ORG signal being turned ON.	
Read the event interrupt cause <islt (bit="" 14),="" 15)="" in="" isol="" rist=""></islt>	[RIST] (READ)
ISLT = 1: Latch the counter value when the LTC signal turns ON.	15 8
ISOL = 1: Latch the counter value when the ORG signal turns ON.	n n
Read the LTC signal <sltc (bit="" 14)="" in="" rsts=""></sltc>	[RSTS] (READ)
0: The LTC signal is OFF.	15 8
1: The LTC signal is ON.	- n
Counter latch command <ltch: command="" control=""></ltch:>	[Control command]
Latch the contents of the counters (COUNTER1 to 4).	2 9h

11-10-4. Stop the counter

COUNTER1 (command position) stops when the PRMD (operation mode) register is set to stop the counter while in timer mode operation.

COUNTER2 (mechanical position), COUNTER3 (deflection), and COUNTER4 (general-purpose) stop when the RENV3 (environment setting 3) register is set to stop.

By setting the RENV3 register, you can stop counting pulses while performing a backlash or slip correction.

COUNTER4 (general-purpose) can be set to count only during operation (BSY = low) using the RENV3 register. By specifying 1/2 of the CLK (reference clock) signal, the time after the start can be controlled.

Stopping COUNTER1 (command) <set (bit="" 11)="" in="" mcce="" prmd=""></set>	[RMD]	(WRITE)
1. Stop COUNTER1 (command position).	15	8
		n
Specify the counting operation for COUNTERS 2 to 4 <set (bits<="" 2h="" cu4h="" td="" to=""><td>[RENV3]</td><td>(WRITE)</td></set>	[RENV3]	(WRITE)
29 to 31) in RENV3>	31	24
CU2H (bit 29) = 1: Stop COUNTER2 (mechanical position)		
CU3H (bit 30) = 1: Stop COUNTER3 (deflection)		
CU4H (bit 31) = 1: Stop COUNTER4 (general-purpose)		
Setting the counters for backlash or slip correction <set (bits="" 24<="" 4b="" cu1b="" td="" to=""><td>[RENV3]</td><td>(WRITE)</td></set>	[RENV3]	(WRITE)
to 27) in RENV3>	31	24
CU1B (bit 16) = 1: Enable COUNTER1 (command position)		
CU2B (bit 17) = 1: Enable COUNTER2 (mechanical position)		
CU3B (bit 18) = 1: Enable COUNTER3 (deflection)		
CU4B (bit 19) = 1: Enable COUNTER4 (general-purpose)		
Specify the counting conditions for COUNTER4 <set (bit="" 14)="" bsyc="" in<="" td=""><td>[RENV3]</td><td>(WRITE)</td></set>	[RENV3]	(WRITE)
RENV3>	15	8
1. Enable COUNTER4 (general-purpose) only while operating (BSY = L).	- n	

11-11. Comparator

11-11-1. Comparator types and functions

This LSI has 5 circuits/axes using 28-bit comparators. It compares the values set in the RCMP1 to 5 registers with the counter values.

Comparators 1 to 4 can be used as comparison counters and can be assigned as COUNTERS 1 to 4. Comparator 5 can be assigned as COUNTER 1 to 4, a positioning counter, or to track the current speed. There are many comparison methods and four processing methods that can be used when the conditions are met.

Specify the comparator conditions in the RENV4 (environment 4) and RENV5 (environment 5) registers. By using these comparators, you can perform the following.

- Use comparators for INT outputs, external output of comparison data, and for internal synchronous starts
- Immediate stop and deceleration stop operations.
- Change operation data to pre-register data (used to change speed while operating).
- Software limit function using Comparators 1 and 2.
- Ring count function using COUNTER1 (command position) and Comparator 1.
- Ring count function using COUNTER2 (mechanical position) and Comparator 2.
- Detect out of step stepper motors using COUNTER3 (deflection) and a comparator.

• Output a synchronous signal (IDX) using COUNTER4 (general-purpose) and a Comparator 4. Comparator 5 is equipped with a pre-register. It too can output an #INT signal when the comparator's conditions are satisfied.

1	follo	owing table.								
Comparison data	Сс	omparator 1	Comparator 2		Comparator 3		Coi	mparator 4	Comparator 5	
Companson uala		C1C0 to 1		C2C0 to 1		C3C0 to 1		C4C0 to 1		C5C0 to 2
COUNTER1 (command position)	0	"00"	0	"00"	0	"00"	0	"00"	0	"000"
COUNTER2 (mechanical position)	0	"01"	0	"01"	0	"01"	0	"01"	0	"001"
COUNTER3 (deflection)	0	"10"	0	"10"	0	"10"	0	"10"	0	"010"
COUNTER4 (general-purpose)	0	"11"	0	"11"	0	"11"	0	"11"	0	"011"
Positioning counter									0	"100"
Current speed									0	"101"
Pre-register		None		None	None		None		Yes	
		+SL		-SL						
		Use		Use						
Major application	С	OUNTER1	C	OUNTER1			ID	X output		
		as a ring		as a ring						
		counter		counter						

[Comparison data] Each comparator can select the data for comparison from the items in the following table.

- O: Comparison possible. Blank: Comparison not possible.

- +SL, -SL are used for software limits.

- If COUNTER3 (deflection) is selected as the comparison counter, the LSI will compare the absolute value of the counter with the comparator data. (Absolute value range: 0 to 32,767)

- The bit assignments of the comparison data settings are as follows:

C1C0 to 1 (RENV4 bits 0 to 1), C2C0 to 1 (RENV4 bits 8 to 9), C3C0 to 1 (RENV4 bits 16 to 17), C4C0 to 1 (RENV4 bits 24 to 25), C5C0 to 2 (RENV5 bits 0 to 2)

[Comparison method] Each comparator can be assigned a comparison method from the table below.

	С	ompara	ator 1	С	ompara	ator 2	Сс	mparator 3	Со	mparator 4	Сс	mparator 5
Comparison method		C1S	C1RM		C2S	C1RM		C3S	;	C4S		C5S
		0 to 2			0 to 2			0 to 2		0 to 3		0 to 2
Comparator = Comparison												
counter (regardless of count	0	"001"	'0'	0	"001"	'0'	0	"001"	0	"0001"	0	"001"
direction)												
Comparator = Comparison	0	"010"	'0'	0	"010"	' O '	0	"010"	0	"0010"	0	"010"
counter (Count up only)	0	010	0	0	010	0	0	010	0	0010	0	010
Comparator = Comparison	0	"011"	'O'	0	"011"	' O '	0	"011"	0	"0011"	0	"011"
counter (Count down only)	0	011	0	0	011	0	0	011	0	0011	0	011
Comparator > Comparison		"100"	' O '	\circ	"100"	'0'	\cap	"100"	0	"0100"	\circ	"100"
counter	0	100	0	0	100	0	0	100	0	0100	0	100
Comparator < Comparison	0	"101"	' ∩ '	0	"101"	' ∩ '	0	"101"	0	"0101"	0	"101"
counter	0	101	0	0	101	0	0	101		0101	0	101
Use for software limits	0	"110"	'0'	О	"110"	'0'						
IDX (synchronous signal)												
output (regardless of									0	"1000"		
counting direction)												
IDX (synchronous signal)									0	"1001"		
output (count up only)							1		0	1001		
IDX (synchronous signal)									0	"1010"		
output (count down only)										1010		
Use COUNTER1 as a ring	0	"001"	'4 '						0	"1010"		
counter	0	001	I						0	1010		
Use COUNTER2 as a ring				0	"001"	'4'				"1010"		
counter				0	001	I			0	1010		

- O: Comparison possible. Blank: Comparison not possible.

- When used for software limits, Comparator 1 is a positive direction limit value and the comparison method is comparator < comparison counter. Comparator 2 is the negative limit value and the comparison method is comparator > comparison counter. Select COUNTER1 (command position) for the comparison counter.
- Comparator 3 must not have C3S0 to 2 set to a value of 110. Setting any of the values may result in failing to satisfy the comparison conditions.
- When C4S0 to 3 = 1000 to 1010 for Comparator 4 <IDX (synchronous signal) output>, select COUNTER4 (general-purpose) for use as the comparison counter. Other counters cannot be used for this function. Enter a positive value for the comparator setting.
- The bit assignments for various comparison methods are as follows:
 C1S0 to 2 (RENV4 bits 2 to 4), C2S0 to 2 (RENV4 bits 10 to 12), C3S0 to 1 (RENV4 bits 18 to 20), C4S0 to 3 (RENV4 bits 26 to 29), C5S0 to 2(RENV5 bits 3 to 5)

when the conditions are satisfied can be selected from the table below.								
Processing method when the	Comparator 1	Comparator 2	Comparator 3	Comparator 4	Comparator 5			
conditions are met	C1D0 to 1	C2D0 to 1	C3D0 to 1	C4D0 to 1	C5D0 to 1			
Do nothing	"00"	"00"	"00"	"00"	"00"			
Immediate stop operation	"01"	"01"	"01"	"01"	"01"			
Deceleration stop operation	"10"	"10"	"10"	"10"	"10"			
Change operation data to pre-register data	"11"	"11"	"11"	"11"	"11"			

[Processing method when comparator conditions are satisfied] The processing method that is used when the conditions are satisfied can be selected from the table below.

- "Do nothing " is mainly used for INT output, external output of comparison result, or internal synchronous starts.

 To change the speed pattern while in operation, change the operation data to the values stored as pre-register data. The PRMV setting will also be transferred to the RMV. However, this does not affect operation.

- The bit assignments to select a processing method are as follows.

C1D0 to 1 (RENV4 bits 5 to 6), C2D0 to 1 (RENV4 bits 13 to 14), C3D0 to 1 (RENV4 bits 21 to 22), C4D0 to 1 (RENV4 bits 30 to 31), C5D0 to 1 (RENV5 bits 6 to 7)

[How to set the INT output, external output of comparison results, and internal synchronous starting]

Set an event interrupt cause <set (bit="" 12)="" 5="" 8="" in="" irc1="" rirq="" to=""></set>	IRIRQI (WRITE)
IRC1 (bit 8) = 1: Output #INT signal when the Comparator 1 conditions are	15 8
satisfied	
IRC2 (bit 9) = 1. Output #INT signal when the Comparator 2 conditions are	<u> n n n n n</u>
satisfied	
satisfied. IDC2 (bit 10) = 1: Output #INT signal when the Comparator 2 conditions are	
(BC3 (Dit T0) = 1) Output #iNT signal when the Comparator 3 conditions are	
satisfied.	
IRC4 (bit 11)= 1: Output #INT signal when the Comparator 4 conditions are	
satisfied.	
IRC5 (bit 12)= 1: Output #INT signal when the Comparator 5 conditions are	
satisfied.	
Read the event interrupt cause <isc1 (bit="" 12)="" 5="" 8="" in="" rist="" to=""></isc1>	
IRC1 (bit 8) = 1: When the Comparator 1 conditions are satisfied	
IPC2 (bit 0) = 1: When the Comparator 2 conditions are satisfied	
IRC2 (bit 3) = 1. When the Comparator 2 conditions are satisfied.	n n n n n
(100 G) = 1. When the Comparator 5 conditions are satisfied.	
(RC4 (bit 11) = 1) when the Comparator 4 conditions are satisfied.	
IRC5 (bit 12) = 1: When the Comparator 5 conditions are satisfied.	
Read the comparator condition status <scp1 (bits="" 12)="" 5="" 8="" in="" mstsw="" to=""></scp1>	[MSTSW] (READ)
SCP1 (bit 8) = 1: When the Comparator 1 conditions are satisfied.	15 8
SCP2 (bit 9) = 1: When the Comparator 2 conditions are satisfied.	
SCP3 (bit 10) = 1. When the Comparator 3 conditions are satisfied	<u> - - - n n n n n n</u>
SCP4 (bit 11) = 1: When the Comparator 4 conditions are satisfied	
SCD5 (bit 12) = 1: When the Comparator 5 conditions are satisfied.	
SCFS(bit 12) = 1. When the Comparator 5 contaitions are satisfied.	
Specify the P3/CP1 (+SL) terminal specifications <p3ivilu (bits="" 1="" 6="" 7)="" in<="" td="" to=""><td>[RENV2] (WRITE)</td></p3ivilu>	[RENV2] (WRITE)
RENV2>	7 0
00: General-purpose input	n n
01: General-purpose output	
10: Output a CP1 (Comparator 1 conditions satisfied) signal using negative	
logic.	
11: Output a CP1 (Comparator 1 conditions satisfied) signal using positive	
Specify the $PI/(CP2 (SI))$ terminal exceptions $< PI/M(0)$ to 1 (hits 8 to 0) in	
	[RENV2] (WRITE)
REINV22	15 8
00: General-purpose input	- - - - - n n
01: General-purpose output	
10: Output CP2 (Comparator 2 conditions satisfied) signal using negative	
logic.	
11: Output CP2 (Comparator 2 conditions satisfied) signal using positive logic.	
Specify the P5/CP3 terminal specifications <set (bits="" 1="" 10="" 11)="" in<="" p5m0="" td="" to=""><td>IRENV21 (WRITE)</td></set>	IRENV21 (WRITE)
RENV2>	
00: General-nurnose innut	
01: Ceneral purpose autout	- - - n n - -
10: Output CD2 (Comparator 2 conditions actisfied) signal using pagative	
To. Output CFS (Comparator 5 conditions satisfied) signal using negative	
11: Output CP3 (Comparator 3 conditions satisfied) signal using positive logic.	
Specify the P6/CP4 terminal specifications <set (bits="" 1="" 12="" 13)="" in<="" p6m0="" td="" to=""><td>[RENV2] (WRITE)</td></set>	[RENV2] (WRITE)
RENV2>	15 8
00: General-purpose input	
01: General-purpose output	<u>- - n n - - - - </u>
10: Output CP4 (Comparator 4 conditions satisfied) signal using negative	
11: Output CP4 (Comparator 4 conditions satisfied) signal using positive logic	
Provide the D7/CDE terminal apositions and D7M0 to 4 (kits 44 to 45) in	
Specify the P7/GP5 terminal specifications <set (bits="" 1="" 14="" 15)="" in<="" p7mu="" td="" to=""><td>[RENV2] (WRITE)</td></set>	[RENV2] (WRITE)
KENV2>	15 8
00: General-purpose input	n n
01: General-purpose output	
10: Output CP5 (Comparator 5 conditions satisfied) signal using negative	
logic.	
11: Output CDE (Componeter E conditions patiefied) signal using positive logic	

Specify the output timing for an internal synchronous signal <set 3<="" syo1="" td="" to=""><td>[RENV5]</td><td>(WRITE)</td></set>	[RENV5]	(WRITE)
(bits 16 to 19) in RENV5>	23	16
0001: When the Comparator 1 conditions are satisfied.		
0010: When the Comparator 2 conditions are satisfied.		
0011: When the Comparator 3 conditions are satisfied.		
0100: When the Comparator 4 conditions are satisfied.		
0101: When the Comparator 5 conditions are satisfied.		
1000: When the acceleration starts.		
1001: When the acceleration is complete.		
1010: When the deceleration starts		
1011: When the deceleration is complete.		
Others: Turn OFF internal synchronous output signal		

[Speed change using the comparator]

When the comparator conditions are met, you can use the function which changes the operation data to the values stored as pre-register data. This function is used to change the speed when a specified position is reached.

Also, Comparator 5 has a pre-register function, and can be specified for use in changing the speed at specified positions. In this case, use the "Pre-register set command (4Fh)," to specify several sets of speed data.

If the speed change data (data used with set commands) are left in Pre-registers 1 and 2 when the current operation completes (Example 1), or if the speed change data is left in Pre-register 1 and some next operation data exists in Pre-register 2 (Example 2), the PCL will ignore the speed change data and shift the data in the pre-registers.

Then, in Example 2, the PCL will start the next operation after shifting the data in the pre-registers.

Example 1

	(PFM=11)			(PFM=00)
Pre-register 2	Speed change data 2		Pre-register 2	Speed change data 2
-	(set)		-	(undetermined)
Pre-register 1	Speed change data 1	Complete current	Pre-register 1	Speed change data 2
	(set)	operation		(undetermined)
Register	Current operation	\rightarrow	Register	Speed change data 1
	data (set)			(undetermined)
Example 2				
	(PFM=11)		_	(PFM=01)
Pre-register 2	Next operation data		Pre-register 2	Next operation data
	(set)			(undetermined)
Pre-register 1	Speed change data	Complete current	Pre-register 1	Next operation data
	(set)	operation		(undetermined)
Register	Current operation	\rightarrow	Register	Next operation data
	data (set)			(set)
Set a pre-registe	[Operation command]			
Identify the pre-r	ИЕР			

11-11-2. Software limit function

A software limit function can be set up using Comparators 1 and 2. Select COUNTER1 (command position) as a comparison counter for Comparators 1 and 2. Use Comparator 1 for a positive direction limit and Comparator 2 for a negative direction limit to stop the axis based on the results of the comparator and the operation direction. When the software limit function is used the following process can be executed.

- 1) Stop pulse output immediately
- 2) Decelerate and then stop pulse output

While using the software limit function, if a deceleration stop is selected as the process to use when the comparator conditions are met (C1D, C2D), when an axis reaches the software limit while in a high speed start (52h, 53h), that axis will stop using deceleration. When some other process is specified for use when the conditions are met, or while in a constant speed start, that axis will stop immediately.

If a software limit is ON while writing a start command, the axis will not start to move in the direction in which the software limit is enabled. However, it can start in the opposite direction.

[Setting example]

RENV4=00003838h: Use Comparator 1 as positive direction software limit. Use Comparator 2 as negative direction software limit. Set to stop immediately when the software limit is reached.

	Set to stop immediately when the software limit is rea
RCMP1= 100,000:	Positive direction limit value
RCMP2= -100,000:	Negative direction limit value

Ne	gative directi RGMP2 (ion limit position -100,000)	Positive directi RGMP1	iion limit position (100,000)
	<	Normal ope	eration zone	>
Unable to feed in the negative direction	e;	Able to feed in the negative direction	Able to feed in the positive direction	Unable to feed in the positive direction

Operation from the negative direction limit position Operation from the positive direction limit position

Specify the comparison method for Comparator 1 <set (bits="" 2="" 4)<="" c1s="" th="" to=""><th>[RENV4] (WRITE)</th></set>	[RENV4] (WRITE)
in RENV4>	7 0
110: Use as a positive direction software limit	n n n
Specify the process to use when the Comparator 1 conditions are met <set< td=""><td>[RENV4] (WRITE)</td></set<>	[RENV4] (WRITE)
C1D0 to 1 (bits 5 to 6) in RENV4>	7 0
01: Immediate stop	
10: Deceleration stop	
Specify the comparison method for Comparator 2 <set (bits="" 10="" 2="" c2s0="" td="" to="" to<=""><td>[RENV4] (WRITE)</td></set>	[RENV4] (WRITE)
12) in RENV4>	15 8
110: Use as a negative direction software limit.	n n n
Specify the process to use when the Comparator 2 conditions are met <set< td=""><td>[RENV4] (WRITE)</td></set<>	[RENV4] (WRITE)
C2D0 to 1 (bits 13 to 14) in RENV4>	15 8
01: Immediate stop	
10: Deceleration stop	

11-11-3. Out of step stepper motor detection function

If the deflection counter value controlled by the motor command pulses and the feed back pulses from an encoder on a stepper motor exceed the maximum deflection value, the LSI will declare that the stepper motor is out of step. The LSI monitors stepper motor operation using COUNTER3 (the deflection counter) and a comparator.

The process which takes place after an out of step condition is detected can be selected from the table. [Processing method to use when the comparator conditions are satisfied].

For this function, use an encoder with the same resolution as the stepper motor.

COUNTER3 (deflection) can be cleared by writing a set command to the deflection counter.

There are two methods for inputting a feedback signal: Input 90° phase difference signals (1x, 2x, 4x) on the EA/EB terminals, input two sets of positive and negative pulses.

If both EA and EB signals change at the same time, the LSI will treat this as an error and output an #INT signal.

[Setting example]

RENV4 = 00360000h: Satisfy the conditions of Comparator 3 < COUNTER3 (deflection) Stop immediately when the conditions are satisfied.

RCMP3 = 32: The maximum deflection value is "32" pulses.

RIRQ = 00000400h: Output an #INT signal when the conditions for Comparator 3 are satisfied.

Specify the EA/EB input <set (bits="" 1="" 20="" 21)="" eim0="" in="" renv2="" to=""></set>	[RENV2] (WRITE
00: 90° phase difference, 1x	23 16
01: 90° phase difference, 2x	
10: 90° phase difference, 4x	
11: 2-pulse mode	
Specify the EA/EB input count direction <set (bit="" 22)="" edir="" in="" renv2=""></set>	[RENV2] (WRITE
0: When the EA phase is leading, or count up on the EA rising edge.	23 8
1: When the EB phase is leading, or count up on the EB rising edge	- n 0 0
Read the EA/EB input error <esee (bit="" 16)="" in="" rest=""></esee>	[REST] (READ
1: An EA/EB input error has occurred.	23 16
	000000-r
Counter reset command <cun3r: command="" control=""></cun3r:>	[Control command]
Clear COUNTER3 (deflection) to zero.	22h

11-11-4. IDX (synchronous) signal output function

Using Comparator 4 and COUNTER4, the PCL can output signals to the P6n/CP4n terminals at specified intervals. Setting C4C0 to C4C1 to "11" (in the general-purpose counter) and setting C4S0 to C4S3 to "1000", "1001 or "1010" (the IDX output), the PCL can be used for IDX (index) operation. The counter range of COUNTER4 will be 0 to the value set in RCMP4. If counting down from 0 the lower limit will be the value set in RCMP4, and if counting up from the value set in RCMP4 the limit will be 0.

The input for COUNTER4 can be set to CI40 to CI41 in RENV2.

By setting IDXM in RENV4, you can select either level output or count output.

Select the specification for the P6/CP4 terminals <set 1="" in="" p6m0="" renv2<="" th="" to=""><th>[RENV2] (WRITE)</th></set>	[RENV2] (WRITE)
(bits 12 to13)>	15 8
10: Output an IDX signal using negative logic	
11: Output an IDX signal using positive logic	
Select the count input for COUNTER4 (general-purpose) <set 41<="" cl40="" td="" to=""><td>[RENV3] (WRITE)</td></set>	[RENV3] (WRITE)
(bits 12 to13) in RENV3>	15 8
00: Output pulses 10PA/PB input	
01: EA/EB input 11ivide the CLK input by 2.	
Select the comparison counter for Comparator 4 <set (bits="" 1="" 24="" 25)<="" c4c0="" td="" to=""><td>[RENV4] (WRITE)</td></set>	[RENV4] (WRITE)
in RENV4>	31 24
11: COUNTER4 (general-purpose).	n n
Select the comparison method for COUNTER4 <set (bits="" 26="" 29)<="" 3="" c4s0="" td="" to=""><td>[RENV4] (WRITE)</td></set>	[RENV4] (WRITE)
in RENV4>	31 24
1000: IDX output (regardless of count direction)	
1001: IDX output (only while counting up)	
1010: IDX output (only while counting down)	
Select the IDX output mode <set (bit="" 23)="" idxm="" in="" renv4=""></set>	[RENV4] (WRITE)
0: Outputs an IDX signal while COUNTER4 = RCMP4.	23 16
1: Outputs an IDX signal for two CLK cycles when COUNTER4 reaches 0 by	
counting.	

Note: While IDXM = 1, writing a "0" to COUNTER4 or resetting COUNTER4 will not output an IDX signal. The setting in IDXM is only effective when C4S0 to C4S3 are set to 1000, 1001, or 1010 (synchronous signal output).

Output example 1: (IDXM = 0: Level output)

Note: When IDXM (synchronous signal output) is set to 0 and IDX outputs C4S0 to C4S3 are set to 1001 or 1010, use a count range for the RCMP4 counter that is >= 2.

Regardless of the feed direction, the PCL will output the IDX signal using negative logic for the output pulses. (Counting range: 0 to 4.)

Settings: RENV2 = 00002000h, RENV3 = 00000000h, RENV4 = 23000000h, RCMP4 = 4

DIR	
ουτ	
P6n/CP4n	
COUNTER4 0 1 2 3 4 0 1 2 3 4 0	1 \ 0\ 4\ 3\ 2\ 1\ 0\ 4\ 3\ 2\ 1\ 0\ 4\ 3
Output example 2 (IDXM = 1: Count output) Regardless of the feed direction, the PCL will output pulses. (Counting range 0 to 4.) Settings: RENV2 = 00002000h, RENV3 = 00000000	the IDX signal using negative logic for the output 0h, RENV4 = 23800000h, RCMP4 = 4
DIR	7
P6n/CP4n	
COUNTER4 0 X 1 X 2 X 3 X 4 X 0 X 1 X 2 X 3 X 4 X 0 X	1 X0X4X3X2X1X0X4X3X2X1X0X4X3

11-11-5. Ring count function

COUNTER1 and 2 have a ring count function for use in controlling a rotating table.

Set C1PM = 1, C1S0 to 2 = 000, and C1C0 to 1 = 00 in RENV4 and COUNTER1 will be in the ring count mode. Then the PCL can perform the following operations.

- Count value = Count up from the value in RCMP1 until reaching 0.

- Count value = Count down from 0 until the count equals the value in RCMP1.

Set C2PM = 1, C2S0 to 2 = 000, and C2C0 to 1 = 01 in RENV4 and COUNTER2 will be in the ring count mode. Then the PCL can perform the following operations.

- Count value = Count up from the value in RCMP2 until reaching 0.

- Count value = Count down from 0 until the count equals the value in RCMP2.

Set COUNTER1 to ring counter operation <set 1,="" 2,<="" c1d0="" c1rm,="" c1s0="" td="" to=""><td>[RENV4]</td><td>(WRITE)</td></set>	[RENV4]	(WRITE)
and C1C0 to 1 in RENV4>	7	0
10000000: Operate COUNTER1 as a ring counter.		
		nnnn
Set COUNTER2 to ring count operation <set 1,="" 2,<="" c2d0="" c2rm,="" c2s0="" td="" to=""><td>[RENV4]</td><td>(WRITE)</td></set>	[RENV4]	(WRITE)
and C2C1 to 0 in RENV4>	15	8
10000001: Operate COUNTER2 as a ring counter.		
		nnnn

Even if the value for PRMV outside the range of 0 to the value in RCMPn, the PCL will continue to perform positioning operations.

When driving a rotating table with 3600 pulses per revolution, and when RCMP1 = 3599, MOD = 41h, and RMV = 7200, the table will rotate twice and the value in COUNTER1, when stopped, will be the same as the value before starting.

Note: To use the ring counter function, set the count value between 0 and the value in RCMPn. If the value is outside the range above, the PCL will not operate normally. Set the comparator conditions (C1S0 to 2, C2S0 to 2) when using a counter as a ring counter to "000."

Setting example

RENV4 = XXXXX80h --- COUNTER1 is in ring counter mode (C1RM = 1, C1S0 to 2 = 000, C1C0 to 1 = 00)

RCMP1 = 4	Count range: 0 to 4
-----------	---------------------

DIR		
OUT		
COUNTER4	$0 \times 1 \times 2 \times 3 \times 4 \times 0 \times 1 \times 2 \times 3 \times 4 \times 0 \times 0$	$1 \qquad \qquad$

11-12. Backlash correction and slip correction

This LSI has backlash and slip correction functions. These functions output the number of command pulses specified for the correction value in the speed setting in the RFA (correction speed) register. The backlash correction is performed each time the direction of operation changes. The slip correction function is performed before a command, regardless of the feed direction. The correction amount and method is specified in the RENV6 (environment setting 6) register. The operation of the counter (COUNTER 1 to 4) can be set using the RENV3 (environment setting 3)

register. Enter the correction value <BR0 to 11 (bits 0 to 11) in RENV6> [RENV6] (WRITE) 15 8 Backlash or slip correction amount value (0 to 4095) _ n n n n 7 n n n n n n n n n Set the correction method <ADJ0 to 1 (bits 12 &13) in RENV6> [RENV6] (WRITE 00: Turn the correction function OFF 15 ۶

01: Backlash correction n n 10: Slip correction Action for backlash/slip correction <CU1B to 4B (bit 26 to 27) in RENV3> [RENV3] (WRITE CU1B (bit 16) = 1: Enable COUNTER1 (command position) 31 24 CU2B (bit 17) = 1: Enable COUNTER2 (mechanical position) 0 _ n n n n CU3B (bit 18) = 1: Enable COUNTER3 (deflection) CU4B (bit 19) = 1: Enable COUNTER4 (general-purpose)

11-13. Vibration restriction function

This LSI has a function to restrict vibration when stopping by adding one pulse of reverse operation and one pulse of forward operation shortly after completing a command pulse operation. Specify the output timing for additional pulses in the RENV7 (environment setting 7) register. When both the reverse timing (RT) and the forward timing (FT) are non zero, the vibration restriction function is enabled.

The dotted lines below are pulses added by the vibration restriction function. (An example in the positive direction)

Positive pulses	Final puls		
	Final pulse		
NeRTative pulses			
		← RT/2 →	← FT/2
		RT *	FT >

Specify the reverse operation timing <set (bits="" 0="" 15="" 15)="" in="" renv7="" rt0="" to=""></set>	[RENV7] (WRITE)
RT range: 0 to 65,535	15 8
The units are 32x the reference clock cycle (approx. 1.6 µsec when CLK =	
19,6608 MHz)	
Settable range: 0 to approx. 0.1 sec.	7 0
	n n n n n n n n
Specify the forward operation timing <set (bits="" 15="" 16="" 31)="" ft0="" in="" renv7="" to=""></set>	[RENV7] (WRITE)
Specify the forward operation timing <set (bits="" 15="" 16="" 31)="" ft0="" in="" renv7="" to=""> FT range: 0 to 65,535</set>	[RENV7] (WRITE) 31 24
Specify the forward operation timing <set (bits="" 15="" 16="" 31)="" ft0="" in="" renv7="" to=""> FT range: 0 to 65,535 The units are 32x the reference clock cycle (approx. 1.6 µsec when CLK =</set>	[RENV7] (WRITE) 31 24
Specify the forward operation timing <set (bits="" 15="" 16="" 31)="" ft0="" in="" renv7="" to=""> FT range: 0 to 65,535 The units are 32x the reference clock cycle (approx. 1.6 µsec when CLK = 19,6608 MHz)</set>	[RENV7] (WRITE) 31 24 n n n n n n n n
Specify the forward operation timing <set (bits="" 15="" 16="" 31)="" ft0="" in="" renv7="" to=""> FT range: 0 to 65,535 The units are 32x the reference clock cycle (approx. 1.6 µsec when CLK = 19,6608 MHz) Settable range: 0 to approx. 0.1 sec.</set>	[RENV7] (WRITE) 31 24 n n n n n 23 16

Note: The optimum values for RT and FT will vary with each piece of machinery and load. Therefore, it is best to obtain these values by experiment.

11-14. Synchronous starting

This LSI can perform the following operation by setting the PRMD (operation mode) register in advance.

- ♦ Start triggered by another axis stopping.
- ♦ Start triggered by an internal synchronous signal from another axis.

The internal synchronous signal output is available with 9 types of timing. They can be selected by setting the RENV5 (environment setting 5) register. By setting the RIRQ (event interrupt cause) register, an #INT signal can be output at the same time the internal synchronous signal is output. You can determine the cause of event interrupt by reading the RIST register. The operation status can be checked by reading the RSTS (extension status) register.

Specify the synchronous starting method <set (bits="" 1="" 18="" 19)="" in="" msy0="" prmd="" to=""></set>	(WRITE)
10: Start with an internal synchronous signal.	23 16
11: Start triggered by another axis stopping.	n n
Select an axis for confirming a stop (setting example) <specify axis="" td="" the="" using<=""><td>[PRMD] (WRITE)</td></specify>	[PRMD] (WRITE)
MAX0 to 1 (bits 20 to 21) in PRMD>	23 16
01: Start when the X axis stops	
10: Start when the Y axis stops	
11: Start when both the X and Y axes have stopped	
Select the synchronous starting mode <set (bit="" 29)="" in="" renv2="" smax=""></set>	[RENV2] (WRITE)
0: PCL6025 compatible mode	31 24
1: PCL6025B mode	n
Specify the internal synchronous signal output timing <set (bits="" 16="" 3="" syo1="" td="" to="" to<=""><td>[RENV5] (WRITE)</td></set>	[RENV5] (WRITE)
19) in RENV5>	23 16
0001: When the Comparator 1 conditions are satisfied.	
0010: When the Comparator 2 conditions are satisfied.	
0011: When the Comparator 3 conditions are satisfied.	
0100: When the Comparator 4 conditions are satisfied.	
0101: When the Comparator 5 conditions are satisfied.	
1000: When the acceleration is started.	
1001: When the acceleration is complete.	
1010: When the deceleration is started.	
1011: When the deceleration is complete	
Others: Internal synchronous output signal is OFF.	
Specify the input for the internal synchronous signal <set (bits="" 1="" 20="" 21)="" in="" renv(5)<="" syi0="" td="" to=""><td>[RENV5] (WRITE)</td></set>	[RENV5] (WRITE)
21) III NEINVOZ	23 16
00.05e an internal synchronous signal output by the X axis. 01: Use an internal synchronous signal output by the X axis	n n
C_{1} Ose an internal synchronous signal output by the T axis.	
0011: Wait for an internal synchronous signal	[RSIS] (READ)
0100: Wait for another axis to stop	7 0
	n n n n
Select the event interrupt (#INT output) cause <set 12="" 4="" bit="" of="" rirq="" to=""></set>	[RIRQ] (WRITE)
IRUS (bit 4) = 1: When the acceleration is started.	7 0
IRUE (bit 5) = 1: When the acceleration is complete.	n n n n
IRDS (bit 6) = 1: When the deceleration is started.	15 8
IRDE (bit 7) = 1: When the deceleration is complete.	
IRC1 (bit 8) = 1: When the Comparator 1 conditions are satisfied.	<u> - - - n n n n n n</u>
IRC2 (bit 9) = 1: When the Comparator 2 conditions are satisfied.	
IRC3 (bit 10) = 1: When the Comparator 3 conditions are satisfied.	
IRC4 (bit 11) = 1: When the Comparator 4 conditions are satisfied.	
IRC5 (bit 12) = 1: When the Comparator 5 conditions are satisfied.	

Read the event interrupt (#INT output) cause <bit 12="" 4="" of="" rist="" to=""> ISUS (bit 4) = 1: When the acceleration is started. ISUE (bit 5) = 1: When the acceleration is complete. ISDS (bit 6) = 1: When the deceleration is started. ISDE (bit 7) = 1: When the deceleration is complete. ISC1 (bit 8) = 1: When the Comparator 1 conditions are satisfied. ISC2 (bit 9) = 1: When the Comparator 2 conditions are satisfied.</bit>	[RIST] 7 <u>n n n n n</u> 15 <u> n</u>	(READ) 0 8 n n n n n
 ISC2 (bit 9) = 1: When the Comparator 2 conditions are satisfied. ISC3 (bit 10) = 1: When the Comparator 3 conditions are satisfied. ISC4 (bit 11) = 1: When the Comparator 4 conditions are satisfied. ISC5 (bit 12) = 1: When the Comparator 5 conditions are satisfied. 		

11-14-1. Start triggered by another axis stopping

If the start condition for the X axis is specified as a "Stop of the Y axis," and if the Y axis stops after operating, the X axis will start moving if it is currently stopped.

Example 1 below shows an example of how to set the "stop of the Y axis" as a condition for starting the X axis.

[Example 1]

After setting steps 1) to 3), start and stop the Y axis and then the X axis will start.

- 1) Set MSY0 to 1 (bits 18 to 19) in PRMD for the X axis to "11." (Start triggered by another axis stopping)
- 2) Set MAX0 to 1 (bits 20 to 21) in PRMD for the X axis to "11." (When the Y axis and then the X axis stops)
- 3) Write a start command for the X axis.

The "start when another axis stops" function has two operation modes: one is PCL6025 compatible and the other is the PCL6025B mode. Select the operation mode using SMAX in the RENV2 register. (When SMAX = 0, the PCL6025 compatible mode is selected.)

[PCL6025 compatible mode]

In order to use "Another axis stops" as a start condition, the axis specifying this condition (X axis) must be ready to start its process and then it can wait for the other axis to stop. At this point the other axis (the Y axis) can be started and stopped.

For example, if the X and Y axes are performing circular interpolation, and if "Both axes stop" is set as a start condition in the pre-register for the next operation, when X and Y are "waiting for both axes to stop" (so that they can start the linear interpolation at the end of the circular interpolation), since they are already stopped the change "from operation to stop" will not occur while they are waiting. Therefore the X and Y axes will never start the linear interpolation.

In other words, the working axis cannot be specified for the MAX setting to start itself.

[PCL6025B mode]

When "start when another axis stops" is specified as the start condition for the next operation in a specific pre-register, the working axis can be called out in the MAX setting so that it starts itself on the next operation at the end of a previous operation.

Example

Settings

Operation mode for the X axis in initial operation: MSY0 to 1 = 00, MAX0 to 1 = 00Operation mode calling for the X axis in the next operation: MSY0 to 1 = 11, MAX0 to 1 = 11Operation mode for the Y axis in initial operation: MSY0 to 1 = 00, MAX0 to 1 = 00Operation mode calling for the Y axis in the next operation: MSY0 to 1 = 11, MAX0 to 1 = 11(X axis positioning operation time) > (Y axis positioning operation time)

1) When the PCL6025 compatible mode (SMAX = 0) is selected



2) When the PCL6025B mode (SMAX = 1) is selected

X axis	Stopping	Initial operation	Next operation	
	Operating			
Y axis	Operating I	nitial operation	Next operation	

When using continuous interpolation, you may set the next operation in the pre-register (you don't need to specify any stop conditions) rather using the "start when another axis stops" function. The settings are shown in Example 2 below.

The example below describes only the items related to the operations. The settings for speed and acceleration are omitted.

[Example 2]

How to set up a continuous interpolation (X-Y axis circular interpolation followed by an X-Y axis linear interpolation)

Step	Register	X axis	Y axis	Description		
	PRMV	10000	10000	X and Y axes perform an circular		
	PRIP	10000	0	interpolation operation of a 90° curve with		
1	PRMD	0000_0064h	0000_0064h	a radius of 10000		
	Start command: Write 0351h (FH constant speed start)			X and Y axes start command		
	PRMV	10000	5000	X and Y axes perform a linear		
2	PRMD	0000_0061h	0000_0061h	interpolation with an end point (1000, 5000)		
	Start command: Write 0351h (FH constant speed start)			X and Y axes start command		

After the settings above are complete, the LSI will execute a continuous operation in the order shown below.

- 1. The X and Y axes perform a CW circular interpolation operation of a 90° curve with a radius of 10000.
- 2. The X and Y axes perform a linear interpolation (10000, 5000)

11-14-2. Starting from an internal synchronous signal

There are 9 types of internal synchronous signal output timing. They can be selected by setting the RENV5 register.

The monitor signal for the internal synchronous signal can be output externally.

Example 1 below shows how to use the end of an acceleration for the internal synchronous signal.

[Example 1]

After completing steps 1) to 3) below, write a start command to the X and Y axes, the X axis will start when the Y axis completes its acceleration.

- 1) Set MSY0 to 1 (bits 18 to19) in the X axis PRMD to 10. (Start with an internal synchronous signal)
- 2) Set SYI0 to 1 (bits 20 to 21) in the X axis RENV5 to 01. (Use an internal synchronous signal from the Y axis.)





Example 2 shows how to start another axis using the satisfaction of the comparator conditions to generate an internal synchronous signal.

Be careful, since comparator conditions satisfied by timing and the timing of the start of another axis may be different according to the comparison method used by the comparators.

[Example 2]

- Use COUNTER1 (command position) and Comparator 1 to start the X axis when the Y axis = 1000.
 - 1) Set MSY0 to 1 (bits 18 to 19) in the X axis PRMD to 10. (Start from an internal synchronous signal)
 - 2) Set SYI0 to 1 (bits 20 to 21) in the X axis RENV5 to 01. (Use an internal synchronous signal from the Y axis)
 - 3) Set SYO0 to 3 (bits 16 to 19) in the Y axis RENV5 to 0001. (Output an internal synchronous signal when the Comparator 1 conditions are satisfied)
 - 4) Set C1C0 to 1 (bits 0 to 1 in the Y axis RENV4 to 00. (Comparator 1 comparison counter is COUNTER1)
 - 5) Set C1S0 to 2(bits 2 to 4 in the Y axis RENV4 to 001. (Comparison method: Comparator 1 = Comparison counter)
 - Set C1D0 to 1(bits 5 to 6) in the Y axis RENV4 to 00. (Do nothing when the Comparator 1 condition are satisfied)
 - 7) Set the RCMP1 value of the Y axis to 1000. (Comparison counter value of Comparator 1 is 1000.)
 - 8) Write start commands for the X and Y axes.

The timing chart below shows the period after the Comparator 1 conditions are established and the X axis starts.

OUTy -						
Y axis command position counter value	997 998	999 1	1000	1001	1002 10	003
CP1y _						
OUTx -						
X axis comand position counter value	0	X	1	2	3	4

Note: In the example above, even if the Y feed amount is set to 2000 and the X feed amount is set to 1000, the X axis will be 1 when the Y axis position equals 1000. Therefore, the operation complete position will be one pulse off for both the X and Y axes. In order to make the operation complete timing the same, set the RCMP1 value to 1001 or set the comparison conditions to "Comparator 1 < comparison counter."

Specify the use of the P0/FUP terminal <set (bits="" 0="" 1="" 1)="" in<="" p0m0="" td="" to=""><td>[RENV2]</td><td>(WRITE)</td></set>	[RENV2]	(WRITE)
RENV2>	7	0
10: Output an FUP (accelerating) signal		· n n
Specify the use of the P1/FDW terminal <set (bits="" 1="" 2="" 3)="" in<="" p1m0="" td="" to=""><td>[RENV2]</td><td>(WRITE)</td></set>	[RENV2]	(WRITE)
RENV2>	7	0
10: Output an FDW (decelerating) signal	<u></u>	<u>nn</u>
Select the output logic for P0 (one shot) / FUP <set (bit="" 16)="" in="" p0l="" renv2=""></set>	[RENV2]	(WRITE)
0: Negative logic	23	16
1: Positive logic		00-n
Select the output logic for P1 (one shot) / FDW <set (bit="" 17)="" in="" p1l="" renv2=""></set>	[RENV2]	(WRITE)
0: Negative logic	23	16
1: Positive logic		00n-
Specify the use of the P3/CP1 (+SL) terminal <set (bits="" 1="" 6="" 7)="" in<="" p3m0="" td="" to=""><td>[RENV2]</td><td>(WRITE)</td></set>	[RENV2]	(WRITE)
RENV2>	7	0
10: Output CP1 (Comparator 1 conditions are satisfied) using negative logic.	n n	
11: Output CP1 (Comparator 1 conditions are satisfied) using positive logic.		
Specify the use of the P4/CP2 (-SL) terminal <set (bits="" 1="" 8="" 9)="" in<="" p4m0="" td="" to=""><td>[RENV2]</td><td>(WRITE)</td></set>	[RENV2]	(WRITE)
10: Output CP2 (Comparator 2 conditions are satisfied) using negative logic	15	اه ۱
11: Output CP2 (Comparator 2 conditions are satisfied) using negative logic.	<u> - - - -</u>	<u> </u> - - n n
Specify the use of the P5/CP3 terminal <set (bits="" 1="" 10="" 11)="" in<="" p5m0="" td="" to=""><td>[RENV2]</td><td>(WRITE)</td></set>	[RENV2]	(WRITE)
RENV2>	15	8
10: Output CP3 (Comparator 3 conditions are satisfied) using negative logic.		n n
11: Output CP3 (Comparator 3 conditions are satisfied) using positive logic.		
Specify the use of the P6/CP4 terminal <set (bits="" 1="" 12="" 13)="" in<="" p6m0="" td="" to=""><td>[RENV2]</td><td>(WRITE)</td></set>	[RENV2]	(WRITE)
RENV2>	15	8
10: Output CP4 (Comparator 4 conditions are satisfied) using negative logic.		
11: Output CP4 (Comparator 4 conditions are satisfied) using positive logic.		<u> </u>
Specify the use of the P7/CP5 terminal <set (bits="" 1="" 14="" 15)="" in<="" p7m0="" td="" to=""><td>[RENV2]</td><td>(WRITE)</td></set>	[RENV2]	(WRITE)
RENV2>	15	8
10: Output CP5 (Comparator 5 conditions are satisfied) using negative logic.		
11: Output CP5 (Comparator 5 conditions are satisfied) using positive logic.		

11-15. Output an interrupt signal

This LSI can output an interrupt signal (#INT signal) : There are 17 types of errors, 19 types of events, and change from operating to stop that can cause an #INT signal to be output . All of the error causes will always output an #INT signal. Each of the event causes can be set in the RIRQ register to output an #INT signal or not.

A stop interrupt is a simple interrupt function which produces an interrupt separate from a normal stop or error stop.

For a normal stop interrupt to be issued, the confirmation process reads the RIST register as described in the Cause of an Event section. If your system needs to provide a stop interrupt whenever a stop occurs, it is easy to use the stop interrupt function.

To approximate a free curve interpolation using multiple linear interpolation operations, event interrupts will be generated at the end of each linear interpolation. When using the stop interrupt, set MENI = 1 in the RMD register. You can set it to not output an #INT signal if there is data for the next operation.

The #INT signal is output continuously until all the causes on all the axes that produced interrupts have been cleared. An interrupt caused by an error is cleared by writing a "REST (error cause) register read command." An interrupt caused by an event is cleared by writing a "RIST (event cause) register read command." A Stop interrupt is cleared by writing to the main status.

To determine which type of interrupt occurred, on which axis and the cause of the interrupt, follow the procedures below.

1) Read the main status of the X axis and check whether bits 2, 4, or 5 is "1."

2) If bit 2 (SENI) is "1," a Stop interrupt occurs.

3) If bit 4 (SERR) is "1," read the REST register to identify the cause of the interrupt.

4) If bit 5 (SINT) is "1," read the RIST register to identify the cause of the interrupt.

5) Repeat steps 1) to 4) above for the Y axis.

The steps above will allow you to evaluate the cause of the interrupt and turn the #INT output OFF.

- Note 1: When reading a register from the interrupt routine, the details of the input/output buffer will change. If the #INT signal is output while the main routine is reading or writing registers, and the interrupt routine starts, the main routine may produce an error. Therefore, the interrupt routine should execute a PUSH/POP on input/output buffer.
- Note 2: While processing all axes in steps 1) to 4) above, it is possible that another interrupt may occur on an axis whose process has completed. In this case, if the CPU interrupts reception mode, and is set for edge triggering, the PCL will latch the #INT output ON and it will not allow a new interrupt to interfere. Therefore, make sure that after you have reset the interrupt reception status the CPU reads main status of all the axes again. Also, make sure there is no #INT signal output from the PCL. Then, end the interrupt routine.

Note 3: When not using the #INT terminal, leave it open. When using more than one PCL, the #INT terminals cannot be wired ORed.

The #INT signal output can be masked by setting the RENV1 (environment setting 1) register. If the #INT output is masked (INTM = 1 in RENV1), and when the interrupt conditions are satisfied, the status will change. However, the #INT signal will not go LOW, but will remain HIGH. While the interrupt conditions are satisfied and if the output mask is turned OFF (INTM = 0 in RENV1), the #INT signal will go LOW.

Read the int	errupt status <seni(bit2), (bit="" 4),="" 5)="" in="" mstsw="" serr="" sint=""></seni(bit2),>	[MSTSW] (READ)
SENI = 1:	When IEND = 1 and a stop interrupt occurs, make this bit 1.	7 0
	After reading MSTS, it will become 0.	
SERR = 1:	Becomes 1 when an error interrupt occurs. Becomes 0 by	
	reading REST.	
SINT = 1:	Becomes 1 when an event interrupt occurs. Becomes 0 by	
	reading RIST.	
Set the inter	rupt mask <intm (bit="" 29)="" in="" renv1=""></intm>	[RENV1] (WRITE)
1: Mask #IN	T output.	31 24
		n
Setting a sto	p interrupt <iend (bit="" 27)="" in="" renv2=""></iend>	[RENV2] (WRITE)
1: Enable a	stop interrupt.	31 24
		n
Select the st	op interrupt mode <meni (bit="" 7)="" of="" prmd=""></meni>	[PRMD] (WRITE)
1: When the	re is data for the next operation in the pre-register, the PCL will	7 0
not outpu	it a stop interrupt.	n
Read the ca	use of the error interrupt <rrest: command="" read=""></rrest:>	[Read command]
Copy the da	ta in the REST register (error interrupt cause) to BUF.	F2h
Read the ev	ent interrupt cause <rrist: command="" out="" read=""></rrist:>	[Read command]
Copy the da	ta in the RIST register (event interrupt cause) to BUF.	F3h
Set the ever	It interrupt cause <wrirq: command="" write=""></wrirq:>	[Write command]
Write the BL	JF data to the RIRQ register (event interrupt cause).	ACh

Operation example in which MENI is set This is operation is used to write data for the next operation and the operation after that when starting.

1) When IEND = 1 a	nd MENI = 0		
BSY output —			
INT output —			
MSTS (2) —	Reading MSTS	Reading MSTS	Reading MSTS
2) When IEND = 1 a	nd MENI = 1	1	
in i output —			
MSTS (2)			
			Reading MSTS

Note: Even if IEND = 1 and MENI = 1, if no pre-register has been specified (a Start command has not been written yet), the PCL will output an interrupt signal.

[Error interrupt causes] < Detail of REST: The cause of an interrupt makes the corresponding bit "1">

Error interrupt causo	Cau	se (REST)
	Bit	Bit name
Stopped by Comparator 1 conditions being satisfied (+SL)	0	ESC1
Stopped by Comparator 2 conditions being satisfied (-SL)	1	ESC2
Stopped by Comparator 3 conditions being satisfied	2	ESC3
Stopped by Comparator 4 conditions being satisfied	3	ESC4
Stopped by Comparator 5 conditions being satisfied	4	ESC5
Stopped by turning ON the +EL input	5	ESPL
Stopped by turning ON the -EL input	6	ESML
Stopped by turning ON the ALM input	7	ESAL
Stopped by turning ON the #CSTP input	8	ESSP
Stopped by turning ON the #CEMG input	9	ESEM
Deceleration stopped by turning ON the SD input	10	ESSD
(Always 0)	11	Not defined
Stopped by an operation data error.	12	ESDT
Simultaneously stopped with another axis due to an error stop on the other axis during an interpolation operation	13	ESIP
Stopped by an overflow of PA/PB input buffer counter occurrence	14	ESPO
Stopped by an over range count occurrence while positioning in an	15	ESAO
interpolation operation		
An EA/EB input error occurred (does not stop).	16	ESEE
An PA/PB input error occurred (does not stop).	17	ESPE

[Event interrupt causes] < The corresponding interrupt bit is set to 1 and then an interrupt occurred>

	Set c (RII	ause RQ)	Cause (RIST)
		Bit name	Bit	Bit name
Automatic stop	0	IREN	0	ISEN
The next operation starts continuously	1	IRNX	1	ISNX
When it is possible to write an operation to the 2nd pre-register	2	IRNM	2	ISNM
When it is possible to write to the 2nd pre-register for Comparator 5	3	IRND	3	ISND
When acceleration starts	4	IRUS	4	ISUS
When acceleration ends	5	IRUE	5	ISUE
When deceleration starts	6	IRDS	6	ISDS
When deceleration ends	7	IRDE	7	ISDE
When the Comparator 1 conditions are satisfied	8	IRC1	8	ISC1
When the Comparator 2 conditions are satisfied	9	IRC2	9	ISC2
When the Comparator 3 conditions are satisfied	10	IRC3	10	ISC3
When the Comparator 4 conditions are satisfied	11	IRC4	11	ISC4
When the Comparator 5 conditions are satisfied	12	IRC5	12	ISC5
When the counter value is reset by a CLR signal input	13	IRCL	13	ISCL
When the counter value is latched by an LTC input	14	IRLT	14	ISLT
When the counter value is latched by an ORG input	15	IROL	15	ISOL
When the SD input is turned ON	16	IRSD	16	ISSD
When the +DR input changes	17	וסחסו	17	ISPD
When the -DR input changes	17		18	ISMD
When the STA input is turned ON	18	IRSA	19	ISSA

12. Electrical Characteristics

12-1. Absolute maximum ratings

Item	Item Symbol Rating		Unit	
Power supply voltage	V _{dd} 5	V _{dd} 5 -0.3 to +6.0		
i ower supply voltage	V _{dd} 3	-0.3 to +4.5	v	
Input voltage	V _{IN}	-0.3 to V _{dd} 5 +0.3	V	
Input current	I _{IN}	±10	mA	
Storage temperature	Tstg	-40 to +125	°C	

12-2. Recommended operating conditions

Item	Symbol	Rating	Unit	
Power supply voltage	V _{dd} 5	4.5 to 5.5	V	
Fower suppry voltage	V _{dd} 3	3.0 to 3.6	v	
Ambient temperature	ТJ	-40 to +70	°C	

12-3. DC characteristics

Item	Symbol	Condition	Min.	Max.	Unit
Static current	I _{dd} 5	CLK = 0 MHz,		45	
consumption	I _{dd} 3	No load		90	μA
	I _{dd} 5	CLK = 20 MHz,		3	
Current consumption	I _{dd} 3	Output frequency = 6.666667 MHz, No load		79	mA
Output leakage current	I _{OZ}		-1	1	μA
Input capacitance				10	pF
LOW input current	I_{IL}		-1		μA
HIGH input current	I _{IH}			1	μA
LOW input voltage	V _{IL}	Inputs and input/output terminals, except CLK.		0.6	V
		CLK terminal		0.8	V
HIGH input voltage	V _{IH}	Inputs and input/output terminals, except CLK.	2.4		V
		CLK terminal	4.0		V
LOW output voltage	V _{OL}	I _{OL} = 8 mA		0.4	V
HIGH output voltage	V _{OH}	I _{ОН} = -8 mA	Vdd5-0.4		V
LOW output current	I _{OL}	$V_{OL} = 0.4 V$		8	mA
HIGH output current	I _{ОН}	V _{OH} = 2.4 V	-8		mA
Internal pull up resistance	R_{UP}		30	144	K-ohm

12-4. AC characteristics 1) (reference clock)

Item	Symbol	Condition	Min.	Max.	Unit
Reference clock frequency	f _{CLK}			20	MHz
Reference clock cycle	T _{CLK}		50		ns
Reference clock HIGH width	Т _{скн}		20		ns
Reference clock LOW width	T _{CKL}		20		ns



12-5. AC characteristics 2) (CPU I/F)

12-5-1. <u>CPU-I/F 1</u>) (IF1 = H, IF0 = H) Z80

Item	Symbol	Condition	Min.	Max.	Unit
Address setup time for #RD \downarrow	T _{AR}		29		ns
Address setup time for #WR \downarrow	T _{AW}		17		ns
Address hold time for #RD, #WR \uparrow	T _{RWA}		0		ns
#CS setup time for #RD↓	T _{CSR}		20		ns
#CS setup time for #WR ↓	T _{CSW}		8		ns
#CS hold time for #RD, #WR \uparrow	T _{RWCS}		0		ns
#WRQ ON delay time for #CS \downarrow	T _{CSWT}	C _L = 40pF		25	ns
#WRQ signal LOW time	T _{WAIT}			4T _{CLK}	ns
Data output delay time for #RD \downarrow	T _{RDLD}	C _L = 40pF		25	ns
Data output delay time for #WRQ \uparrow	T _{WTHD}	C _L = 40pF		15	ns
Data float delay time for #RD \uparrow	T _{RDHD}	C _L = 40pF		12	ns
#WR signal width	T _{WR}	Note 1	10		ns
Data setup time for #WR ↑	T _{DWR}		14		ns
Data hold time for #WR ↑	TWRD		0		ns

Note 1: When a #WRQ signal is output, the duration will be the interval between #WRQ = H and #WR = H.

<Read cycle>





<Write cycle>

12-5-2. CPU-I/F 2) (IF1 = H, IF0 = L) 8086

Item	Symbol	Condition	Min.	Max.	Unit
Address setup time for #RD \downarrow	T _{AR}		28		ns
Address setup time for #WR \downarrow	T _{AW}		17		ns
Address hold time for #RD, #WR \uparrow	T _{RWA}		0		ns
#CS setup time for #RD \downarrow	T _{CSR}		19		ns
#CS setup time for #WR ↓	T _{CSW}		8		ns
#CS hold time for #RD, #WR ↑	T _{RWCS}		0		ns
#WRQ ON delay time for #CS \downarrow	T _{CSWT}	C _L = 40pF		25	ns
#WRQ signal LOW time	T _{WAIT}			4T _{CLK}	ns
Data output delay time for #RD \downarrow	T _{RDLD}	C _L = 40pF		30	ns
Data output delay time for #WRQ \uparrow	T _{WTHD}	C _L = 40pF		13	ns
Data float delay time for #RD \uparrow	T _{RDHD}	C _L = 40pF		16	ns
#WR signal width	T _{WR}	Note 1	10		ns
Data setup time for #WR \downarrow	T _{DWR}		14		ns
Data hold time for #WR ↑	T _{WRD}		0		ns

Note 1: When a #WRQ signal is output, the duration will be the interval between #WRQ = H and #WR = H.

<Read cycle>



<Write cycle>



12-5-3. CPU-I/F 3) (IF1 = L, IF0 = H) H8

Item	Symbol	Condition	Min.	Max.	Unit
Address setup time for #RD \downarrow	T _{AR}		29		ns
Address setup time for #WR \downarrow	T _{AW}		13		ns
Address hold time for #RD, #WR \uparrow	T _{RWA}		0		ns
#CS setup time for #RD \downarrow	T _{CSR}		20		ns
#CS setup time for #WR \downarrow	T _{CSW}		9		ns
#CS hold time for #RD, #WR \uparrow	T _{RWCS}		0		ns
#WRQ ON delay time for #CS \downarrow	T _{CSWT}	C _L = 40pF		25	ns
#WRQ signal LOW time	T _{WAIT}			4T _{CLK}	ns
Data output delay time for #RD \downarrow	T _{RDLD}	C _L = 40pF		30	ns
Data output delay time for #WRQ \uparrow	T _{WTHD}	C _L = 40pF		13	ns
Data float delay time for #RD ↑	T _{RDHD}	C _L = 40pF		16	ns
#WR signal width	T _{WR}	Note 1	10		ns
Data setup time for #WR ↑	T _{DWR}		12		ns
Data hold time for #WR ↑	T _{WRD}		0		ns

Note 1: When a #WRQ signal is output, the duration will be the interval between #WRQ = H and #WR = H.

<Read cycle>






12-5-4. CPU-I/F 4) (IF1 = L, IF0 = L) 68000

Item	Symbol	Condition	Min.	Max.	Unit
Address setup time for #LS \downarrow	T _{AS}		19		ns
Address hold time for #LS \uparrow	T _{SA}		0		ns
#CS setup time for #LS \downarrow	T _{CSS}		11		ns
#CS hold time for #LS ↑	T _{SCS}		0		ns
R/#W setup time for #LS ↓	T _{RWS}		3		ns
R/#W hold time for #LS $↑$	T _{SRW}		3		ns
#ACK ON dolou time for #LS	T _{SLAKR}	C _L = 40pF	1T _{CLK}	4T _{CLK} +29	ns
#ACK ON delay lime for #LS \$	T _{SLAKW}	$\begin{array}{c c c c c c c c c c c c c c c c c c c $	4T _{CLK} +29	ns	
$\#$ CK OEE dolou time for $\#$ S \uparrow	T _{SHAKR}	C _L = 40pF		18	ns
#ACK OFF delay lime for #L3	T _{SHAKW}	C _L = 40pF		18	ns
Data output advance time for #ACK \downarrow	T _{DAKLR}	C _L = 40pF	1T _{CLK}		ns
Data float delay time for #LS \uparrow	T _{SHD}	$C_L = 40 pF$		16	ns
Data setup time for #LS ↑	T _{DSL}		13		ns
Data hold time for #ACK \downarrow	TAKDH		0		ns

<Read cycle>



<Write cycle>



12-6. Operation timing

	Item	Symbol	Condition	Min.	Max.	Unit
#RST in	out signal width		Note 1	10Т _{СLК}		ns
CLR inp	ut signal width			2T _{CLK}		ns
EA, EB i	nput signal width	T _{EAB}	Note 2	1Т _{СLК} (3Т _{СLК})		ns
EZ input	signal width		Note 2	1Т _{СLК} (3Т _{СLК})		ns
PA, PB i	nput signal width	T _{PAB}	Note 3	1Т _{СLК} (3Т _{СLК})		ns
ALM inp	ut signal width		Note 4	2T _{CLK}		ns
INP inpu	t signal width		Note 4	2T _{CLK}		ns
			RENV1 bit 12 to 14 = 000	254Т _{СLК}	255Т _{СLК}	ns
			RENV1 bit 12 to 14 = 001	254 х 8Т _{СLК}	255 х 8Т _{СLК}	
			RENV1 bit 12 to 14 = 010	254 х 32Т _{СLК}	255 x 32T _{CLK}	
ERC out	nut signal width		RENV1 bit 12 to 14 = 011	254 x 128T _{CLK}	255 х 128Т _{СLК}	
	put signal width		RENV1 bit 12 to 14 = 100	254 х 1024T _{CLK}	255 х 1024Т _{СLК}	
			RENV1 bit 12 to 14 = 101	254 x 4096T _{CLK}	255 x 4096T _{CLK}	
			RENV1 bit 12 to 14 = 110	254 x 8192T _{CLK}	255 x 8192T _{CLK}	
			RENV1 bit 12 to 14 = 111	LEVEL output		
+EL, -EL	input signal		Note 4	2T _{CLK}		ns
SD input	signal width		Noto 4	эт		
			Note 4			ns
ם פח±	P input signal		Note 4	ZICLK		ns
width	ix input signal		NOLE 5	2T _{CLK}		ns
#PE inpu	ut signal width		Note 5	2T _{CLK}		ns
PCS inp	ut signal width			2T _{CLK}		ns
LTC inpu	ut signal width			2T _{CLK}		ns
	Output signal			8T _{CLK}		ns
#CSTA	Width			- CER		
	width			5Т _{СLК}		ns
	Output signal			8T _{CLK}		ns
#CSTP	Input signal					
	width			5Т _{СLК}		ns
#BSY się	gnal ON delay	T _{CMDBSY}			5T _{CLK}	ns
time		T _{STABSY}			7T _{CLK}	ns
Start del	av time	T _{CMDPLS}			15Т _{СLК}	ns
		T _{STAPLS}			17Т _{СLК}	ns

Note 1: The actual CLK input signal is 10 cycles longer while the #RST terminal is LOW.

Note 2: If the input filter is ON < EINF (bit 18) = 1 in RENV2 >, the minimum time will be $3T_{CLK}$.

Note 3: If the input filter is ON < PINF (bit 19) = 1 in RENV2 >, the minimum time will be $3T_{CLK}$. Note 4: If the input filter is ON < FLTR (bit 26) = 1 in RENV1 >, the minimum time will be $80T_{CLK}$.

Note 5: If the input filter is ON < DRF (bit 27) = 1 in RENV1 >, the minimum time will be $655,360T_{CLK}$.

1) When the EA, EB inputs are in the 2-pulse mode



13. External Dimensions



Appendix: List of various items

Appendix 1: List of commands

<Operation commands>

COMB0	Symbol	Description	COMB0	Symbol	Description
05h	CMEMG	Emergency stop	50h	STAFL	FL constant speed start
06h	CMSTA	#CSTA output (simultaneous start)	51h	STAFH	FH constant speed start
07h	CMSTP	#CSTP output (simultaneous stop)	52h	STAD	High speed start 1 (FH constant speed -> Deceleration stop)
40h	FCHGL	Immediate change to FL constant speed	53h	STAUD	High speed start 2 (acceleration -> FH constant speed -> deceleration stop)
41h	FCHGH	Immediate change to FH constant speed	54h	CNTFL	FL constant speed start for remaining number of pulses
42h	FSCHL	Decelerate to FL speed	55h	CNTFH	FH constant speed start for remaining number of pulses
43h	FSCHH	Accelerate to FH speed	56h	CNTD	High speed start 1 for remaining number of pulses
49h	STOP	Immediate stop	57h	CNTUD	High speed start 2 for remaining number of pulses
4Ah	SDSTP	Deceleration stop			

< General-purpose port control commands>

COMB0	Symbol	Description	COMB0	Symbol	Description
10h	P0RST	Set the P0 terminal LOW	18h	P0SET	Set the P0 terminal HIGH
11h	P1RST	Set the P1 terminal LOW	19h	P1SET	Set the P1 terminal HIGH
12h	P2RST	Set the P2 terminal LOW	1Ah	P2SET	Set the P2 terminal HIGH
13h	P3RST	Set the P3 terminal LOW	1Bh	P3SET	Set the P3 terminal HIGH
14h	P4RST	Set the P4 terminal LOW	1Ch	P4SET	Set the P4 terminal HIGH
15h	P5RST	Set the P5 terminal LOW	1Dh	P5SET	Set the P5 terminal HIGH
16h	P6RST	Set the P6 terminal LOW	1Eh	P6SET	Set the P6 terminal HIGH
17h	P7RST	Set the P7 terminal LOW	1Fh	P7SET	Set the P7 terminal HIGH

<Control commands>

COMB0	Symbol	Description	COMB0	Symbol	Description
00h	NOP	(Invalid command)	26h	PRECAN	Clear the operation pre-register
04h	SRST	Software reset	27h	PCPCAN	Clear the RCMP5 pre-register
20h	CUN1R	Reset COUNTER1 (command position)	28h	STAON	Substitute PCS input
21h	CUN2R	Reset COUNTER2 (mechanical position)	29h	LTCH	Substitute LTC input
22h	CUN3R	Reset COUNTER3 (deflection counter)	2Ah	SPSTA	Uses the same process as the #CSTA input, but for this axis
23h	CUN4R	Reset COUNTER4 (general-purpose)	2Bh	PRESHF	Shift the operation pre-register data
24h	ERCOUT	Output an ERC signal	2Ch	PCPSHF	Shift the RCMP5 pre-register
25h	ERCRS	Reset the ERC signal	4Fh	PRSET	Set the speed change data in the working pre-register.

<Register control commands>

		Register			2nd pre-register						
No	Description		Read c	ommand	Write command		Read co		command Write comm		ommand
	2 cccp.ion	Name	COMBO	Symbol	COMBO	Symbol	Name	COMBO	Symbol	COMBO	Symbol
	Number of feed pulses /		COMBO	Cymbol	COMDO	Cymbol		COMBO	Cymbol	COMBO	Cymbol
1	target position	RMV	D0h	RRMV	90h	WRMV	PRMV	C0h	RPRMV	80h	WPRMV
2	Initial speed	DEI	D1h	DDEI	01h	W/DEI	DDEI	C1h	DDDEI	81h	WDDEI
2		DEH	D111 D2h	DDEH	9111 02h	WRFH	DDEH	C2h	DDDEH	82h	WPRFL
3	Acceleration rate		D2h		02h			C2h		0211 93h	
4	Deceleration rate		D3H D4h		9311 04h			C4h		0311 94h	WEROR
5	Deceleration rate		D4II D5h		9411 05h			C4II		0411 05h	
0	Speed magnification rate	RIVIG	Don	RRING	950	WRING	PRIMG	Con	RPRING	001	WPRING
/	Ramping-down point	RUP	Don	RRUP	900	WRDP	PRUP	Con	RPRUP	801	WPRDP
8	Operation mode		D/n		97n	WRMD		C/n	RPRIMU	8/N	WPRMD
9	Circular Interpolation center	RIP	Dau	RRIP	98n	WRIP	PRIP	Can	RPRIP	88N	WPRIP
10	accelerating	RUS	D9h	RRUS	99h	WRUS	PRUS	C9h	RPRUS	89h	WPRUS
11	S-curve range while decelerating	RDS	DAh	RRDS	9Ah	WRDS	PRDS	CAh	RPRDS	8Ah	WPRDS
12	Feed speed to correct feed distance	RFA	DBh	RRFA	9Bh	WRFA					
13	Environment setting 1	RENV1	DCh	RRENV1	9Ch	WRENV1					
14	Environment setting 2	RENV2	DDh	RRENV2	9Dh	WRENV2					
15	Environment setting 3	RENV3	DEh	RRENV3	9Eh	WRENV3					
16	Environment setting 4	RENV4	DFh	RRENV4	9Fh	WRENV4					
17	Environment setting 5	RENV5	E0h	RRENV5	A0h	WRENV5					
18	Environment setting 6	RENV6	E1h	RRENV6	A1h	WRENV6					
19	Environment setting 7	RENV7	E2h	RRENV7	A2h	WRENV7					
20	COUNTER1 (command	RCUN1	E3h	RRCUN1	A3h	WRCUN1					
21	COUNTER2 (mechanical position)	RCUN2	E4h	RRCUN2	A4h	WRCUN2					
22	COUNTER3 (deflection counter)	RCUN3	E5h	RRCUN3	A5h	WRCUN3					
23	COUNTER4 (general-purpose)	RCUN4	E6h	RRCUN4	A6h	WRCUN4					
24	Comparator 1 data	RCMP1	E7h	RRCMP1	A7h	WRCMP1					
25	Comparator 2 data	RCMP2	E8h	RRCMP2	A8h	WRCMP2					
26	Comparator 3 data	RCMP3	E9h	RRCMP3	A9h	WRCMP3					
27	Comparator 4 data	RCMP4	EAh	RRCMP4	AAh	WRCMP4					
28	Comparator 5 data	RCMP5	EBh	RRCMP5	ABh	WRCMP5	PRCP5	CBh	RPRCP5	8Bh	WPRCP5
29	Enable various event	RIRQ	ECh	RRIRQ	ACh	WRIRQ					
30	COUNTER1 latch data	RI TC1	FDb	RRI TC1							
31	COUNTER2 latch data	RI TC2	FFh	RRI TC2							
32	COUNTER3 latch data	RI TC3	FFh	RRI TC3							
33	COUNTER4 latch data	RI TC4	E0h	RRI TC4							
34	Extension status	RSTS	F1h	RRSTS							
35	Frror INT status	REST	F2h	RREST							
36	Event INT status	RIST	F3h	RRIST							
37	Positioning counter	RPLS	F4h	RRPIS							
38	F7 counter speed monitor	RSPD	F5h	RRSPD							
30	Ramping-down point	RSDC	F6h	RRSDC							
33	Number of steps for circular	1.000		IN ODO							
40	interpolation	RCI	FCh	RRCI	BCh	WRCI	PRCI	CCh	RPRCI	8Ch	WPRCI
41	Counter of steps for circular interpolation	RCIC	FDh	RRCIC							
42	Interpolation status	RIPS	FFh	RRIPS							

Appendix 2: Setting speed pattern

Pre-register	Description	Bit length setting range	Setting range	Register
PRMV	Positioning amount	28	-134,217,728 to 134,217,727 (8000000h) (7FFFFFh)	RMV
PRFL	Initial speed (FL speed)	16	1 to 65,535 (0FFFFh)	RFL
PRFH	Operation speed (FH speed)	16	1 to 65,535 (0FFFFh)	RFH
PRUR	Acceleration rate	16	1 to 65,535 (0FFFFh)	RUR
PRDR	Deceleration rate Note 1	16	0 to 65,535 (0FFFFh)	RDR
PRMG	Speed magnification rate	12	2 to 4,095 (0FFFh)	RMG
PRDP	Ramping-down point	24	0 to 16,777,215 (0FFFFFFh)	RDP
PRUS	S-curve acceleration range	15	0 to 32,767 (7FFFh)	RUS
PRDS	S-curve deceleration range	15	0 to 32,767 (7FFFh)	RDS

Note 1: If PRDR is set to zero, the deceleration rate will be the value set in the PRUR.

[Relative position of each register setting for acceleration and deceleration factors]



Rampling-down point for positioning operation: Set in PRDP or set automatically

PRFL: FL speed setting register (16-bit)

Specify the speed for FL low speed operations and the start speed for high speed operations (acceleration/deceleration operations) in the range of 1 to 65,535 (0FFFFh). The speed will be calculated from the value in PRMG.

FL speed [pps] = PRFL x $\frac{\text{Reference clock frequency [Hz]}}{(\text{PRMG + 1}) \times 65536}$

PRFH: FH speed setting register (16-bit)

Specify the speed for FH low speed operations and the start speed for high speed operations (acceleration/deceleration operations) in the range of 1 to 65,535 (0FFFFh). When used for high speed operations (acceleration/deceleration operations), specify a value larger than PRFL.

The speed will be calculated from the value placed in PRMG. FH speed [pps] = PRFH x $\frac{\text{Reference clock frequency [Hz]}}{(\text{PRMG + 1}) \times 65536}$ PRUR: Acceleration rate setting register (16-bit)

Specify the acceleration characteristic for high speed operations (acceleration/deceleration operations), in the range of 1 to 65,535 (0FFFh) Relationship between the value entered and the acceleration time will be as follows:

1) Linear acceleration (MSMD = 0 in the PRMD register) Acceleration time [s] = $\frac{(PRFH - PRFL) \times (PRUR + 1) \times 4}{Reference clock frequency [Hz]}$

2) S-curve acceleration without a linear range (MSMD=1 in the PRMD register and PRUS register =0)

Acceleration time [s] = (PRFH - PRFL) x (PRUR + 1) x 8 Reference clock frequency [Hz]

- 3) S-curve acceleration with a linear range (MSMD = 1 in the PRMD register and PRUS register >0) Acceleration time [s] = $\frac{(PRFH - PRFL + 2 \times PRUS) \times (PRUR + 1) \times 4}{2}$ Reference clock frequency [Hz]
- PRDR: Deceleration rate setting register (16-bit)

Normally, specify the deceleration characteristics for high speed operations (acceleration /deceleration operations) in the range of 1 to 65,535 (0FFFFh). Even if the ramping-down point is set to automatic (MSDP = 0 in the PRMD register), the value placed in the PRDR register will be used as the deceleration rate. However, when PRDR = 0, the deceleration rate will be the value placed in the PRUR. When the ramping-down point is set automatically, the following limitations are applied.

- While in the Linear interpolation 1 or circular interpolation, and when the synthetic speed constant control function is applied (MIPF = 1 in the PRMD), arrange that (deceleration time) = (acceleration time).
- For other operations, arrange (deceleration time) \leq (acceleration time x 2).

Setting exceeding the above limitations may not decrease the speed to the specified FL speed when stopping. In this case, use a manual ramping-down point (MSDP = 1 in the PRMD register).

The relationship between the value entered and the deceleration time is as follows.

1) Linear deceleration (MSMD = 0 in the PRMD register)

Deceleration time [s] = $\frac{(PRFH - PRFL) \times (PRDR + 1) \times 4}{Pr}$ Reference clock frequency [Hz]

S-curve deceleration without a linear range (MSMD=1 in the PRMD register and PRDS register = 0)

Deceleration time [s] = $\frac{(PRFH - PRFL) \times (PRDR + 1)}{Pref} \times 8$ Reference clock frequency [Hz]

3) S-curve deceleration with a linear range (MSMD=1 in the PRMD register and PRDS register > 0) Deceleration time [s] = $\frac{(PRFH - PRFL + 2 \times PRDS) \times (PRDR + 1) \times 4}{PRFL + 2 \times PRDS \times (PRDR + 1) \times 4}$ Reference clock frequency [Hz]

• PRMG: Magnification rate register (12-bit)

Specify the relationship between the PRFL and PRFH settings and the speed, in the range of 2 to 4,095 (0FFFh). As the magnification rate is increased, the speed setting units will tend to be approximations. Normally set the magnification rate as low as possible.

The relationship between the value entered and the magnification rate is as follows.

J	J i i i ,			1 (
Setting	Magnification rate	Output speed range	Setting	Magnification rate	Output speed range
2999 (0BB7h)	0.1	0.1 to 6,553.5	59 (3Bh)	5	5 to 327,675
1499 (5DBh)	0.2	0.2 to 13,107.0	29 (1Dh)	10	10 to 655,350
599 (257h)	0.5	0.5 to 32,767.5	14 (0Eh)	20	20 to 1,310,700
299 (12Bh)	1	1 to 65,535	5 (5h)	50	50 to 3,276,750
149 (95h)	2	2 to 131,070	2 (2h)	100	100 to 6,553,500

[Magnification rate setting example, when the reference clock =19.6608 MHz] (Output speed unit: pps)

PRDP: Ramping-down point register (24-bits)

Specify the value used to determine the deceleration start point for positioning operations that include acceleration and deceleration

The meaning of the value specified in the PRDP changes with the "ramping-down point setting method ", (MSD0) in the PRMD register.

<When set to manual> (MSDP = 1 in the PRMD register)

The number of pulses at which to start deceleration, set in the range of 0 to16,777,215 (0FFFFFh). The optimum value for the ramping-down point can be calculated as shown in the equation below.

1) Linear deceleration (MSMD=0 of the PRMD register)

Optimum value [Number of pulses] = $\frac{(PRFH^2 - PRFL^2) \times (PRDR + 1)}{(PRMG + 1) \times 32768}$

However, the optimum value for a triangle start, without changing the value in the PRFH register while turning OFF the FH correction function (MADJ = 1 in the PRMD register) will be calculated as shown in the next equation below.

(When using idling control, modify the value for PRMV in the equation below by deducting the number of idling pulses from the value placed in the PRMV register. The number of idling pulses will be "1 to 6 when IDL = 2 to 7 in RENV 5.)

Optimum value [Number of pulses] = $\frac{PRMV \times (PRDR + 1)}{PRUR + PRDR + 2}$

2) S-curve deceleration without a linear range

(MSMD=1 in the PRMD register and the PRDS register =0) Optimum value [Number of pulses] = $\frac{(PRFH^2 - PRFL^2) \times (PRDR + 1) \times 2}{(PRMG + 1) \times 32768}$

3) S-curve deceleration with a linear range (MSMD=1 in the PRMD register and the PRDS register >0)

Optimum value [Number of pulses] -	(PRFH + PRFL) x (PRFH - PRFL + 2 x PRDS) x (PRDR + 1)
Optimum value [Number of pulses] =	(PRMG + 1) x 32768

Start deceleration at the point when the (positioning counter value) \leq (PRDP set value).

<When set to automatic (MSDP = 0 in the PRMD register)>

This is an offset value for the automatically set ramping-down point. Set in the range of -8,388,608 (800000h) to 8,388,607(7FFFFFh).

When the offset value is a positive number, the axis will start deceleration at an earlier stage and will feed at the FL speed after decelerating. When a negative number is entered, the deceleration start timing will be delayed. If the offset is not required, set to zero.

When the value for the ramping-down point is smaller than the optimum value, the speed when stopping will be faster than the FL speed. On the other hand, if it is larger than the optimum value, the axis will feed at FL constant speed after decelerating.

◆ PRUS: S-curve acceleration range register (15-bit)

Specify the S-curve acceleration range for S-curve acceleration/deceleration operations in the range of 1 to 32,767 (7FFFh).

The S-curve acceleration range S_{SU} will be calculated from the value placed in PRMG.

$$S_{SU}[pps] = PRUS x \frac{Reference clock frequency [Hz]}{(PRMG + 1) x 65536}$$

In other words, speeds between the FL speed and (FL speed + S_{SU}), and between (FH speed - Ssu) and the FH speed, will be S-curve acceleration operations. Intermediate speeds will use linear acceleration.

However, if zero is specified, "(PRFH - PRFL) / 2" will be used for internal calculations, and the operation will be an S-curve acceleration without a linear component.

PRDS: S-curve deceleration range setting register (15-bit)

Specify the S-curve deceleration range for S-curve acceleration/deceleration operations in the range of 1 to 32,767 (7FFFh).

The S-curve acceleration range $S_{\mbox{\scriptsize SU}}$ will be calculated from the value placed in PRMG.

In other words, speeds between the FH speed (FH speed - S_{SD}), and between (FL speed + S_{SD}) and the FL speed, will be S-curve deceleration operations. Intermediate speeds will use linear deceleration.

However, if zero is specified, "(PRFH - PRFL) / 2" will be used for internal calculations, and the operation will be an S-curve deceleration without a linear component.

Appendix 3: Label list

Label	Type	Position	Description	Reference
A0	Terminal name	8	Address bus 0 (LSB)	P7 16 17
Δ1	Terminal name	9 Q	Address bus 1	P7 16 17
A1 A2	Terminal name	9 10	Address bus 1	P7, 10, 17
A2		10	Address bus 2 (MOD)	F7, 10, 17
A3	Terminal name	TT	Address bus 3 (MSB)	P7, 16
ADJU to 1	Register bit	RENV6 12-13		P45, 125
ALML	Register bit	RENV1 9	Set the input logic for the ALM signal (0: Negative, 1: Positive)	P36, 106
ALMM	Register bit	RENV1 8	Select the process to use when the ALM input is ON (0: Immediate stop, 1:	P36, 106
	- · ·		Deceleration stop)	-
ALMX		44	X axis driver alarm signal (to stop the axis)	P9, 106
ALMy	Terminal name	84	Y axis driver alarm signal (to stop the axis)	P9, 106
AS0 to 15	Register bit	RSPD 0-15	Monitor current speed	P52
BR0 to 11	Register bit	RENV6 0-11	Specify a backlash correction or slip correction amount.	P45, 125
BSYC	Register bit	RENV3 14	Increment/decrement COUNTER4 only while in operation (#BSY = L)	P41, 116
#BSYx	Terminal name	68	Operation monitor output for the X axis	P10
#BSYy	Terminal name	107	Operation monitor output for the Y axis	P10
BUFB0	Byte map name	4 for Z80	Write/read the input/output buffer (bits 0 to 7).	P16, 18
BUFB1	Byte map name	5 for Z80	Write/read the input/output buffer (bits 8 to 15)	P16, 18
BUFB2	Byte man name	6 for 780	Write/read the input/output buffer (bits 16 to 23)	P16_18
BUFB3	Byte man name	7 for 780	Write/read the input/output buffer (bits 24 to 31)	P16 18
BUEWO	Word man name	4 for 8086	Write/read the input/output buffer (bits 0 to 15)	P17 18
BUEW/1	Word map name	6 for 8086	Write/read the input/output buffer (bits 16 to 31)	P17 18
201 111	map name			, .0
C1C0 to 1	Pogistor bit		Select a comparison counter for comparator1	D42 117
	Degister bit			D42, 117
		RENV4 5-6	Select a process to execute when the comparator'l conditions are met	F42, 118
0150 t0 2	Register bit	RENV4 2-4		F42, 118
C1RM	Register bit	RENV4 7	Set COUNTER1 for ring count operation using Comparator 1.	P42, 118
C2C0 to 1	Register bit	RENV4 8-9	Select a comparison counter for comparator2	P42. 117
C2D0 to 1	Register bit	RENV4 13-14	Select a process to execute when the comparator2 conditions are met	P42, 118
C2S0 to 2	Register bit	RENV4 10-12	Select a comparison method for comparator2	P42, 118
C2RM	Register bit	RENV4 15	Set COUNTER2 for ring count operation using Comparator 2	P42, 124
C3C0 to 1	Register bit	RENV4 16-17	Select a comparison counter for comparator3	P42, 117
C3D0 to 1	Register bit	RENV4 21-22	Select a process to execute when the comparator3 conditions are met	P43, 118
C3S0 to 2	Register bit	RENV4 18-20	Select a comparison method for comparator3	P43, 118
C4C0 to 1	Register bit	RENV4 24-25	Select a comparison counter for comparator4	P43, 118
C4D0 to 1	Register bit	RENV4 30-31	Select a process to execute when the comparator4 conditions are met	P43, 118
C4S0 to 3	Register bit	RENV4 26-29	Select a comparison method for comparator4	P43_118
C5C0 to 2	Register bit	RENV5 0-2	Select a comparison counter for comparator5	P44, 118
C5D0 to 1	Register bit	RENV5.6-7	Select a process to execute when the comparator5 conditions are met	P44 118
C5S0 to 2	Register bit	RENV5 3-5	Select a comparison method for comparator5	P44 118
#CEMG	Torminal name	39	Emergency stop signal	D9 115
	Pogistor bit	DENIV/3 8 0	Specify the input count COUNTER2 (mechanical position)	P0, 113
	Register bit	REINV3 6-9	Specify the input count COUNTER2 (inechanical position)	F41, 112
CI30 to 31	Register bit	RENV3 10-11	Specify the input count COUNTER3 (deflection counter)	P41, 112
CI40 to 41		RENV3 12-13	Specify the input count COUNTER4 (general-purpose)	P41, 112
CLK	Terminal name	119	Reference clock (19.6608 MHz as standard)	P7
CLR0 to 1	Register bit	RENV1 20-21	Select the CLR input mode	P37, 114
CLRx	Terminal name	46	Clear the counter input for the X axis	P10, 114
CLRy	Terminal name	86	Clear the counter input for the Y axis	P10, 114
CMEMG	Command	05h	Emergency stop	P22, 105
CMSTA	Command	06h	Output #CSTA (simultaneous start) signal	P22, 108
CMSTP	Command	07h	Output #CSTP (simultaneous stop) signal	P22, 110
CND0 to 3	Register bit	RSTS 0-3	Operation status monitor	P50
CNTD	Command	56h	Remaining high speed start pulses (FH constant speed -> Deceleration stop)	P22
CNTFH	Command	55h	Remaining pulses FH constant speed start pulses	P22
CNTFL	Command	54h	Remaining pulses FL constant speed start pulses	P22
	Commercel	5.7h	Remaining high speed start pulses (accelerate -> FH constant speed -> deceleration	DOO
CNTUD	Command	ə/n	stop)	F22
COMB0	Byte map name	0 when Z80	Write control command	P16, 18
COMB1	Byte map name	1 when Z80	Axis selection	P16, 18
COMW	Word map name	0 when 8086	Assign an axis, or write a control command	P17, 18
COUNTER1	Circuit name		28-bit counter for command position control	P2 112
COUNTER2	Circuit name		28-bit counter for mechanical position control	P2, 112
COUNTER3	Circuit name		16-bit counter for the deflection counter	P2 112
	Circuit name		28-bit counter for the general-purpose counter	P2 112
#09	Terminal name	5	Chin select signal	D7
#CSTA	Terminal name	36	Simultaneous start signal	P8 107
#001A	Torminal name	27	Cimultaneous stati signal	D9 100
#001F			Onerete COUNTED4 (command position) with backlack (align according	FO, 109
	Register bit	RENV3 24	Operate COUNTERT (command position) with backlash/slip correction	F41, 110
	Register bit	RENV3 16	Reset COUNTERT (command position) by turning ON the CLR input.	P41, 114
CU1L	Register bit	RENV5 24	Reset COUNTER1 (command position) right after latching the count value.	P44, 114
CU1R	Register bit	RENV3 20	Reset COUNTER1 (command position) when the zero return is complete	P44, 114
CU2B	Register bit	RENV3 25	Operate COUNTER2 (mechanical position) with backlash/slip correction	P44, 114
CU2C	Register bit	RENV3 17	Reset COUNTER2 (mechanical position) by turning ON the CLR input	P44, 114
CU2H	Register bit	RENV3 29	Stop the count on COUNTER2 (mechanical position)	P44, 114
CU2L	Register bit	RENV5 25	Reset COUNTER2 (mechanical position) right after latching the count value.	P44, 114
CU2R	Register bit	RENV3 21	Reset COUNTER2 (mechanical position) when the zero return is complete	P44, 114
CU3B	Register bit	RENV3 25	Operate COUNTER3 (deflection) with backlash/slip correction	P44, 114

Label	Туре	Position	Description	Reference
CU3C	Register bit	RENV3 18	Reset the COUNTER3 (deflection) by turning ON the CLR input.	P44, 114
CU3H	Register bit	RENV3 30	Stop the count on COUNTER3 (deflection)	P44, 114
CU3L	Register bit	RENV5 26	Reset COUNTER3 (deflection) right after latching the count value.	P44, 114
CU3R	Register bit	RENV3 22	Reset COUNTER3 (deflection) when the zero return is complete	P44, 114
CU4B	Register bit	RENV3 27	Operate COUNTER4 (general-purpose) backlash/slip correction	P44, 114
CU4C	Register bit	RENV3 19	Reset COUNTER4 (general-purpose) by turning ON the CLR input	P44, 114
CU4H	Register bit	RENV3 31	Stop the count on COUNTER4 (general-purpose)	P44, 114
CU4L	Register bit	RENV5 27	Reset COUNTER4 (general-purpose) right after latching the count value.	P44, 114
CU4R	Register bit	RENV3 23	Reset COUNTER4 (general-purpose) when the zero position operation is complete	P44, 114
CUN1R	Command	20h	Reset COUNTER1 (command position)	P24, 114
CUN2R	Command	21h	Reset COUNTER2 (mechanical position)	P24, 114
CUN3R	Command	22h	Reset COUNTER3 (deflection counter)	P24, 114
CUN4R	Command	23h	Reset COUNTER4 (general purpose)	P24, 114
D0	Terminal name	18	Data bus 0 (LSB)	P8
D1	Terminal name	19	Data bus 1	P8
D2	Terminal name	20	Data bus 2	P8
D3	Terminal name	21	Data bus 3	P8
D4	Terminal name	22	Data bus 4	P8
D5	Terminal name	23	Data bus 5	P8
D6		24	Data bus 6	P8
D7	Terminal name	25	Data bus 7	P8
D8		27	Data bus 8	P8
D9	Terminal name	28	Data bus 9	P8
D10		29	Data bus 10	P0
D11 D12	Terminal name	30	Data bus 11	P0
D12	Terminal name	20	Data bus 12	
D13	Terminal name	32	Data bus 13	
D14	Terminal name	34	Data bus 15 (MSR)	P8
	Terminal name	63	Motor drive direction signal for the X axis	P9 97
	Terminal name	102	Motor drive direction signal for the X axis	P9 97
DRF	Register hit	RENV1 27	Apply a filter to +DR -DR signal input	P37_62
	Register bit	RENV1 25	Select +DR _DR signal input logic (0: Negative logic 1: Positive logic)	P37_62
+DRx	Terminal name	52	Manual (+) input for the X axis	P9.62
-DRx	Terminal name	53	Manual (-) input for the X axis	P9. 62
+DRv	Terminal name	91	Manual (+) input for the Y axis	P9. 62
-DRv	Terminal name	92	Manual (-) input for the Y axis	P9. 62
DTMF	Register bit	RENV1 28	Turn OFF the direction change timer (0.2 msec)	P37
EAx	Terminal name	58	Encoder A phase signal for the X axis	P9
EAv	Terminal name	97	Encoder A phase signal for the Y axis	P9
EBx	Terminal name	59	Encoder B phase signal for the X axis.	P9
EBy	Terminal name	98	Encoder B phase signal for the Y axis	P9
ECZ0 to 3	Register bit	RSPD 16-19	Read the count value of the EZ input to monitor the zero return	P52
EDIR	Register bit	RENV2 22	Reverse the EA, EB input count direction	P39, 113
EIM0 to 1	Register bit	RENV2 20-21	Specify the EA, EB input parameters	P39, 113
EINF	Register bit	RENV2 18	Apply a noise filter to the EA/EB input	P39, 113
ELLx	Terminal name	127	Select the input logic of the end limit signal for the X axis	P8, 100
ELLv	Terminal name	128	Select the input logic of the end limit signal for the Y axis	P8. 100
, ,	Destates bit		Select the process to execute when the EL input is ON (0: Immediate stop. 1:	D00 74
ELM	Register bit	RENV1 3	Deceleration stop)	P36, 74
+ELx	Terminal name	40	(+) end limit signal for the X axis	P8, 100
-ELx	Terminal name	41	(-) end limit signal for the X axis	P8, 100
+ELy	Terminal name	80	(+) end limit signal for the Y axis	P8, 100
-ELy	Terminal name	81	(-) end limit signal for the Y axis.	P8, 100
EOFF	Register bit	RENV2 30	Invalid EA, EB input	P39, 113
EPW0 to 2	Register bit	RENV1 12-14	Specify the ERC output signal pulse width	P36, 105
ERCL	Register bit	RENV1 15	Set the output logic of the ERC signal (0: Negative logic, 1: Positive logic)	P36, 105
ERCOUT	Command	24h	Output an ERC signal	P24, 106
ERCRST	Command	25h	Reset the output when the ERC signal is set to level output	P24, 106
ERCx	Terminal name	69	Driver deflection clear output for the X axis	P10, 105
ERCy	Terminal name	80	Driver deflection clear output for the Y axis	P10, 105
EROE	Register bit	RENV1 10	Automatic output of the ERC signal	P36, 105
EROR	Register bit	RENV1 11	Auto output an ERC signal when the zero return is complete	P36, 105
ESAL	Register bit	REST 7	Equals 1 when stopped by the ALM input turning ON	P51, 108
ESAO	Register bit	REST 15	Equals 1 when the positioning counter exceeds the count range	P51
ESC1	Register bit	REST 0	Stopped when the comparator1 conditions (+SL) are met	P51
E302	Register bit	KESI 1	Stopped when the comparator2 conditions (-SL) are met	P51
ESC3	Register bit	REST 2	Stopped when the comaprator3 conditions (detect out-of-step) are met	P51
ESU4	Register bit	RESI 3	Stopped when the comparator4 conditions are met.	P51
	Register bit	KESI 4	Stopped when the comparators conditions are met	P51
	Register bit	REST 12	Stopped by an operation data error	P51
ESEE	Register bit	REST 10	All EAVEB Input error occurred	P51
ESEM	Register bit	REST 9	Stops by inputting #CEMG ON input	1751, 111
ESIP	Register bit	REST 13	when any other axis in an interpolation operation stops in an emergency, this axis stops simultaneously	P51
ESMI	Register hit	REST 6	Stops simulateously	P51 100
ESPE	Register hit	REST 17	A PA/PB input error occurred	P51 59
	register bit			

Label	Type	Position	Description	Reference
ESPI	Register hit	REST 5	Stopped because the + EL input turned ON	P51 100
ESPO	Register bit	REST 14	The PA/PB input buffer counter overflowed	P51 59
ESSD	Register bit	REST 10	Deceleration stop caused by the SD input turning ON	P51, 102
ESSP	Register bit	REST 8	Stops by inputting #CSTP_ON input	P51 110
EZL	Register bit	RENV2 23	Set the input logic for the EZ signal (0: Falling, 1: Rising)	P39. 64
 F7x	Terminal name	60	X axis encoder Z phase signal	P9 64
EZv	Terminal name	99	Y axis encoder Z phase signal	P9. 64
ETW0 to 1	Register bits	RENV1 16-17	Specify the ERC signal OFF timer	P36, 105
EZD0 to 3	Register bits	RENV3 4-7	Enter an EZ count value for a zero return	P41, 64
FCHGH	Command	41h	Change immediately to FH speed	P22
FCHGL	Command	40h	Change immediately to FL speed	P22
FDWx	Terminal name	66	Monitor output while the X axis is decelerating.	P10
FDWy	Terminal name	105	Monitor output while the Y axis is decelerating.	P10
FLTR	Register bit	RENV1 26	Apply input filter	P37
FSCHH	Command	43h	Accelerate to FH speed	P22
FSCHL	Command	42h	Decelerate to FL speed	P22
FT0 to 15	Register bits	RENV7 16-31	Enter an FT time for the vibration reduction function	P45, 125
FUPx	Terminal name	65	Monitor output while the X axis is accelerating.	P10
FUPy	Terminal name	104	Monitor output while the Y axis is accelerating.	P10
IDC0 to 2	Register bits	RSPD 20-22	Monitor the idling count (0 to 7 pulses)	P52, 99
IDL0 to 2	Register bits	RENV5 8-10	Enter the number of idling pulse (0 to 7 pulses)	P44, 99
IDXM	Register bit	RENV4 23	Select IDX output specification (0: Level output, 1: Pulse output)	P43, 123
IEND	Register bit	RENV2 27	Specify that the stop interrupt will be output.	P39, 132
IF0	Terminal name	3	CPU-I/F mode selection 0	P7
IF1	Terminal name	4	CPU-I/F mode selection 1	P7
#IFB	Terminal name	16	Busy CPU-I/F	P8
INPL	Register bit	RENV1 22	Select input logic of INP signal (0: Negative, 1: Positive)	P37, 104
INPx	Terminal name	45	In position input for the X axis	P10, 104
INPy	Terminal name	85	In position input for the Y axis	P10, 104
#IN I	Terminal name	13	Interrupt request signal	P7, 131
	Register bit	RENV1 29	Mask the INT output terminal	P37, 132
IOPU to 7	Sub-status bits	5515W 0-7	Read the PU to P7 terminal status.	P20
IOPB	Byte map name	2 When	Read the general I/O port	P16
IPCC	Pegister hit		Executing a CCW circular interpolation	P54
IPCW	Register bit	RIPS 18	Executing a CW circular interpolation	P54
IPF	Register bit	RIPS 17	Executing a linear interpolation by entering master axis feed amount	P54
IPFx	Register bit	RIPS 4	X axis linear interpolation mode from a specified master axis feed amount	P54
IPEv	Register bit	RIPS 5	Y axis linear interpolation mode from a specified master axis feed amount	P54
IPFx	Register bit	RIPS 12	Specify a synthetic constant speed for the X axis	P54
IPFv	Register bit	RIPS 13	Specify synthetic constant speed for the Y axis	P54
IPL	Register bit	RIPS 16	Executing a normal linear interpolation	P54
IPLx	Register bit	RIPS 0	X axis is in normal linear interpolation mode	P54
IPLv	Register bit	RIPS 1	Y axis is in normal linear interpolation mode	P54
IPSx	Register bit	RIPS 8	X axis is in circular interpolation mode	P54
IPSv	Register bit	RIPS 9	Y axis is in circular interpolation mode	P54
IRC1	Register bit	RIRQ 8	Enable an INT when the comparator1 conditions are met	P48, 133
IRC2	Register bit	RIRQ 9	Enable an INT when the comparator2 conditions are met	P48, 133
IRC3	Register bit	RIRQ 10	Enable an INT when the comparator3 conditions are met	P48, 133
IRC4	Register bit	RIRQ 11	Enable an INT when the comparator4 conditions are met	P48, 133
IRC5	Register bit	RIRQ 12	Enable an INT when the comparator5 conditions are met	P48, 133
IRCL	Register bit	RIRQ 13	Enable an INT when the count value is reset by a CLR input	P48, 133
IRDE	Register bit	RIRQ 7	Enable an INT when the deceleration is finished	P48, 133
IRDR	Register bit	RIRQ 17	Enable an INT when the ±DR input changes	P48, 133
IRDS	Register bit	RIRQ 6	Enable an INT when the deceleration starts	P48, 133
IREN	Register bit	RIRQ 0	Enable an INT when there is a normal stop	P48, 133
IRLT	Register bit	RIRQ 14	Enable an INT when the count value is latched by an LTC input	P48, 133
IRN	Register bit	RIRQ 1	Enable INT by continuing with the next operation.	P48, 133
IRND	Register bit	RIRQ 3	Enable an INT when writing to the 2nd pre-register for comparator5 is enabled	P48, 133
IRNM	Register bit	RIRQ 2	Enable an INT when writing to 2nd pre-register for operation is enabled	P48, 133
IROL	Register bit	RIRQ 15	Enable an INT when the count value is latched by an ORG input	P48, 133
IRSA	Register bit	RIRQ 18	Enable an INT by turning ON the #CSTA input	P48, 133
IRSD	Register bit	RIRQ 16	Enable an INT by turning ON the SD input	P48, 133
IRUE	Register bit	RIRQ 5	Enable an INT when the acceleration is finished	P48, 133
	Register bit		Enable an IN I when acceleration starts	P48, 133
1501	Register bit		Comparator 1 conditioned status	P52, 133
1502	Register bit	RIST 9	Comparator 2 conditioned status	P52, 133
1803	Register bit		Comparator 3 conditioned status	P52, 133
1804	Register bit		Comparator 4 conditioned status	P52, 133
1805	Register bit	KIST 12	Comparator 5 conditioned status	P52, 133
IOUL	Register bit		Reset the count value when a GLK signal IS input	P52, 133
	Register bit		Equals 1 when deceleration starts	P52, 133
	Register bit		Equals 1 When depend autometically	P52, 133
	Register bit		Equals 1 when stopped automatically	P52, 133
	Register bit		Equals 1 when the count value is latched by an LTC input	P52, 133
UNIO	Register bit	NIOT 10	רקעמוס ד אוופוד מ –די ה וווףענ signatis iniput.	ruz, 100

Label	Туре	Position	Description	Reference
ISN	Register bit	RIST 1	To start the next operation continuously.	P52, 133
ISND	Register bit	RIST 3	Enable writing to the 2nd pre-register for comparator5	P52, 133
ISNM	Register bit	RIST 2	Enable writing to the 2nd pre-register for operations	P52, 133
ISOL	Register bit	RIST 15	Latched count value from the ORG input	P52, 133
ISPD	Register bit	RIST 17	Equals 1 when the +DR input is ON	P52, 133
ISSA	Register bit	RIST 19	Equals 1 when the CSTA input is ON	P52, 133
ISSD	Register bit	RIST 16	Equals 1 when the SD input is ON	P52, 133
ISUE	Register bit	RIST 5	Equals 1 when the acceleration is finished	P52, 133
ISUS	Register bit	RIST 4	Equals 1 when to start acceleration	P52, 133
LTCH	Command	29h	Substitute the LTC input (for counting or latching)	P24, 115
LTCL	Register bit	RENV1 23	Select the trigger edge for the LTC signal (0: Falling edge, 1: Rising edge)	P37, 115
LTCx	Terminal name	47	Latch the input for the X axis	P10, 115
LTCy	Terminal name	87	Latch the input for the Y axis	P10, 115
LTFD	Register bit	RENV5 14	Latch the current speed data in place of COUNTER3	P44, 115
LTM0 to 1	Register bits	RENV5 12-13	Specify the latch timing of COUNTERS 1 to 4	P44, 115
LTOF	Register bit	RENV5 15	Stop the latch using hardware timing	P44, 115
MADJ	Register bit	RMD 26	Disable the FH correction function	P34
MAX0 to 1	Register bits	RMD 20-21	Specify the axis used to control stopping for a simultaneous start	P120
MCCE	Register bit	RMD 11	Stop the operation of COUNTER1 (command position)	P34, 116
MENI	Register bit	RMD 7	Does not output a stop INT between blocks while in continuous operation using the	P33, 132
			PIE-I Egister.	
METM	Register bit	RMD 12	pulse)	P34, 132
MINP	Register bit	RMD 9	The operation is complete when the INP input turns ON	P34, 104
MIPF	Register bit	RMD 15	Enable a synthetic constant speed during an interpolation operation	P34, 77
MOD	Register bits	RMD 0-6	Operation mode selection	P33
MPCS	Register bit	RMD 14	Start control positioning using a PCI input	P34. 96
MDIE	De sietes bit	DMD 07	Automatically enter an end point pull in operation at the end of arc interpolation	D24
MPIE	Register bit	RIVID 27	operation.	P34
MSDE	Register bit	RMD 8	Decelerate (decelerate and stop) when the SD input turns ON	P34, 102
MSDP	Register bit	RMD 13	Specify the ramping-down point manually	P34
MSMD	Register bit	RMD 10	S-curve acceleration/deceleration (linear accel/decel when 0)	P34
MSN0 to 1	Register bits	RMD 16-17	Sequence number used to control the operation block	P34
MSPE	Register bit	RMD 24	Enable #CSTP input	P34, 110
MSPO	Register bit	RMD 25	Output a #CSTP (simultaneous stop) signal when stopped by an error	P34, 110
MSTSB0	Byte map name	0 when using	Read the main status (bits 0 to 7)	P16
	b) to map hame	a Z80		
MSTSB1	Byte map name	1 when using a 780	Read the main status (bits 8 to 15)	P16
MOTOW	Word man name	0 when using	Pood the main statue hite (hite 0 to 15)	D17
10131300	word map name	an 8086		F I <i>I</i>
MSY0 to 1	Register bit	RMD 18-19	Synchronization start timing	P34, 126
MVCx	Terminal name	67	Monitor output while the X axis is feeding at constant.	P10
MVCy	Terminal name	106	Monitor output while the Y axis is feeding at constant.	P10
Non	<u> </u>			500
NOP	Command	00h	(Invalid command)	P22
0.001	Desite to the			D 00.04
ORGL	Register bit	RENV17	Select the input logic for the ORG signal (U: Negative logic, 1: Positive logic)	P36, 64
ORGX	Terminal name	43	Zero position signal for X axis	P8, 64
ORGy	Terminal name	83 DENIV2.0.2	Zero position signal for Y axis	P8, 64
	General-purpose	INEINVO U-S		r'40, 04
OTP0 to 7	port name	OTPW 0-7	General-purpose ports	P18
OTPB	Byte map name	2 when using	Change status of general output port (valid only for the output specified bits)	P16
	-,	a Z80		
OTPW	Word map name	2 when using	Change status of general output port (valid only for the output specified bits)	P17
OUTx	Terminal name	62	Motor driving pulse signals for X axis	P9. 97
OUTy	Terminal name	101	Motor driving pulse signals for Y axis	P9 97
				, .,
P0L	Register bit	RENV2 16	Set output logic of P0 terminal (0: Negative logic, 1: Positive logic)	P23, 39
P0x/FUPx	Terminal name	71	General-purpose port 0 for the X axis / Monitor output during acceleration	P10, 38
	Terminal name	110	General-purpose port 0 for the V axis / Monitor output during acceleration	P11 38
	Terminal halle	70	Constal purpose port offor the Visite (Maritan subscheduling acceleration	D10,00
		72	General-purpose port 1 for the X axis / Monitor output during deceleration	10, 38
P1y/FDWy	I erminal name	111	General-purpose port 1 for the Y axis / Monitor output during deceleration	P10, 38
P2x/MVCx	Terminal name	73	General-purpose port 2 for the X axis / Feeding at constant speed	P10, 38
P2y/MVCy	Terminal name	112	General-purpose port 2 for the Y axis / Feeding at constant speed	P10, 38
P3x/CP1x(+SLx)	Terminal name	74	General-purpose port 3 for the X axis / Comparator 1 (+ software limit) output	P10, 38
P3v/CP1v(+SLv)	Terminal name	113	General-purpose port 3 for the Y axis / Comparator 1 (+ software limit) output	P10.38
	Terminal name	75	General-purpose port 4 for the X axis / Comparator 2 (aoffuera limit) output	P11 39
		10	Concrete purpose port 4 for the X axis / Comparation 2 (- software inflit) output	D11, 30
P4y/CP2y(-SLy)		114	General-purpose port 4 for the Y axis / Comparator 2 (- software limit) output	P11, 38
P5x/CP3x	I erminal name	76	General-purpose port 5 for the X axis / Comparator 3 output	P11, 38
P5y/CP3y	Terminal name	115	General-purpose port 5 for the Y axis / Comparator 3 output	P11, 38
P6x/CP4x	Terminal name	77	General-purpose port 6 for the X axis / Comparator 4 output	P11, 38
P6y/CP4v	Terminal name	116	General-purpose port 6 for the Y axis / Comparator 4 output	P11, 38
P7x/CP5x	Terminal name	78	General-purpose port 7 for the X axis / Comparator 5 output	P11. 38
				,

Label	Туре	Position	Description	Reference
P7y/CP5y	Terminal name	117	General-purpose port 7 for the Y axis / Comparator 5 output	P11, 38
P0M0 to 1	Register bits	RENV2 0-1	Specify the P0/FUP terminal details	P38
P0RST	Command	10h	Set the general-purpose output port terminal P0 LOW	P23
P0SET	Command	18h	Set the general-purpose output port terminal P0 HIGH	P23
P1L	Register bit	RENV2 17	Set the P1 terminal output logic (0: Negative logic, 1: Positive logic)	P23, 39
P1MU to 1	Register bits	RENV2 2-3	Specify the P1/FDW terminal details	P23
PISET	Command	19h	Set the general-purpose output port terminal P1 LOW	P23
P2M0 to 1	Register bits	RENV2 4-5	Specify the P2/MVC terminal details	P38
P2RST	Command	12h	Set the general-purpose output port terminal P2 LOW	P23
P2SET	Command	1Ah	Set the general-purpose output port terminal P2 HIGH	P23
P3M0 to 1	Register bits	RENV2 6-7	Specify the P3/CP1 (+SL) terminal details	P38
P3RST	Command	13h	Set the general-purpose output port terminal P3 LOW	P23
P3SET D4M0 to 1	Command Register bits		Set the general-purpose output port terminal P3 HIGH	P23
P4N0 to 1 P4RST	Command	14h	Set the general nurnose output nort terminal P4 LOW	P23
P4SET	Command	1Ch	Set the general-purpose output port terminal P4 HIGH	P23
P5M0 to 1	Register bits	RENV2 10-11	Specify the P5/CP3 terminal details	P38
P5RST	Command	15h	Set the general-purpose output port terminal P5 LOW	P23
P5SET	Command	1Dh	Set the general-purpose output port terminal P5 HIGH	P23
P6M0 to 1	Register bits	RENV2 12-13	Specify the P6/CP4/IDX terminal details	P38
P6RST	Command	16h	Set the general-purpose output port terminal P6 LOW	P23
P7M0 to 1	Register bits	IEII RENI/2 14 15	Sective general-purpose output port terminal Po HIGH	F23
P7RST	Command	17h	Set the general-purpose output port terminal P7 LOW	P23
P7SET	Command	1Fh	Set the general-purpose output port terminal P7 HIGH	P23
PAx	Terminal name	56	Manual pulsar phase A input for the X axis	P9, 57
PAy	Terminal name	95	Manual pulsar phase A input for the Y axis	P9, 57
PBx	Terminal name	57	Manual pulsar phase B input for the X axis	P9, 57
PBy	Terminal name	96	Manual pulsar phase B input for the Y axis	P9, 57
PCPCAN	Command Desister hit	27h	Clear the pre-register (PRCP5) for RCMP5	P24, 30
PCSL	Register bit	RENV1 24	Set the input logic for the PCSh signal (U: Negative logic, 1: Positive logic)	P24, 37, 108
PCSv	Terminal name	89	Start positioning control for the Y axis	P10, 108
PD0 to 10	Register bit	RENV6 16-26	Set a division rate for PA, PB inputs.	P45, 57
PDIR	Register bit	RENV2 26	Reverse the counting direction of the PA and PB inputs	P39, 59
#PEx	Terminal name	54	Enable the PA, PB, +DR, -DR inputs for X axis	P9, 57, 62
#PEy	Terminal name	93	Enable the PA, PB, +DR, -DR inputs for Y axis	P9, 57, 62
PFC0 to 1	Register bits	RSTS 18-19	Used as a status monitor for the RCMP5 pre-register.	P30, 50
PFMU to 1 PIM0 to 1	Register bits	RSTS 20-21 RENV2 24-25	Used as a status monitor of the working pre-register.	P30, 29 P30, 50
PINE	Register bit	RENV2 24-23	Apply a poise filter to the PA/PB inputs	P39, 39
PMD0 to 2	Register bits	RENV1 0-2	Specify the output pulse details	P36, 97
PMG0 to 4	Register bits	RENV6 27-31	Specify the multiplication rate for the PA/PB inputs.	P45, 57
PMSK	Register bit	RENV2 28	Specify the output pulse mask.	P39
POFF	Register bit	RENV2 31	Disable PA, PB inputs.	P39, 59
PRCI	Pre-register name		2nd pre-register for RCI	P28, 53
PRCP5	Pre-register name		2nd pre-register for RCMP5	P28, 47
PRDR	Pre-register name		2nd pre-register for RDP	P28, 31
PRDS	Pre-register name		2nd pre-register for RDS	P28, 35
PRECAN	Command	26h	Cancel the operation pre-register.	P24
PRESHF	Command	27h	Shift the data in the operation pre-register.	P24
PRFH	Pre-register name		2nd pre-register for RFH	P28, 31
PRFL	Pre-register name		2nd pre-register for RFL	P28, 31
PRMD	Pre-register name		2nd pre-register for RMD	P28 33
PRMG	Pre-register name		2nd pre-register for RMG	P28, 32
PRMV	Pre-register name		2nd pre-register for RMV	P28, 31
PRSET	Command	4Fh	Put speed change data into the operation pre-register.	P24, 120
PRUR	Pre-register name		2nd pre-register for RUR	P28, 31
PRUS	Pre-register name		2nd pre-register for RUS	P28, 35
PSTP	Register bit	RENV6 15	Specity the stop method used for stopping when a PA/PB stop command is received	P45, 60
PCI	Pogistor namo		Circular interpolation stop number data	D53 81
RCIC	Register name		Circular interpolation step number counter	P53
RCMP1	Register name		Comparison data for comparator1	P47, 117
RCMP2	Register name		Comparison data for comparator2	P47, 117
RCMP3	Register name		Comparison data for comparator3	P47, <u>117</u>
RCMP4	Register name		Comparison data for comparator4	P47, 117
RCMP5	Register name		Comparison data for comparator5	P47, 117
RCUN1	Register name		COUNTER1 (command position)	P46, 112
	Register name			P40, 112
RCUN4	Register name		COUNTER4 (general-purpose counter)	P46 112
#RD	Terminal name	6	Lead signal	P7
RDP	Register name		Ramping-down point	P32, 84
RDR	Register name		Deceleration rate	P32, 84
RDS	Register name		S-curve range of deceleration	P35, 86

Label	Туре	Position	Description	Reference
RENV1	Register name		Environment setting register 1 (Specify the input/output terminals)	P28, 36
RENV2	Register name		Environment setting register 2 (Specify the details for the general-purpose port)	P28, 38
RENV3	Register name		Environment setting register 3 (Specify the details for a zero return or counter)	P28_40
RENV4	Register name		Environment setting register 4 (Specify the details for comparators 1 to 4))	P28 42
	Register name		Environment setting register 5 (Specify the details for comparator 5)	D29 43
	Register name		Environment setting register 6 (Specify the feed amount correction)	P28 44
REINVO RENIV7	Register name		Environment setting register 7 (Specify the vibration reduction function details)	P28 44
RENT	Register name		Error INT status	P20, 44
REA	Register name		Speed for feeding the feed correction amount	P28_35
RFH	Register name		Operation speed	P28_31
RFL	Register name		Initial speed	P28. 31
חום	Degister name		Center position of a circular interpolation / Master axis feed amount when executing	D25 70
RIP	Register name		a linear interpolation using multiple LSI chips	P35, 79
RIPS	Register name		Interpolation setting status and operation status	P54
RIRQ	Register name		Enable various event interrupts	P48, 132
RIST	Register name		Event INT status	P52, 132
RLTC1	Register name		COUNTER1 (command position) latch data	P49, 115
RLTC2	Register name		COUNTER2 (mechanical position) latch data	P49, 115
RLTC3	Register name		COUNTER3 (deflection counter) latch data	P49, 115
RLTC4	Register name		COUNTER4 (general-purpose) latch data	P49, 115
RMD	Register name		Operation mode	P28, 33
RMG	Register name		Speed magnification rate	P32, 84
	Register name		Number of pulses remaining to be fed	P31, 64
RPL3	Command	CCh		P20, 32
RPRCP5	Command	CBh	Conv PRCP5 data to BLIF	P26
RPRDP	Command	C6h	Conv PRDP data to BUF	P26
RPRDR	Command	C4h	Copy PRDR data to BUF	P26
RPRDS	Command	CAh	Copy PRDS data to BUF	P26
RPRFH	Command	C2h	Copy PREH data to BUE	P26
RPRFI	Command	C1h	Copy PREL data to BUE	P26
RPRIP	Command	C8h	Copy PRIP data to BUF	P26
RPRMD	Command	C7h	Copy PRMD data to BUF	P26
RPRMG	Command	C5h	Copy PRMG data to BUF	P26
RPRMV	Command	C0h	Copy PRMV data to BUF	P26
RPRUR	Command	C3h	Copy PRUR data to BUF	P26
RPRUS	Command	C9h	Copy PRUS data to BUF	P26
RRCI	Command	FCh	Copy RCI data to BUF	P26
RRCIC	Command	FDh	Copy RCIC data to BUF	P26
RRCMP1	Command	E7h	Copy RCMP1 data to BUF	P26
RRCMP2	Command	E8h	Copy RCMP2 data to BUF	P26
RRCMP3	Command	E9h	Copy RCMP3 data to BUF	P26
RRCMP4	Command	EAh	Copy RCMP4 data to BUF	P26
RRCMP5	Command	EBh	Copy RCMP5 data to BUF	P26
RRCUN1	Command	E3h	Copy RCUN1 data to BUF	P26
RRCUN2	Command	E4h	Copy RCUN2 data to BUF	P26
RRCUN3	Command	E5h	Copy RCUN3 data to BUF	P26
RRCUN4	Command	E6h	Copy RCUN4 data to BUF	P26
RRDP	Command	D6h	Copy RDP data to BUF	P26
RRDR	Command	D4n		P26
	Command	DAII	Copy RENV1 data to RUE	F20 D26
	Command	DCI	Copy RENVI data to BUF	P20
	Command	DEh	Copy RENV2 data to BUF	P20
RRENV4	Command	DEh	Copy RENV4 data to BUF	P26
RRENV5	Command	E0h	Copy RENV5 data to BUF	P26
RRENV6	Command	E1h	Copy RENV6 data to BUF	P26
RRENV7	Command	E2h	Copy RENV7 data to BUF	P26
RREST	Command	F2h	Copy REST data to BUF	P26
RRFA	Command	DBh	Copy RFA data to BUF	P26
RRFH	Command	D2h	Copy RFH data to BUF	P26
RRFL	Command	D1h	Copy RFL data to BUF	P26
RRIP	Command	D8h	Copy RIP data to BUF	P26
RRIPS	Command	FFh	Copy RIPS data to BUF	P26
RRIRQ	Command	ECh	Copy RIRQ data to BUF	P26
RRIST	Command	F3h	Copy RIST data to BUF	P26
RRLTC1	Command	EDh	Copy RLTC1 data to BUF	P26
RRLTC2	Command	EEh	Copy RLTC2 data to BUF	P26
RRLTC3	Command	EFh	Copy RLTC3 data to BUF	P26
RRLTC4	Command	F0h	Copy RLTC4 data to BUF	P26
KKMD	Command	D/h		P26
RRMG	Command	D5h	Copy RMG data to BUF	P26
	Command	DUh		P26
KKPLS DBSDC	Command	F4N	COPY RELS GATA TO BUE	P26
RKODC	Command		Copy ROD data to BUF	F20
KKSPU DDete	Command	F 50 E 1 b		P20
DDUD	Command	1 ⁻ 111	Copy DLD data to DLE	F20 D26
	Command	Doh	Copy PLIS data to PLIE	P20
11100	Command			1 20

Label	Туре	Position	Description	Reference
RSDC	Register name		Automatically calculated value for the ramping-down point	P28, 53
RSPD	Register name		EZ count / Monitor current speed	P28, 52
#RST	Terminal name	2	Reset signal	P7, 94
RSTS	Register name		Extension status	P28, 50
RT0 to 15	Register bits	RENV7 0-15	Enter the RT time for the vibration reduction function	P45, 125
RUR	Register name		Acceleration rate	P31, 84
RUS	Register name		S-curve range during acceleration	P35, 84
SALM	Sub-status bit	SSTSW 11	Equals 1 when the ALM input is ON	P20, 106
SCLR	Register bit	RSTS 13	Equals 1 when the CLR input signal is ON	P49, 113
SCP1	Main status bit	MSTSW 8	Equals 1 when the CMP1 comparison conditions are met	P19, 118
SCP2	Main status bit	MSTSW 9	Equals 1 when the CMP2 comparison conditions are met	P19, 118
SCP3	Main status bit	MSTSW 10	Equals 1 when the CMP3 comparison conditions are met	P19, 118
SCP4	Main status bit	MSTSW 11	Equals 1 when the CMP4 comparison conditions are met	P19, 118
SCP5	Main status bit	MSTSW 12	Equals 1 when the CMP5 comparison conditions are met	P19, 118
SDIN	Register bit	RSTS 15	Equals 1 when the SD input signal is ON	P50, 104
SDIR	Register bit	RSIS 4	Set the operation direction (0: Plus direction, 1: Minus direction)	P50
SDL	Register bit	RENV1 6	Set the input logic of the SD signal (0: Negative logic, 1: Positive logic)	P36, 102
SDLI	Register bit	RENV1 5	Specify the latch function for the SD input (0: ON, 1: OFF)	P36, 102
SDM	Register bit	RENV1 4	Select the process to execute when the SD input is ON (U: Deceleration only, 1: Decelerate and stop)	P36, 102
SDM0 to 1	Pagistar hits	RIPS 20-21	Current phase of a circular interpolation	P54
SDRM	Register bit	RSTS 12	Equals 1 when the -DR input signal is ON	P50_62
SDRP	Register bit	RSTS 11	Equals 1 when the +DR input signal is ON	P50_62
SDSTP	Command	44h		P22
SDx	Terminal name	42	Ramping-down signal for the X axis	P8 100
SDv	Terminal name	82	Ramping-down signal for the Y axis	P8, 100
SED0 to 1	Register hits	RIPS 22-23	Final phase of a circular interpolation	P54
	Command bit	0.000		D 10
SELX	name	COMW 8	Select the X axis	P18, 75
SEL V	Command bit		Solect the V axis	D19 75
SLLY	name	CONIN 9		F 10, 73
SEMG	Register bit	RSTS 7	#CEMG input signal is ON	P50, 110
SEND	Main status bit	MSTSW 3	Equals 0 when started automatically, becomes 1 when stopped	P19
SENI	Main status bit	MSTSW 2	Equals 1 when an interrupt is caused by stopping.	P19, 132
SEOR	Main status bit	MSTSW 13	Equals 1 when unable to execute a position override.	P19, 97
SERC	Register bit	RSTS 9	Equals 1 when the ERC output signal is ON	P50, 106
SERR	Main status bit	MSTSW 4	Equals 1 when an error interrupt occurs	P19, 132
SEST	Register bit	RSTS 17	#STA input signal is ON.	P50, 108
SEZ	Register bit	RSTS 10	Equals 1 when the EZ input signal is ON	P50, 75
SFC	Sub-status bit	SSTSW 10	Equals 1 when feeding at constant speed	P20
SFD	Sub-status bit	SSTSW 9	Equals 1 when decelerating	P20
SFU	Sub-status bit	SSTSW 8	Equals 1 when accelerating	P20
SINP	Register bit	RSTS 16	Equals 1 when the INP input signal is ON	P50, 104
SINT	Main status bit	MSTSW 5	Equals 1 when an event interrupt occurs	P19, 132
SLTC	Register bit	RSTS 14	Equals 1 when the LTC input signal is ON	P50, 114
SMAX	Register bit	RENV2 29	Select the PCL6025B mode for the "start when the specified axis stops" function.	P39, 127
SMEL	Sub-status bit	SSTSW 13	Equals 1 when the –EL input is ON	P20, 100
SORG	Sub-status bit	SSTSW 14	Equals 1 when the ORG input is ON	P20, 103
SPCS	Register bit	RSTS 8	Equals 1 when the PCS input signal is ON	P50, 108
SPDF	Main status bit	MSTSW 15	Equals 1 when the pre-register for comparator 5 is full	P19, 30
SPEL	Sub-status bit	SSTSW 12	Equals 1 when the +EL input is ON	P19, 100
SPRF	Main status bit	MSTSW 14	Equals 1 when the next-operation pre-register is full	P19, 29
SPSTA	Command	2Ah	I ne same process as the #CSTA input	P22
SRST	Command	U4h	Software reset	P24
SKUN	iviain status bit	MSISW1		P19
SSC0 to 1	Iviain status bits	NSTSW 7-6	Sequence code	P19
SSCIM	Iviain status bit	IVISTSW 0	Equals 1 when a start command has already been written	P19
	Sup-status Dit	0010W 15	Equals 1 when the #0.5TA input signal is ON	PE0, 102
331A	Register bit	R5155	Equals 1 when the #CSTA input signal is ON	P50, 108
SSIP	Register bit	RSIS6	Equals 1 when the #CSTP input signal is ON	P50, 110
SSTSB	Byte map name	3 when using	Used to read the sub status	P16
		a 200 2 when using		ł
SSTSW	Word map name	an 8086	Used to read the sub status, general input/output port	P17
STAD	Command	52h	High speed start 1 (FH constant speed -> deceleration ston)	P21
STAFH	Command	51h	Start using FH constant speed	P21
STAFL	Command	50h	Start using FL constant speed	P21
STAM	Register bit	RENV1 18	Select #CSTA signal input specification (0: Level trigger, 1: Edge trigger)	P36, 108
#STAx	Terminal name	49	X axis simultaneous start signal	P8, 107
#STAv	Terminal name	88	Y axis simultaneous start signal	P8, 107
STAON	Command	28h	Substitute for a PCS input	P24, 96
STAUD	Command	53h	High speed start 2 (acceleration -> FH constant speed -> deceleration stop)	P21
STOP	Command	49h	Immediate stop	P22
STPM	Register bit	RENV1 19	Select #CSTP stop method (0: Immediate stop. 1: Deceleration stop)	P36, 110
SYI0 to 1	Register bits	RENV5 20-21	Select the axis used to input an internal synchronous signal	P44, 126
SYO0 to 3	Register bits	RENV5 16-19	Set the output timing of the internal synchronous signal	P44, 126
	y			
WPRCI	Command	8Ch	Write BUF data into PRCI	P26

Label	Туре	Position	Description	Reference
WPRCP5	Command	8Bh	Write BUF data into PRCP5	P26
WPRDP	Command	86h	Write BUF data into PRDP	P26
WPRDR	Command	84h	Write BUF data into PRDR	P26
WPRDS	Command	8Ah	Write BUF data into PRDS	P26
WPRFH	Command	82h	Write BUF data into PRFH	P26
WPRFL	Command	81h	Write BUF data into PRFL	P26
WPRIP	Command	88h	Write BUF data into PRIP	P26
WPRMD	Command	87h	Write BUF data into PRMD	P26
WPRMG	Command	85h	Write BUF data into PRMG	P26
WPRMV	Command	80h	Write BUF data into PRMV	P26
WPRUR	Command	83h	Write BUF data into PRUR	P26
WPRUS	Command	89h	Write BUF data into PRUS	P26
#WR	Terminal name	7	Write signal	P7
WRCI	Command	BCh	Write BUF data into the RCI register	P26
WRCMP1	Command	A7h	Write BUF data into the RCMP1 register	P26
WRCMP2	Command	A8h	Write BUF data into the RCMP2 register	P26
WRCMP3	Command	A9h	Write BUF data into the RCMP3 register	P26
WRCMP4	Command	AAh	Write BUF data into the RCMP4 register	P26
WRCMP5	Command	ABh	Write BUF data into the RCMP5 register	P26
WRCUN1	Command	A3h	Write BUF data into the RCUN1 register	P26
WRCUN2	Command	A4h	Write BUF data into the RCUN2 register	P26
WRCUN3	Command	A5h	Write BUF data into the RCUN3 register	P26
WRCUN4	Command	A6h	Write BUF data into the RCUN4 register	P26
WRDP	Command	96h	Write BUF data into the RDP register	P26
WRDR	Command	94h	Write BUF data into the RDR register	P26
WRDS	Command	9Ah	Write BUF data into the RDS register	P26
WRENV1	Command	9Ch	Write BUF data into the RENV1 register	P26
WRENV2	Command	9Dh	Write BUF data into the RENV2 register	P26
WRENV3	Command	9Eh	Write BUF data into the RENV3 register	P26
WRENV4	Command	9Fh	Write BUF data into the RENV4 register	P26
WRENV5	Command	A0h	Write BUF data into the RENV5 register	P26
WRENV6	Command	A1h	Write BUF data into the RENV6 register	P26
WRENV7	Command	A2h	Write BUF data into the RENV7 register	P26
WRFA	Command	9Bh	Write BUF data into the RFA register	P26
WRFH	Command	92h	Write BUF data into the RFH register	P26
WRFL	Command	91h	Write BUF data into the RFL register	P26
WRIP	Command	98h	Write BUF data into the RIP register	P26
WRIRQ	Command	ACh	Write BUF data into the RIRQ register	P26
WRMD	Command	97h	Write BUF data into the RMD register	P26
WRMG	Command	95h	Write BUF data into the RMG register	P26
WRMV	Command	90h	Write BUF data into the RMV register	P26
#WRQ	Terminal name	14	Wait request signal	P7
WRUR	Command	93h	Write BUF data into the RUR register	P26
WRUS	Command	99h	Write BUF data into the RUS register	P26

The PCL6025B is a functionally upgraded version of the PCL6025.

This section describes items that have been added to the PCL6025B.

1. How to identify the PCL6025 and PCL6025B

Some registers have been added and they can be checked to identify the PCL6025 version.

1) Enter any number of 16 bits or larger value (10000h to FFFF0000h) into the input/output buffer.

- 2) Write a WRENV6 command (A1h). (Input/output buffer -> RENV6 register)
- 3) Write a "0" in order to clear the input/output buffer.
- 4) Write a RRENV6 command (E1h). (Input/output buffer <- RENV6 register)
- 5) Read the input/output buffer. If the data read is 10000h or smaller, this is a PCL6025. If the data read is the value entered in step 1) above, this is a PCL6025B.

2. Additional items on the PCL6025B

2-1. Main status

Added bit 2 (SENI) and bit 13 (SEOR)

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0	
			0005	0004	0000	0000	0004	0004	0000	CINIT				001		

SPDF SPRF SEOR SCP5 SCP4 SCP3 SCP2 SCP1 SSC1 SSC0 SINT SERR SEND SENI SRUN SSCM

Bit	Bit name	Detail
2	SENI	Stop interrupt flag
		When IEND = 1 in the RENV2 register, a change from operating to stopped will make this
		bit be "1."
		(By reading main status, it returns to "0.")
13	SEOR	This bit becomes "1" when the PCL cannot execute a position override.
		(When the main status is read, it returns to "0.")

2-2. Operation command

The following command has been added.

COMB0	Symbol	Detail
4Fh	PRSET	Pre-register set command.

2-3. Register control command

The following command has been added.

No	Regi-s	Details	Read command		Write co	ommand	2nd	Read c	ommand	Write command	
110.	ter		COMB0	Symbol	COMB0	Symbol	register	COMB0	Symbol	COMB0	Symbol
	RCIC	Circular interpolation step counter	FDh	RRCIC							

2-4. PRMD (RMD) register

Bit 7 (MENI) and operation mode (MOD) details have been added.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
MIPF	MPCS	MSDP	МЕТМ	MCCE	MSME	MINP	MSDE	MENI				MOD			
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	MIPM	MADJ	MSPO	MSPE	0	0	MAX1	MAX0	MSY1	MSY0	MSN1	MSN0

Bit	Bit name	Detail
0 to 6	MOD	The following operation modes have been added.
		100 0010 (42h): Positioning operation (specify an absolute position in COUNTER1)
		100 0011 (43h): Positioning operation (specify an absolute position in COUNTER2)
		100 0010 (52h): Positioning operation synchronized with PA/PB (specify an absolute position in COUNTER1)
		100 0011 (53h): Positioning operation synchronized with PA/PB (specify an absolute position in COUNTER2)
		110 1000 (68h): Continuous linear interpolation 1 synchronized with PA/PB
		110 1010 (6Ah): Continuous linear interpolation 2 synchronized with PA/PB
		110 0011 (6Bh): Linear interpolation 2 synchronized with PA/PB
7	MENI	1: When a pre-register is already set, the PCL will not output an INT signal, even if IEND
		is changed to "1."

2-5. RENV2 register

Bits 2	27 to 3	1 have	been	added.											
15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
P7M1	P7M0	P6M1	P6M0	P5M1	P5M0	P4M1	P4M0	P3M1	P3M0	P2M1	P2M0	P1M1	P1M0	P0M1	P0M0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
POFF	EOFF	SMAX	PMSK	IEND	PDIR	PIM1	PIM0	EZL	EDIR	EIM1	EIM0	PINF	EINF	P1L	P0L

Bit	Bit name	Detail
27	IEND	Regardless of whether a normal or emergency stop occurs, the PCL will output an INT signal when stopped.
28	PMSK	Masks output pulses.
29	SMAX	 Enables the currently working axis to be specified for the "start when the specified axis stops" function.
30	EOFF	1: Disables EA/EB inputs.
31	POFF	1: Disables PA/PB inputs.

2-6. RENV4 register

Bit 7	(C1RM	1), bit 1	5 (C2I	RM) ar	nd bit 2	3 (IDX	M) hav	e beer	n adde	d.					
15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
C2RM	C2D1	C2D0	C2S2	C2S1	C2S0	C2C1	C2C0	C1RM	C1D1	C1D0	C1S2	C1S1	C1S0	C1C1	C1C0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
C4D1	C2D0	C4S3	C4S2	C4S1	C4S0	C4C1	C4C0	IDXM	C3D1	C3D0	C3S2	C3S1	C3S0	C3C1	C3C0

Bit	Bit name	Detail
7	C1RM	1: Sets COUNTER1 for ring counter operation using Comparator 1.
15	C2RM	1: Sets COUNTER2 for ring counter operation using Comparator 2.
23	IDXM	0: Output an IDX signal while COUNTER4 = RCMP2.
		1: When COUNTER4 becomes "0" by counting down, the PCL will output an IDX signal for
		two CLK cycles. (This is only valid when C4S0 to C4S3 are set 1000, 1001 or 1010.)

2-7. RENV5 register

Bits 24 (CU1L) to bit 27 (CU4L) have been added.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
LTOF	LTFD	LTM1	LTM0	0	IDL2	IDL1	IDL0	C5D1	C5D0	C5S2	C5S1	C5S0	C5C2	C5C1	C5C0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	CU4L	CU3L	CU2L	CU1L	0	0	SYI1	SYI0	SYO3	SYO2	SYO1	SYO0

Bit	Bit name	Details
24	CU1L	1: The PCL resets COUNTER1 at the same time it latches COUNTER1.
25	CU2L	1: The PCL resets COUNTER2 at the same time it latches COUNTER2.
26	CU3L	1: The PCL resets COUNTER3 at the same time it latches COUNTER3.
27	CU4L	1: The PCL resets COUNTER4 at the same time it latches COUNTER4.

2-8. RENV6 register

Bit 15 (PSTP), bits 16 to 26 (BD0 to 10), and bits 27 to 31 (RMG0 to 4) have been added.

15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
PSTP	0	ADJ1	ADJ0	BR11	BR10	BR9	BR8	BR7	BR6	BR5	BR4	BR3	BR2	BR1	BR0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
PMG4	PMG3	B PMG2	PMG1	PMG0	PD10	PD9	PD8	PD7	PD6	PD5	PD4	PD3	PD2	PD1	PD0

Bit	Bit name	Detail
15	PSTP	1: Even when a stop command is written, the pulses already input on PA/PB will be
		fed.
16 to 26	PD0 to 10	Set the PA/PB division rate [Divide by (set value / 2048)]
27 to 31	PMG0 to 4	Set the PA/PB multiplication rate [enter (multiplication value - 1)]

2-9. RSTS register

Bits 1	18 & 1	9 (PFC	0 to 1)	and bi	ts 20 (& 21 (P	FM0 to	o 1) ha	ve bee	en add	ed.				
15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
SDIN	SLTC	SCLR	SDRM	SDRP	SEZ	SERC	SPCS	SEMG	SSTP	SSTA	SDIR	CND3	CND2	CND1	CND0
31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16
0	0	0	0	0	0	0	0	0	0	PFM1	PFM0	PFC1	PFC0	SEST	SINP

Bit	Bit name	Detail
18 to 19	PFC0 to 1	Monitors the use conditions of the RCMP5 pre-register.
20 to 21	PFM0 to 1	Monitors the use conditions of the operation pre-registers (other than RCMP5).

2-10. RCIC register

A register to read the circular interpolation step count value has been added. (Read only)

31 3	30	0
0	Step count value	

2-11. Stop in the middle of a circular interpolation

The PCL6025 cannot resume the remainder of a circular interpolation when stopped in the middle of the operation.

The PCL6025B can continue the operation using the Residual Amount Start command (54h to 57h).

2-12. Improved precision for the FH correction calculation

The PCL6025 can produce a large deviation using the calculated results from certain combinations of PRFL, PRFH, PRUR, and PRDR values. If this happens, the automatically calculated result for the ramp down point can also have a large deviation, and the LSI will drive the axes at FL speed and then stop.

The PCL6025B has improved the FH correction calculation precision, as compared with the PCL6025. Therefore, for positioning operations using small feed amounts, the speed curve may change.

[Handling Precautions]

1. Design precautions

- 1) Never exceed the absolute maximum ratings, even for a very short time.
- 2) Take precautions against the influence of heat in the environment, and keep the temperature around the LSI as cool as possible.
- 3) Please note that ignoring the following may result in latching up and may cause overheating and smoke.
- Do not apply a voltage greater than the specified voltages for the Vdd5 terminal to the input/output terminals and do not pull them below GND.
- Please consider the voltage drop timing when turning the power ON/OFF.
- Be careful not to introduce external noise into the LSI.
- Hold the unused input terminals to +5 V or GND level.
- Do not short-circuit the outputs.
- Protect the LSI from inductive pulses caused by electrical sources that generate large voltage surges, and take appropriate precautions against static electricity.
- 4) Provide external circuit protection components so that overvoltages caused by noise, voltage surges, or static electricity are not fed to the LSI.
- 5) Turn the Vdd5 (+5V) and Vdd3 (+3.3V) supply ON/OFF at the same time, or as nearly the same time as possible. Turning the power on to either voltage supply may cause a "break-through current" to flow. Continued application of a "break-through current" may generate heat and shorten the life of the LSIs.
- 2. Precautions for transporting and storing LSIs
 - 1) Always handle LSIs carefully and keep them in their packages. Throwing or dropping LSIs may damage them.
 - 2) Do not store LSIs in a location exposed to water droplets or direct sunlight.
 - 3) Do not store the LSI in a location where corrosive gases are present, or in excessively dusty environments.
 - 4) Store the LSIs in an anti-static storage container, and make sure that no physical load is placed on the LSIs.
- 3. Precautions for installation
 - 1) In order to prevent damage caused by static electricity, pay attention to the following.
 - Make sure to ground all equipment, tools, and jigs that are present at the work site.
 - Ground the work desk surface using a conductive mat or similar apparatus (with an appropriate resistance factor). However, do not allow work on a metal surface, which can cause a rapid change in the electrical charge on the LSI (if the charged LSI touches the surface directly) due to extremely low resistance.
 - When picking up an LSI using a vacuum device, provide anti-static protection using a conductive rubber pick up tip. Anything which contacts the leads should have as high a resistance as possible.
 - When using a pincer that may make contact with the LSI terminals, use an anti-static model. Do not use a metal pincer, if possible.
 - Store unused LSIs in a PC board storage box that is protected against static electricity, and make sure there is adequate clearance between the LSIs. Never directly stack them on each other, as it may cause friction that can develop an electrical charge.
 - 2) Operators must wear wrist straps which are grounded through approximately 1M-ohm of resistance.
 - 3) Use low voltage soldering devices and make sure the tips are grounded.
 - 4) Do not store or use LSIs, or a container filled with LSIs, near high-voltage electrical fields, such those produced by a CRT.
 - 5) Plastic packages can become infiltrated with water from the air, and the moisture will creep into them as time passes, even when they are stored in a dry room. Dry them before soldering if there is any chance they may have absorbed moisture.

To dry them out, we recommend keeping them at a high temperature $125^{\circ}C\pm 5$ for 20 to 36 hours. However, please note: the LSI must not be exposed to high heat more than 2 times.

6) When using an infrared or air reflow system to apply solder, carefully observe the following restrictions and the total number of reflow the chips more than two times.

- * Temperature profile: Temperature profile (temperature at the surface of the plastic) in an infrared reflow furnace must be within the range shown in the figure below.
- * Maximum temperature: The maximum temperature at the plastic surface must not exceed 260°C peak, and not more than 250° for 10 seconds [Profile].

Also, we recommend that the soldering should be performed at as low a temperature as possible and for as little time as possible to reduce the thermal stress on the package



[Profile (the lead-free solders can be used)]

- 7) Do not use a solder dip method as it may cause a rapid temperature change in the packages, and may damage the devices.
- 4. Other precautions
 - 1) When the LSI will be used in poor environments (high humidity, corrosive gases, or excessive amounts of dust), we recommend applying a moisture prevention coating.
 - 2) The package resin is made of fire-retardant material; however, it can burn. When baked or burned, it may generate gases or fire. Do not use it near ignition sources or flammable objects.
 - 3) This LSI is designed for use in commercial apparatus (office machines, communication equipment, measuring equipment, and household appliances). If you use it in any device that may require high quality and reliability, or where faults or malfunctions may directly affect human survival or injure humans, such as in nuclear power control devices, aviation devices or spacecraft, traffic signals, fire control, or various types of safety devices, we will not be liable for any problem that occurs, even if it was directly caused by the LSI. Customers must provide their own safety measures to ensure appropriate performance in all circumstances.

November 28, 2008

No. DA70119-0/0E

* The specifications may be changed without notice for improvement.

NPM Nippon Pulse Motor Co., Ltd.

Tokyo Office:	Nippon Pulse Motor Co., Ltd. Tachihi Bldg. No. 3, 1, Sakae-cho 6 -Chome, Tachikawa City, Tokyo 190-0003, Japan Phone: +81-42-534-7701 Fax: +81-42-534-0026 Web: <u>http://www.npm.co.jp</u> E-mail: <u>int-l@npm.co.jp</u>
London Office:	Nippon Pulse Motor Co., Ltd. Vista Business Centre 50 Salisbury Road, Hounslow, Middlesex TW4 6JQ UK Phone: +44-20-8538-0315 Fax: +44-20-8538-0316 Web: <u>http://www.npm.co.jp</u> E-mail: <u>int-l@npm.co.jp</u>
USA:	Nippon Pulse America, Inc. 4 Corporate Drive, Radford, VA 24141, U.S.A. Phone: +1-540-633-1677 Fax: +1-540-633-1674 Web: http://www.nipponpulse.com E-mail: info@nipponpulse.com
China:	Nippon Pulse Shanghai Co., Ltd. Room 1072, No.555, Pudongdadao Road, Shanghai, 200120, China Phone: +86-21-6859-2622/2623 Fax: +86-21-6859-2628 Web: <u>http://www.npmchina.com</u> E-mail: <u>yj@npmshanghai.sina.net</u>

MNAL. No. PCL-6025B-1 1B-5205-0.5 (5205) ims