




PF/PFC Series Unipolar Motors

Wiring Diagram and Rotation Chart



No.	BLK	BRN	ORN	YLW	No.
1	ON	OFF	ON	OFF	4
2	OFF	ON	ON	OFF	3
3	OFF	ON	OFF	ON	2
4	ON	OFF	OFF	ON	1